



June 11, 2024

To All Bidders:

Subject: **Bid No. 8195-W4, Door & Hardware Replacement / WPS**

ADDENDUM NO. 4

To Whom It May Concern:

With reference to our bid request relative to the above subject, please refer to the changes/modifications/clarifications to the original proposal request.

- **PLEASE FIND ATTACHED SURVEY REPORTS FOR THE FOLLOWING SCHOOLS: CHANDLER ELEMENTARY, CHANDLER MAGNET, ELM PARK, UNION HILL. THERE IS NO ASBESTOS AT MCGRATH**
- **PLEASE SEE BELOW QUESTIONS RECEIVED AND RESPONSES FROM CITY:**

For the doors we need to install new lockable rim exit devices, will their vertical rods be installed at top and bottom? The reason we ask as the bottom will require drilling into the floor which could be suspect ACM. If so, please provide most recent Asbestos Survey.

Answer: Vertical rods will be installed at top and bottom. See attached reports for initial 5 schools (minus McGrath); reports for remaining schools will be provided to the awarded bidder for their information/reference.

Abatement will be, if required, by WPS Environmental Health and Safety under separate contract.

For the removal and disposal of selective doors, has there been an asbestos survey completed to test those doors?

Answer: An asbestos survey was not completed for each individual door in this project, but the schools are tested as part of a larger monitoring program.

Are we reusing existing door closer and over head stops on the interior doors that are to be replaced? Some are missing and some are damaged.

Answer: WPS will furnish door closers and overhead stops as needed/identified by the GC for specific locations



There is no cutting & patching, finish carpentry, flooring, or painting spec, do we assume that all hardware that is to be removed, the holes from the removal will be left exposed?

Answer: WPS will be responsible for patching by in-house trades staff; Awardee shall provide Owner with specific list and documentation of locations requiring patching.

At Head Start Millbury Street School, the basement plan does not reflect actual conditions. Classrooms “Art Room & Science/Team Room” have half walls with half doors, plans show new safebolt lock and lever as well as replacing the door on the Art Room Door?

Answer: At this location, provide materials only; WPS will construct a wall and install furnished door and hardware at a later date.

Bidders are requested to acknowledge and/or include this addendum with submission. All other terms, conditions and specifications remain unchanged.

Very truly yours,

Christopher J. Gagliastro
Purchasing Director



EMSL Analytical, Inc.

10-39 45th Road Long Island City, NY 11101

Tel/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 032313147

Customer ID: ATC62

Customer PO: 11-81-0030

Project ID:

Attention: Brian Williams
Atlas Technical
73 William Franks Drive
West Springfield, MA 01089

Phone:
Fax: (413) 781-3734
Received Date: 10/11/2023 10:04 AM
Analysis Date: 10/11/2023
Collected Date: 10/10/2023

Project: 183COW2359/ Chandler Elementary School/ 114 Chandler St Worcester

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
CE-1a 032313147-0001	Cafeteria Door - Door Insulation	Brown Fibrous Homogeneous	50% MinWool	50.0% Non-fibrous (Other)	None Detected
CE-1b 032313147-0002	Cafeteria Door - Door Insulation	Yellow Fibrous Homogeneous	3% Cellulose 7% Synthetic 20% MinWool 60% Glass	10.0% Non-fibrous (Other)	None Detected
CE-2a 032313147-0003	Cafeteria Door - Window Glazing	Gray Non-Fibrous Homogeneous		94.0% Non-fibrous (Other)	6% Chrysotile
CE-2b 032313147-0004	Cafeteria Door - Window Glazing				Positive Stop (Not Analyzed)

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Long Island City, NY AIHA LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NJ NY022, CT PH-0170, MA AA000170

Initial report from: 10/11/2023 19:40:02

Chandler Magnet School - Periodic Survey Report - Fall/Winter 2023

Location	Material Description	Amount	Condition
<u>101</u>			
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Brown Floor Tile	690 SF	8 minor nicked tiles, light wear. 3 missing
	9" x 9" Brown Floor Tile Mastic	690 SF	8 minor nicked tiles, light wear. 3 missing
	9" x 9" Gray w/White Streaks Floor Tile	6 SF	Intact
	9" x 9" Gray w/White Streaks Floor Tile Mastic	6 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	684 SF	14 chipped
	9" x 9" Green w/White & Black Floor Tile Mastic	684 SF	14 chipped
	9" x 9" Light Green w/White & Black Floor Tile	60 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	60 SF	Intact
<u>102</u>			
	12" x 12" Tan Floor Tile	110 SF	Intact
	12" x 12" Tan Floor Tile Mastic	110 SF	Intact
	6" Black Cove Base	50 LF	Minor damage
	6" Black Cove Base Mastic	50 LF	Minor damage
	9" x 9" Green w/White & Black Floor Tile	610 SF	Chipped
	9" x 9" Green w/White & Black Floor Tile Mastic	610 SF	Chipped
	9" x 9" Green/Brown Floor Tile	586 SF	6 nicked tiles
	9" x 9" Green/Brown Floor Tile Mastic	586 SF	6 nicked tiles
	9" x 9" Light Green w/White & Black Floor Tile	30 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	30 SF	Intact

Location	Material Description	Amount	Condition
<u>103</u>			
	12" x 12" Beige Floor Tile	2 SF	Intact
	12" x 12" Beige Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Brown w/Black & Beige Streaks	698 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks Mastic	698 SF	Intact
	9" x 9" Green/Brown Floor Tile	552 SF	5 tiles missing by heater, 6 broken & 3 cracking
	9" x 9" Green/Brown Floor Tile Mastic	552 SF	5 tiles missing by heater, 6 broken & 3 cracking
	9" x 9" Light Brown w/Beige Streaks	50 SF	Intact
	9" x 9" Light Brown w/Beige Streaks Mastic	50 SF	Intact
<u>104</u>			
	12" x 12" Gray Mottled Floor Tile	10 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	10 SF	Intact
	12" x 12" Tan Floor Tile	20 SF	Intact
	12" x 12" Tan Floor Tile Mastic	20 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	717 SF	Cracking/chipped
	9" x 9" Green w/White & Black Floor Tile Mastic	717 SF	Cracking/chipped
	9" x 9" Green/Brown Floor Tile	552 SF	5 chipped tiles, 4 worn & 7 missing
	9" x 9" Green/Brown Floor Tile Mastic	552 SF	5 chipped tiles, 4 worn & 7 missing
	9" x 9" Light Brown w/Beige Streaks	3 SF	Cracking
	9" x 9" Light Brown w/Beige Streaks Mastic	3 SF	Cracking

Location	Material Description	Amount	Condition
<u>105</u>			
	12" x 12" Gray Mottled Floor Tile	1 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	1 SF	Intact
	12" x 12" Tan Floor Tile	2 SF	Intact
	12" x 12" Tan Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	739 SF	6 chipped/cracking
	9" x 9" Green w/White & Black Floor Tile Mastic	739 SF	6 chipped/cracking
	9" x 9" Green/Brown Floor Tile	552 SF	7 chipped tiles, 4 missing
	9" x 9" Green/Brown Floor Tile Mastic	552 SF	7 chipped tiles, 4 missing
	9" x 9" Light Green w/White & Black Floor Tile	8 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	8 SF	Intact

106

	12" x 12" Tan Floor Tile	30 SF	Intact
	12" x 12" Tan Floor Tile Mastic	30 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	700 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	700 SF	Intact
	9" x 9" Green/Brown Floor Tile	552 SF	Intact
	9" x 9" Green/Brown Floor Tile Mastic	552 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	20 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	20 SF	Intact

Location	Material Description	Amount	Condition
<u>107</u>			
	12" x 12" Tan Floor Tile	15 SF	Intact
	12" x 12" Tan Floor Tile Mastic	15 SF	Intact
	6" Black Cove Base	65 LF	2 LF missing
	6" Black Cove Base Mastic	65 LF	2 LF missing
	9" x 9" Green w/White & Black Floor Tile	735 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	735 SF	Intact
	9" x 9" Green/Brown Floor Tile	650 SF	4 nicked by entrance, worn tiles, cracking throughout
	9" x 9" Light Green Floor Tile	40 SF	4 nicked by entrance, worn tiles, cracking throughout
	9" x 9" Light Green Floor Tile Mastic	40 SF	Intact
<u>Hall Storage by 107</u>			
	6" Black Cove Base	15 LF	Intact
	6" Black Cove Base Mastic	15 LF	Intact
<u>Hall Storage by Room 107</u>			
	9" x 9" Brown Floor Tile	85 SF	Intact (Limited visibility)
	9" x 9" Brown Floor Tile Mastic	85 SF	Intact (Limited visibility)
<u>108</u>			
	6" Black Cove Base	70 LF	Intact
	6" Black Cove Base Mastic	70 LF	Intact
	9" x 9" Green/Brown Floor Tile	810 SF	1 chipped in center, 2 chipped in prep area, 1 missing by heater
	9" x 9" Green/Brown Floor Tile Mastic	810 SF	1 chipped in center, 2 chipped in prep area, 1 missing by heater
	9" x 9" Light Green Floor Tile	90 SF	Intact
	9" x 9" Light Green Floor Tile Mastic	90 SF	Intact

Location	Material Description	Amount	Condition
<u>108 (Back Rm & Closet)</u>			
	12" x 12" Beige Floor Tile	12 SF	Intact
	12" x 12" Beige Floor Tile Mastic	12 SF	Intact
	12" x 12" Blue w/White Speckled Floor Tile	5 SF	Intact
	12" x 12" Blue w/White Speckled Floor Tile Mastic	5 SF	Intact
	12" x 12" Gray Mottled Floor Tile	5 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	5 SF	Intact
	12" x 12" Tan Floor Tile	22 SF	Intact
	12" x 12" Tan Floor Tile Mastic	22 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	946 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	946 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	10 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	10 SF	Intact
<u>104</u>			
	6" Black Cove Base	60 LF	Intact
	6" Black Cove Base Mastic	60 LF	Intact
<u>114</u>			
	12" x 12" Tan Floor Tile	6 SF	Intact
	12" x 12" Tan Floor Tile Mastic	6 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	886 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	886 SF	Intact
	9" x 9" Light Green Floor Tile	1050 SF	4 chip by entrance, 3 chipped in center
	9" x 9" Light Green Floor Tile Mastic	1050 SF	4 chip by entrance, 3 chipped in center
	9" x 9" Light Green w/White & Black Floor Tile	8 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	8 SF	Intact
<u>114, Bath</u>			
	9" x 9" Red Floor Tile	48 SF	Intact
	9" x 9" Red Floor Tile Mastic	48 SF	Intact (1 nicked)

Location	Material Description	Amount	Condition
<u>114 Storage</u>			
	12" x 12" Beige Floor Tile	30 SF	Intact
	12" x 12" Beige Floor Tile Mastic	30 SF	Intact
	9" x 9" Brown Floor Tile	200 SF	Intact
	9" x 9" Brown Floor Tile Mastic	200 SF	Intact
<u>114 Closet</u>			
	9" x 9" Brown Floor Tile	36 SF	Intact
	9" x 9" Brown Floor Tile Mastic	36 SF	Intact
<u>Storage by 112</u>			
	9" x 9" Brown Floor Tile	64 SF	Intact
	9" x 9" Brown Floor Tile Mastic	64 SF	Intact
<u>112</u>			
	12" x 12" Light Tan Floor Tile	60 SF	Intact
	12" x 12" Light Tan Floor Tile Mastic	60 SF	Intact
	12" x 12" Tan Floor Tile	3 SF	Intact
	12" x 12" Tan Floor Tile Mastic	3 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Brown Floor Tile	684 SF	4 chipped, worn by entrance
	9" x 9" Brown Floor Tile Mastic	684 SF	4 chipped, worn by entrance
	9" x 9" Green/Brown Floor Tile	620 SF	4 worn tiles, 2 nicked
	9" x 9" Green/Brown Floor Tile Mastic	620 SF	4 worn tiles, 2 nicked
	9" x 9" Light Brown w/Black Floor Tile	3 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile Mastic	3 SF	Intact
	9" x 9" Light Green Floor Tile	16 SF	Intact
	9" x 9" Light Green Floor Tile Mastic	16 SF	Intact
<u>Custodial by 112</u>			
	9" x 9" Brown Floor Tile Mastic	30 SF	Exposed (no tile)

Location	Material Description	Amount	Condition
<u>111</u>			
	12" x 12" Beige Floor Tile	14 SF	Intact
	12" x 12" Beige Floor Tile Mastic	14 SF	Intact
	12" x 12" Gray Mottled Floor Tile	40 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	40 SF	Intact
	12" x 12" Tan Floor Tile	6 SF	Intact
	12" x 12" Tan Floor Tile Mastic	6 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Brown Floor Tile	460 SF	1 chipped by chalkboard, 2 worn
	9" x 9" Brown Floor Tile Mastic	460 SF	1 chipped by chalkboard, 2 worn
	9" x 9" Gray w/White Streaks Floor Tile	4 SF	Intact
	9" x 9" Gray w/White Streaks Floor Tile Mastic	4 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	676 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	676 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	10 SF	Cracking
	9" x 9" Light Green w/White & Black Floor Tile Mastic	10 SF	Cracking

Location	Material Description	Amount	Condition
<u>110</u>			
	12" x 12" Gray Mottled Floor Tile	35 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	35 SF	Intact
	12" x 12" Tan Floor Tile	40 SF	Intact
	12" x 12" Tan Floor Tile Mastic	40 SF	Intact
	6" Black Cove Base	35 LF	Intact
	6" Black Cove Base Mastic	35 LF	Intact
	9" x 9" Brown Floor Tile	690 SF	Nicked tiles throughout, 2 chipped tiles
	9" x 9" Brown Floor Tile Mastic	690 SF	Nicked tiles throughout, 2 chipped tiles
	9" x 9" Green w/White & Black Floor Tile	625 SF	Gouged/cracking, 2 chipped
	9" x 9" Green w/White & Black Floor Tile Mastic	625 SF	Gouged/cracking, 2 chipped
	9" x 9" Light Green w/White & Black Floor Tile	50 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	50 SF	Intact
<u>Room between 109 & 110</u>			
	6" Black Cove Base	5 LF	Intact
	6" Black Cove Base Mastic	5 LF	Intact

Location	Material Description	Amount	Condition
<u>109</u>			
	12" x 12" Gray Mottled Floor Tile	2 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	2 SF	Intact
	12" x 12" Tan Floor Tile	6 SF	Intact
	12" x 12" Tan Floor Tile Mastic	6 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile	2 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	25 LF	Intact
	6" Black Cove Base Mastic	25 LF	Intact
	9" x 9" Brown Floor Tile	690 SF	14 nicked tiles, 6 missing, 6 chipped
	9" x 9" Brown Floor Tile Mastic	690 SF	14 nicked tiles, 6 missing, 6 chipped
	9" x 9" Brown w/Black & Beige Streaks	730 SF	chipped/gouged; missing/exposed mastic
	9" x 9" Brown w/Black & Beige Streaks Mastic	730 SF	chipped/gouged; missing/exposed mastic
	9" x 9" Solid Beige Floor Tile	6 SF	Intact
	9" x 9" Solid Beige Floor Tile Mastic	6 SF	Intact
	9" x 9" Tan w/Black Floor Tile	12 SF	Intact
	9" x 9" Tan w/Black Floor Tile Mastic	12 SF	Intact
<u>109-110 Hall</u>			
	12" x 12" Beige Floor Tile	1 SF	Intact
	12" x 12" Beige Floor Tile Mastic	1 SF	Intact
	9" x 9" Brown Floor Tile	51 SF	Intact
	9" x 9" Brown Floor Tile Mastic	51 SF	Intact
	9" x 9" Light Brown w/White Floor Tile	8 SF	Intact
	9" x 9" Light Brown w/White Floor Tile Mastic	8 SF	Intact

Location	Material Description	Amount	Condition
<u>109-110 Room Between</u>			
	9" x 9" Brown Floor Tile	162 SF	Chipped/gouged
	9" x 9" Brown Floor Tile Mastic	162 SF	Chipped/gouged
	9" x 9" Light Brown w/White Floor Tile	8 SF	Intact
	9" x 9" Light Brown w/White Floor Tile Mastic	8 SF	Intact
<u>201</u>			
	12" x 12" Tan Floor Tile	30 SF	Intact
	12" x 12" Tan Floor Tile Mastic	30 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile	2 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Brown w\White Streak Floor Tile	20 SF	Intact
	9" x 9" Brown w\White Streak Floor Tile Mastic	20 SF	Intact
	9" x 9" Green Floor Tile	586 SF	10 chipped tiles by whiteboard, 3 chipped in center
	9" x 9" Green Floor Tile Mastic	586 SF	10 chipped tiles by whiteboard, 3 chipped in center
	9" x 9" Green w/White & Black Floor Tile	678 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	678 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	20 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	20 SF	Intact
<u>201 Storage</u>			
	12" x 12" Beige Floor Tile	2 SF	Intact
	12" x 12" Beige Floor Tile Mastic	2 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks	698 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks Mastic	698 SF	Intact
	9" x 9" Light Brown w/Beige Streaks	50 SF	Intact
	9" x 9" Light Brown w/Beige Streaks Mastic	50 SF	Intact

Location	Material Description	Amount	Condition
<u>202</u>			
	12" x 12" Beige Floor Tile	6 SF	Intact
	12" x 12" Beige Floor Tile Mastic	6 SF	Intact
	12" x 12" Blue Floor Tile	20 SF	Intact
	12" x 12" Blue Floor Tile Mastic	20 SF	Intact
	12" x 12" Gray w/White Floor Tile	12 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	12 SF	Intact
	12" x 12" Tan Floor Tile	4 SF	Intact
	12" x 12" Tan Floor Tile Mastic	4 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile	2 SF	Intact
	12" x 12" White w/Black Speckles Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Green Floor Tile	172 SF	4 chipped tiles
	9" x 9" Green Floor Tile Mastic	172 SF	4 chipped tiles
	9" x 9" Green w/White & Black Floor Tile	566 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	566 SF	Intact
	9" x 9" Green w/White Floor Tile	80 SF	Intact
	9" x 9" Green w/White Floor Tile Mastic	80 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	60 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	60 SF	Intact

Location	Material Description	Amount	Condition
<u>203</u>			
	12" x 12" Beige Floor Tile	4 SF	Intact
	12" x 12" Beige Floor Tile Mastic	4 SF	Intact
	12" x 12" Gray w/White Floor Tile	6 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	6 SF	Intact
	12" x 12" Light Tan Floor Tile	4 SF	Intact
	12" x 12" Light Tan Floor Tile Mastic	4 SF	Intact
	12" x 12" Tan Floor Tile	12 SF	Intact
	12" x 12" Tan Floor Tile Mastic	12 SF	Intact
	6" Black Cove Base	75 LF	Minor damage (5 LF missing)
	6" Black Cove Base Mastic	75 LF	Minor damage (5 LF missing)
	9" x 9" Brown Floor Tile	172 SF	1 nicked tile, 17 cracked tiles, chipping along walls
	9" x 9" Brown Floor Tile	700 SF	Minor cracking/chipping
	9" x 9" Brown Floor Tile Mastic	172 SF	1 nicked tile, 17 cracked tiles, chipping along walls
	9" x 9" Brown Floor Tile Mastic	700 SF	Minor cracking/chipping
	9" x 9" Light Brown w/Black Floor Tile	4 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile	20 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile Mastic	4 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile Mastic	20 SF	Intact
<u>204 A & B</u>			
	6" Black Cove Base	75 LF	Minor damage (3 LF missing)
	6" Black Cove Base Mastic	75 LF	Minor damage (3 LF missing)

Location	Material Description	Amount	Condition
<u>204A & B</u>			
	12" x 12" Beige w/Black Speckled Floor Tile	30 SF	Intact
	12" x 12" Beige w/Black Speckled Floor Tile Mastic	30 SF	Intact
	12" x 12" Gray w/Brown Floor Tile	6 SF	Intact
	12" x 12" Gray w/Brown Floor Tile Mastic	6 SF	Intact
	12" x 12" Tan Floor Tile	2 SF	Intact
	12" x 12" Tan Floor Tile Mastic	2 SF	Intact
	9" x 9" Green Floor Tile	690 SF	13 chipped tiles
	9" x 9" Green Floor Tile Mastic	690 SF	13 chipped tiles
	9" x 9" Green w/White & Black Floor Tile	856 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	856 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile	6 SF	Intact
	9" x 9" Light Brown w/Black Floor Tile Mastic	6 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	50 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	50 SF	Intact
	9" x 9" Solid Olive Floor Tile	10 SF	Intact
	9" x 9" Solid Olive Floor Tile Mastic	10 SF	Intact

Location	Material Description	Amount	Condition
<u>205</u>			
	12" x 12" Beige Floor Tile	10 SF	Intact
	12" x 12" Beige Floor Tile Mastic	10 SF	Intact
	12" x 12" Tan Floor Tile	15 SF	Intact
	12" x 12" Tan Floor Tile Mastic	15 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Green Floor Tile	172 SF	2 chipped
	9" x 9" Green Floor Tile Mastic	172 SF	2 chipped
	9" x 9" Green w/White & Black Floor Tile	43 SF	Missing tile under radiator
	9" x 9" Green w/White & Black Floor Tile Mastic	473 SF	Missing tile under radiator
	9" x 9" Light Green w/White & Black Floor Tile	252 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	252 SF	Intact

Location	Material Description	Amount	Condition
<u>206</u>			
	12" x 12" Beige Floor Tile	6 SF	Chipped
	12" x 12" Beige Floor Tile Mastic	6 SF	Chipped
	12" x 12" Light Gray Speckled Floor Tile	3 SF	Intact
	12" x 12" Light Gray Speckled Floor Tile Mastic	3 SF	Intact
	12" x 12" Tan Floor Tile	150 SF	Intact
	12" x 12" Tan Floor Tile Mastic	150 SF	Intact
	6" Black Cove Base	75 LF	Minor damage (3 LF missing)
	6" Black Cove Base Mastic	75 LF	Minor damage (3 LF missing)
	9" x 9" Brown Floor Tile	172 SF	4 chipped in center
	9" x 9" Brown Floor Tile	591 SF	6 chipped
	9" x 9" Brown Floor Tile Mastic	591 SF	6 chipped
	9" x 9" Brown Floor Tile Mastic	172 SF	4 chipped in center
	9" x 9" Green w/White & Black Floor Tile	720 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	720 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	30 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	30 SF	Intact

<u>207</u>			
	12" x 12" Green Mottled Floor Tile	8 SF	Intact
	12" x 12" Green Mottled Floor Tile Mastic	8 SF	Intact
	12" x 12" Tan Floor Tile	60 SF	Chipped
	12" x 12" Tan Floor Tile Mastic	60 SF	Chipped
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Green Floor Tile Mastic	586 SF	6 chipped
	9" x 9" Green w/White & Black Floor Tile	676 SF	2 chipped/cracked
	9" x 9" Green w/White & Black Floor Tile Mastic	676 SF	2 chipped/cracked
	9" x 9" Grey Floor Tile	586 SF	6 chipped

Location	Material Description	Amount	Condition
<u>208</u>			
	6" Black Cove Base	75 LF	Minor damage (2 LF missing)
	6" Black Cove Base Mastic	75 LF	Minor damage (2 LF missing)
	9" x 9" Green Floor Tile	690 SF	1 chipped by heater, minor cracking throughout
	9" x 9" Grey Floor Tile Mastic	690 SF	1 chipped by heater, minor cracking throughout

208, Multi-use Bath

9" x 9" Light Green Floor Tile	64 SF	Covered with 12" x 12" tiles
9" x 9" Light Green Floor Tile Mastic	64 SF	Covered with 12" x 12" tiles

216

12" x 12" Tan Floor Tile	20 SF	Intact
12" x 12" Tan Floor Tile Mastic	20 SF	Intact
6" Black Cove Base	75 LF	15 LF missing, 6 LF detaching
6" Black Cove Base Mastic	75 LF	15 LF missing, 6 LF detaching
9" x 9" Brown Floor Tile	2 SF	Intact
9" x 9" Brown Floor Tile Mastic	2 SF	Intact
9" x 9" Brown w/Black & Beige Streaks	708 SF	Chipped
9" x 9" Brown w/Black & Beige Streaks Mastic	708 SF	Chipped
9" x 9" Green Floor Tile	690 SF	5 chipped, 1 nicked tile, 10 cracked
9" x 9" Green Floor Tile Mastic	690 SF	5 chipped, 1 nicked tile, 10 cracked
9" x 9" Light Brown w/White Floor Tile	20 SF	Intact
9" x 9" Light Brown w/White Floor Tile Mastic	20 SF	Intact

Bath by 208

12" x 12" Gray Mottled Floor Tile	90 SF	Intact
12" x 12" Gray Mottled Floor Tile Mastic	90 SF	Intact

Location	Material Description	Amount	Condition
<u>216, Multi-use Bath</u>			
	12" x 12" Tan Floor Tile	64 SF	Intact
	12" x 12" Tan Floor Tile Mastic	64 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles)	64 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles) Mastic	64 SF	Intact
<u>Bath by 216</u>			
	12" x 12" Tan Floor Tile	90 SF	Intact
	12" x 12" Tan Floor Tile Mastic	90 SF	Intact
<u>215</u>			
	12" x 12" Beige Floor Tile	2 SF	Intact
	12" x 12" Beige Floor Tile Mastic	2 SF	Intact
	12" x 12" Gray Mottled Floor Tile	5 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	5 SF	Intact
	12" x 12" Tan Floor Tile	2 SF	Intact
	12" x 12" Tan Floor Tile Mastic	2 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Green Floor Tile	690 SF	7 chipped tiles, 4 nicked, 1 missing
	9" x 9" Green Floor Tile Mastic	690 SF	7 chipped tiles, 4 nicked, 1 missing
	9" x 9" Green w/White & Black Floor Tile	671 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	671 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	70 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	70 SF	Intact

Location	Material Description	Amount	Condition
<u>214</u>			
	12" x 12" Beige Floor Tile	5 SF	Intact
	12" x 12" Beige Floor Tile Mastic	5 SF	Intact
	12" x 12" Tan Floor Tile	12 SF	Intact
	12" x 12" Tan Floor Tile Mastic	12 SF	Intact
	12" x 12" Tan w/White Floor Tile	20 SF	Intact
	12" x 12" Tan w/White Floor Tile Mastic	20 SF	Intact
	6" Black Cove Base	75 LF	Minor damage
	6" Black Cove Base Mastic	75 LF	Minor damage
	9" x 9" Brown Floor Tile	690 SF	2 chipped tiles
	9" x 9" Brown Floor Tile Mastic	690 SF	2 chipped tiles
	9" x 9" Brown w/Black & Beige Streaks	711 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks Mastic	711 SF	Intact
	9" x 9" Tan w/Black Floor Tile	2 SF	Intact
	9" x 9" Tan w/Black Floor Tile Mastic	2 SF	Intact

Location	Material Description	Amount	Condition
<u>212</u>			
	12" x 12" Gray w/White Floor Tile	10 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	10 SF	Intact
	12" x 12" Tan Floor Tile	3 SF	Intact
	12" x 12" Tan Floor Tile Mastic	3 SF	Intact
	6" Black Cove Base	75 LF	Minor damage (15 LF missing)
	6" Black Cove Base Mastic	75 LF	Minor damage (15 LF missing)
	9" x 9" Brown Floor Tile	690 SF	7 cracked\chipped tiles, 2 nicked tiles
	9" x 9" Brown Floor Tile Mastic	690 SF	7 cracked\chipped tiles, 2 nicked tiles
	9" x 9" Brown w/Black & Beige Streaks	718 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks Mastic	718 SF	Intact
	9" x 9" Light Brown w/White Floor Tile	4 SF	Intact
	9" x 9" Light Brown w/White Floor Tile Mastic	4 SF	Intact
	9" x 9" Tan w/Beige & Brown Floor Tile	3 SF	Intact
	9" x 9" Tan w/Beige & Brown Floor Tile Mastic	3 SF	Intact
	9" x 9" Tan w/Black Floor Tile	12 SF	Intact
	9" x 9" Tan w/Black Floor Tile Mastic	12 SF	Intact

Location	Material Description	Amount	Condition
<u>211</u>			
	12" x 12" Beige Floor Tile	6 SF	Intact
	12" x 12" Beige Floor Tile Mastic	6 SF	Intact
	12" x 12" Gray w/White Floor Tile	10 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	10 SF	Intact
	12" x 12" Green Mottled Floor Tile	2 SF	Intact
	12" x 12" Green Mottled Floor Tile Mastic	2 SF	Intact
	12" x 12" Tan Floor Tile	130 SF	Intact
	12" x 12" Tan Floor Tile Mastic	130 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Green Floor Tile	575 SF	5 chipped tiles
	9" x 9" Green Floor Tile Mastic	575 SF	5 chipped tiles
	9" x 9" Green w/White & Black Floor Tile	562 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	562 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	40 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	40 SF	Intact
<u>1st Floor; Above plaster ceiling</u>			
	Pipe Insulation	2000 LF	Pipe insulation above 1st floor plaster ceiling (amount assumed)
<u>2nd Floor Custodial Closet across from Stairs</u>			
	9" x 9" Brown w/Black & Beige Streaks	38 SF	Intact
	9" x 9" Brown w/Black & Beige Streaks Mastic	38 SF	Intact
	9" x 9" Light Brown w/Beige Streaks	2 SF	Intact
	9" x 9" Light Brown w/Beige Streaks Mastic	2 SF	Intact
	Pipe Fitting Insulation	6 Each	1 damaged

Location	Material Description	Amount	Condition
<u>210</u>			
	12" x 12" Beige Floor Tile	60 SF	Intact
	12" x 12" Beige Floor Tile Mastic	60 SF	Intact
	12" x 12" Gray w/White Floor Tile	40 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	40 SF	Intact
	12" x 12" Tan Floor Tile	24 SF	Intact
	12" x 12" Tan Floor Tile Mastic	24 SF	Intact
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
	9" x 9" Green Floor Tile	920 SF	3 chipped by door, 5 in room, 20 LF cracking in front
	9" x 9" Green Floor Tile Mastic	920 SF	3 chipped by door, 5 in room, 20 LF cracking in front
	9" x 9" Green w/Beige Speckled Floor Tile	3 SF	Intact
	9" x 9" Green w/Beige Speckled Floor Tile Mastic	3 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	614 SF	4 chipped
	9" x 9" Green w/White & Black Floor Tile Mastic	614 SF	4 chipped
	9" x 9" Light Green w/White & Black Floor Tile	10 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	10 SF	Intact

Location	Material Description	Amount	Condition
<u>209</u>			
	12" x 12" Gray w/White Floor Tile	20 SF	Intact
	12" x 12" Gray w/White Floor Tile Mastic	20 SF	Intact
	12" x 12" Tan Floor Tile	40 SF	Intact
	12" x 12" Tan Floor Tile Mastic	40 SF	Intact
	6" Black Cove Base	75 LF	Minor damage (10 LF missing, mastic painted)
	6" Black Cove Base Mastic	75 LF	Minor damage (10 LF missing, mastic painted)
	9" x 9" Brown Floor Tile	690 SF	15 chipped tiles on front & rear walls
	9" x 9" Brown Floor Tile Mastic	690 SF	15 chipped tiles on front & rear walls
	9" x 9" Light Brown w/Black Floor Tile	655 SF	Chipped by edge
	9" x 9" Light Brown w/Black Floor Tile Mastic	655 SF	Chipped by edge
	9" x 9" Light Brown w/White Floor Tile	33 SF	Intact
	9" x 9" Light Brown w/White Floor Tile Mastic	33 SF	Intact
	9" x 9" Tan w/Black Floor Tile	2 SF	Intact
	9" x 9" Tan w/Black Floor Tile Mastic	2 SF	Intact

Multi-use Room

9" x 9" Light Green Floor Tile	576 SF	1 chipped
9" x 9" Light Green Floor Tile Mastic	576 SF	Intact

Multi-use Room (General room/Guidance)

12" x 12" Tan Floor Tile	538 SF	Intact
12" x 12" Tan Floor Tile Mastic	538 SF	Intact
9" x 9" Floor Tile (under 12" x 12" tiles)	538 SF	Intact
9" x 9" Floor Tile (under 12" x 12" tiles) Mastic	538 SF	Intact

General Room Storage

9" x 9" Brown Floor Tile	140 SF	Intact
9" x 9" Brown Floor Tile Mastic	140 SF	Intact

Location	Material Description	Amount	Condition
<u>Clinician's Lobby</u>			
	9' x 9" Tan Floor Tile	100 SF	5 chipped
	9' x 9" Tan Floor Tile Mastic	100 SF	5 chipped
<u>Clinician's Office</u>			
	9' x 9" Tan Floor Tile	304 SF	No Access (Previous - Intact)
	9' x 9" Tan Floor Tile Mastic	304 SF	No Access (Previous - Intact)
<u>Server/Storage</u>			
	9" x 9" Brown Floor Tile	240 SF	Intact
	9" x 9" Brown Floor Tile Mastic	240 SF	Intact
<u>Guidance Offices</u>			
	9" x 9" Green Floor Tile	576 SF	2 chipped in lobby
	9" x 9" Green Floor Tile Mastic	576 SF	2 chipped in lobby
<u>Guidance - Rm. 1</u>			
	6" Black Cove Base	25 LF	Intact
	6" Black Cove Base Mastic	25 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	48 SF	2 tiles missing
	9" x 9" Green w/White & Black Floor Tile Mastic	48 SF	2 tiles missing
<u>Guidance - Rm. 2</u>			
	6" Black Cove Base	25 LF	Intact
	6" Black Cove Base Mastic	25 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	120 SF	2 SF missing
	9" x 9" Green w/White & Black Floor Tile Mastic	120 SF	2 SF missing
<u>Guidance - Rm. 3</u>			
	12" x 12" Tan Floor Tile	2 SF	Intact
	12" x 12" Tan Floor Tile Mastic	2 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	44 SF	Chipped, missing under raditor
	9" x 9" Green w/White & Black Floor Tile Mastic	44 SF	Chipped, missing under raditor
	9" x 9" Light Green w/White & Black Floor Tile	2 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	2 SF	Intact

Location	Material Description	Amount	Condition
<u>Guidance - Rm. 4</u>			
	6" Black Cove Base	25 LF	Intact
	6" Black Cove Base Mastic	25 LF	Intact
<u>Guidance - Rm. 4</u>			
	9" x 9" Green w/White & Black Floor Tile	60 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	60 SF	Intact
<u>Guidance Lobby</u>			
	6" Black Cove Base	75 LF	Intact
	6" Black Cove Base Mastic	75 LF	Intact
<u>Guidance Lobby (Hall & Closet)</u>			
	12" x 12" Beige Floor Tile	3 SF	Intact
	12" x 12" Beige Floor Tile Mastic	3 SF	Intact
	12" x 12" Tan Floor Tile	12 SF	Intact
	12" x 12" Tan Floor Tile Mastic	12 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	2 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	283 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	2 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	283 SF	Intact
<u>Main Office</u>			
	6" Black Cove Base	105 LF	3 LF missing
	6" Black Cove Base Mastic	105 LF	3 LF missing
<u>Main Office, Closet & Vault</u>			
	12" x 12" Tan Floor Tile	350 SF	2 chipped
	12" x 12" Tan Floor Tile Mastic	350 SF	2 chipped
<u>Main Office Storage</u>			
	9" x 9" Brown Floor Tile	110 SF	Intact
	9" x 9" Brown Floor Tile Mastic	110 SF	Intact

Location	Material Description	Amount	Condition
<u>Main Office Hall</u>			
	12" x 12" Tan Floor Tile	80 SF	Intact
	12" x 12" Tan Floor Tile Mastic	80 SF	Intact
	6" Black Cove Base	50 LF	Intact
	6" Black Cove Base Mastic	50 LF	Intact
<u>Principal's Office</u>			
	12" x 12" Tan Floor Tile	240 SF	Intact
	12" x 12" Tan Floor Tile Mastic	240 SF	Intact
	6" Black Cove Base	50 LF	Intact
	6" Black Cove Base Mastic	50 LF	Intact
<u>Guidance Asst. Principal's Conference Rm.</u>			
	12" x 12" Beige Floor Tile	2 SF	Intact
	12" x 12" Beige Floor Tile Mastic	2 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	77 SF	2 chipped/cracked
	9" x 9" Green w/White & Black Floor Tile Mastic	77 SF	2 chipped/cracked
	9" x 9" Light Green Floor Tile	1 SF	Intact
	9" x 9" Light Green Floor Tile Mastic	1 SF	Intact
<u>Assistant Principal's Office</u>			
	6" Black Cove Base	25 LF	2 LF detaching
	6" Black Cove Base Mastic	25 LF	2 LF detaching
<u>Conference Room (Asst. Principal Office)</u>			
	12" x 12" Tan Floor Tile	150 SF	1 chipped
	12" x 12" Tan Floor Tile Mastic	150 SF	1 chipped
<u>Guidance Asst. Principal's Office</u>			
	12" x 12" Beige Floor Tile	1 SF	Intact
	12" x 12" Beige Floor Tile Mastic	1 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	79 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	79 SF	Intact

Location	Material Description	Amount	Condition
<u>Break Room</u>			
	6" Black Cove Base	25 LF	Intact
	6" Black Cove Base Mastic	25 LF	Intact
<u>Guidance (General)</u>			
	12" x 12" Beige Floor Tile	8 SF	Cracking, 1 chipped
	12" x 12" Beige Floor Tile Mastic	8 SF	Cracking, 1 chipped
	9" x 9" Green w/White & Black Floor Tile	217 SF	3 chipped, missing by hatch
	9" x 9" Green w/White & Black Floor Tile Mastic	217 SF	3 chipped, missing by hatch
	9" x 9" Light Green Floor Tile	3 SF	Intact
	9" x 9" Light Green Floor Tile Mastic	3 SF	Intact
<u>Guidance Break Room</u>			
	9" x 9" Green w/White & Black Floor Tile	80 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	80 SF	Intact
<u>Nurse Office</u>			
	12" x 12" Gray Mottled Floor Tile	12 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	12 SF	Intact
	6" Black Cove Base	50 LF	Intact
	6" Black Cove Base Mastic	50 LF	Intact
	9" x 9" Green w/White & Black Floor Tile	115 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	115 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile	3 SF	Intact
	9" x 9" Light Green w/White & Black Floor Tile Mastic	3 SF	Intact
<u>Nurse Closet</u>			
	9" x 9" Green w/White & Black Floor Tile	18 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	18 SF	Intact

Location	Material Description	Amount	Condition
<u>Nurse Bathroom</u>			
	12" x 12" Gray Mottled Floor Tile	5 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	5 SF	Intact
	12" x 12" Tan Floor Tile	3 SF	Intact
	12" x 12" Tan Floor Tile Mastic	3 SF	Intact
	9" x 9" Brown Floor Tile	40 SF	Intact
	9" x 9" Brown Floor Tile Mastic	40 SF	Intact
<u>115</u>			
	6" Black Cove Base	30 LF	Intact
	6" Black Cove Base Mastic	30 LF	Intact
	9" x 9" Brown Floor Tile	1408 SF	Intact. Under 12" x 12" Tiles
	9" x 9" Brown Floor Tile Mastic	1408 SF	Intact. Under 12" x 12" Tiles
<u>116</u>			
	6" Black Cove Base	100 LF	Intact
	6" Black Cove Base Mastic	100 LF	Intact
<u>116 (Art Room)</u>			
	9" x 9" Green Floor Tile	816 SF	Covered
	9" x 9" Green Floor Tile Mastic	816 SF	Covered
<u>116 Storage</u>			
	9" x 9" Green Floor Tile	120 SF	Covered
	9" x 9" Green Floor Tile Mastic	120 SF	Covered
<u>117</u>			
	6" Black Cove Base	100 LF	Intact
	6" Black Cove Base Mastic	100 LF	Intact
<u>117 & Closet</u>			
	9" x 9" Green Floor Tile	816 SF	Covered
	9" x 9" Green Floor Tile Mastic	816 SF	Covered

Location	Material Description	Amount	Condition
<u>Custodial Office by Rm. 120</u>			
	12" x 12" Tan Floor Tile	200 SF	Intact
	12" x 12" Tan Floor Tile Mastic	200 SF	Intact
<u>Storage #1</u>			
	12" x 12" Tan Floor Tile	64 SF	Intact
	12" x 12" Tan Floor Tile Mastic	64 SF	Intact
<u>120</u>			
	6" Black Cove Base	90 LF	Intact
	6" Black Cove Base Mastic	90 LF	Intact
	9" x 9" Gray w/Black Streaks Floor Tile	460 SF	Covered
	9" x 9" Gray w/Black Streaks Floor Tile Mastic	460 SF	Covered
	9" x 9" Light Green Floor Tile	460 SF	Covered
	9" x 9" Light Green Floor Tile Mastic	460 SF	Covered
<u>Teach Room (by 120)</u>			
	6" Black Cove Base	35 LF	Intact
	6" Black Cove Base Mastic	35 LF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles)	80 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles) Mastic	80 SF	Intact

Location	Material Description	Amount	Condition
<u>119</u>			
	12' x 12" Sand Floor Tile	25 SF	Intact
	12" x 12" Dark Gray Floor Tile	10 SF	Intact
	12" x 12" Dark Gray Floor Tile Mastic	10 SF	Intact
	12" x 12" Gray Mottled Floor Tile	40 SF	Intact
	12" x 12" Gray Mottled Floor Tile Mastic	40 SF	Intact
	12" x 12" Sand Floor Tile Mastic	25 SF	Intact
	12" x 12" Tan Floor Tile	25 SF	Intact
	12" x 12" Tan Floor Tile Mastic	25 SF	Intact
	9" x 9" Brown w\White Streak Floor Tile	10 SF	Intact
	9" x 9" Brown w\White Streak Floor Tile Mastic	10 SF	Intact
	9" x 9" Gray w\Black Streak Floor Tile	200 SF	Intact
	9" x 9" Gray w\Black Streak Floor Tile Mastic	200 SF	Intact
	9" x 9" Green w/White & Black Floor Tile	40 SF	Intact
	9" x 9" Green w/White & Black Floor Tile Mastic	40 SF	Intact
	9" x 9" Green/Brown Floor Tile	414 SF	2 missing tiles & 5 chipped
	9" x 9" Green/Brown Floor Tile Mastic	414 SF	2 missing tile & 5 chipped
	9" x 9" Light Green Floor Tile	50 SF	Intact
	9" x 9" Light Green Floor Tile Mastic	50 SF	Intact
	Fire Door	1 Each	Intact
	Transite Panel	100 SF	Intact (Behind Uni-Vents)

<u>118</u>			
	12" x 12" Brown Mottled Floor Tile - Rm. 118	943 SF	19 LF cracking/chipped
	12" x 12" Brown Mottled Floor Tile Mastic- Rm. 118	943 SF	19 LF cracking/chipped
	Transite Panel	100 SF	Intact (Behind Uni-Vents)

Location	Material Description	Amount	Condition
<u>121A</u>			
	12" x 12" Tan Floor Tile	690 SF	1 chipped tile
	12" x 12" Tan Floor Tile Mastic	690 SF	1 chipped tile
	9" x 9" Floor Tile (under 12" x 12" tiles)	690 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles) Mastic	690 SF	Intact
<u>122A</u>			
	Transite Panel	75 SF	Intact (Behind Uni-Vents)
<u>121B</u>			
	12" x 12" Tan Floor Tile	690 SF	Intact (2 nicked)
	12" x 12" Tan Floor Tile Mastic	690 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles)	690 SF	Intact
	9" x 9" Floor Tile (under 12" x 12" tiles) Mastic	690 SF	Intact
	Transite Panel	50 SF	Intact (Behind Uni-Vents)
<u>120 - Adjacent Hall</u>			
	9" x 9" Light Green Floor Tile	1024 SF	13 chipped tiles
	9" x 9" Light Green Floor Tile Mastic	1024 SF	13 chipped tiles
<u>Lobby (Outside of Lobby Room)</u>			
	6" Black Cove Base	30 LF	Intact
	6" Black Cove Base Mastic	30 LF	Intact
<u>Lobby Room outside of Auditorium</u>			
	6" Black Cove Base	35 LF	Intact
	6" Black Cove Base Mastic	35 LF	Intact
<u>Auditorium</u>			
	9" x 9" Gray w\Black Streak Floor Tile	460 SF	Intact
	9" x 9" Gray w\Black Streak Floor Tile Mastic	460 SF	Intact
	Duct Seam Sealant	50 LF	Intact
	Joint Sealer Insulation	150 SF	Exposed

Location	Material Description	Amount	Condition
<u>Literacy</u>			
	6" Black Cove Base	100 LF	Minor damage
	6" Black Cove Base Mastic	100 LF	Minor damage
<u>Stage</u>			
	Fire Curtain	600 SF	Intact
	Wiring	300 LF	Not Observed
<u>Boiler Rm. - Adjacent Room</u>			
	Fire Door	1 Each	Intact
	Plaster Ceiling - Boiler Room	1050 SF	Intact
<u>Tank Room</u>			
	Tank Insulation	200 SF	Minor gouges & tears
<u>Boiler Room - Crawlspace</u>			
	Pipe Insulation	750 LF	Limited access. Debris & exposed ends
<u>Cafeteria</u>			
	12" x 12" Tan Floor Tile	2 SF	Chipped
	12" x 12" Tan Floor Tile Mastic	2 SF	Chipped
	12" x 12" Tan w/White Floor Tile	1387 SF	Intact
	12" x 12" Tan w/White Floor Tile Mastic	1387 SF	Intact
	6" Black Cove Base	200 LF	Intact
	6" Black Cove Base Mastic	200 LF	Intact
	9" x 9" Light Brown w/White Floor Tile	2230 SF	Minor damage
	9" x 9" Light Brown w/White Floor Tile Mastic	2230 SF	Minor damage
<u>Teacher's Dining</u>			
	6" Black Cove Base	105 LF	2 LF missing
	6" Black Cove Base Mastic	105 LF	2 LF missing
<u>Gym</u>			
	9" x 9" Green Floor Tile	552 SF	1 chipped tile
	9" x 9" Green Floor Tile Mastic	552 SF	1 chipped on landing

Location Material Description

Amount Condition

Girl's Locker Room

Pipe Insulation

130 LF 4 exposed ends

Girl's Locker Room Bathroom

Pipe Insulation

115 LF 2 Exposed ends, 2 LF Cracking

Hallway by Girl's Locker Room

Pipe Insulation

100 LF Intact

Boy's Locker Rm. & Storage

Pipe Insulation

30 LF Intact

Boy's Locker Rm. Bathroom

Pipe Insulation

30 LF Abated

Visitor's Locker Room

Pipe Insulation

40 LF Abated

Gym Basement 125, Mass Science Resource Center


9" x 9" Brown Floor Tile

816 SF 5 chipped tiles

9" x 9" Brown Floor Tile Mastic

816 SF 5 chipped tiles

Inspector: Justin Levesque



Date: 1/25/2024



EMSL Analytical, Inc.

10-39 45th Road Long Island City, NY 11101

Tel/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 032313147

Customer ID: ATC62

Customer PO: 11-81-0030

Project ID:

Attention: Brian Williams
Atlas Technical
73 William Franks Drive
West Springfield, MA 01089

Phone:

Fax: (413) 781-3734

Received Date: 10/11/2023 10:04 AM

Analysis Date: 10/11/2023

Collected Date: 10/10/2023

Project: 183COW2359/ Chandler Elementary School/ 114 Chandler St Worcester

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 10/11/2023

Sample Receipt Time: 10:04 AM

Analysis Completed Date: 10/11/2023

Analysis Completed Time: 7:15 PM

Analyst(s):

Kerrie Gibson

Kerrie Gibson PLM (1)

M. Fragoso

Madison Fragoso PLM (2)

Samples Reviewed and approved by:

Charles Johnson

Charles Johnson, Asbestos Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Long Island City, NY AIHA LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NJ NY022, CT PH-0170, MA AA000170

Initial report from: 10/11/2023 19:40:02

Elm Park Community School - Periodic Survey Report - Fall/Winter 2023

Location	Material Description	Amount	Condition
<u>134/Computer</u>			
	9" x 9" White w\Brown Floor Tile	700 SF	40 LF cracking under area rug
	9" x 9" White w\Brown Floor Tile Mastic	700 SF	Intact
<u>139 Art Room</u>			
	9" x 9" White w\Black Floor Tile	1300 SF	Intact
	9" x 9" White w\Black Floor Tile Mastic	1300 SF	Intact
<u>1st Floor, Common Area</u>			
	9" x 9" Gray Floor Tile	750 SF	5 chipped tiles, Minor cracking throughout
	9" x 9" Gray Floor Tile Mastic	750 SF	Cracking tiles that are in still intact
<u>208</u>			
	9" x 9" Tan Floor Tile	750 SF	6 chipped
	9" x 9" Tan Floor Tile Mastic	750 SF	6 chipped
<u>208 R.T. Rm</u>			
	9" x 9" Tan Floor Tile	50 SF	Intact. Carpeted
	9" x 9" Tan Floor Tile Mastic	50 SF	Intact. Carpeted
<u>239 Principal's Office</u>			
	9" x 9" White w\Brown Floor Tile	180 SF	Intact
	9" x 9" White w\Brown Floor Tile Mastic	180 SF	Intact
<u>240 Conference Room</u>			
	9" x 9" Tan Floor Tile	270 SF	2 nicked tiles. Intact
	9" x 9" Tan Floor Tile Mastic	270 SF	Intact
<u>2nd Floor, Common Area</u>			
	9" x 9" Gray Floor Tile	750 SF	Very light cracking throughout, 4 chipped tiles
	9" x 9" Gray Floor Tile Mastic	750 SF	Intact

Location	Material Description	Amount	Condition
<u>Assistant Principal's Office</u>			
	9" x 9" Tan Floor Tile	110 SF	2 chipped tiles
	9" x 9" Tan Floor Tile Mastic	110 SF	2 chipped tiles
<u>Boiler Room</u>			
	Boiler Breeching	40 SF	Spot damage (< 3 SF)
	Ceiling Plaster	900 SF	Intact
	Fire Door	2 Each	Intact
	Flex Connector	1 Each	Intact
<u>Cafeteria</u>			
	9" x 9" Tan Floor Tile	2800 SF	40 LF cracking by stage, 30 nicked\chipped throughout
	9" x 9" Tan Floor Tile Mastic	2800 SF	40 LF cracking by stage, 30 nicked\chipped throughout
<u>Cafeteria Rm. 229 Storage</u>			
	9" x 9" Tan Floor Tile	200 SF	2 missing by door, 12 broken tiles
	9" x 9" Tan Floor Tile Mastic	200 SF	2 missing by door, 12 broken tiles
<u>Cafeteria Rm. 268 Storage</u>			
	9" x 9" Tan Floor Tile	350 SF	No Access (Mild cracking (Limited visibility))
	9" x 9" Tan Floor Tile Mastic	350 SF	No Access (Mild cracking (Limited visibility))
<u>Counselors Office</u>			
	9" x 9" Tan Floor Tile	100 SF	Intact
	9" x 9" Tan Floor Tile Mastic	100 SF	Intact
<u>Custodian's Closet</u>			
	9" x 9" Tan Floor Tile	100 SF	10 chipped tiles
	9" x 9" Tan Floor Tile Mastic	100 SF	10 chipped tiles
<u>E.S.L. 124</u>			
	9" x 9" Gray Floor Tile	270 SF	Intact
	9" x 9" Gray Floor Tile Mastic	270 SF	Intact

Location	Material Description	Amount	Condition
<u>Foyer</u>			
	9" x 9" Gray Floor Tile	1800 SF	4 nicked tiles
	9" x 9" Gray Floor Tile Mastic	1800 SF	Intact
<u>Gym Equip Rm. 256</u>			
	9" x 9" White w\Black Floor Tile	300 SF	1 chipped
	9" x 9" White w\Black Floor Tile Mastic	300 SF	1 chipped
<u>Gym Laundry</u>			
	9" x 9" Beige w\Brown Floor Tile	110 SF	Intact (Limited visibility)
	9" x 9" Beige w\Brown Floor Tile Mastic	110 SF	Intact (Limited visibility)
<u>Gym Office</u>			
	9" x 9" Gray Floor Tile	250 SF	Intact
	9" x 9" Gray Floor Tile Mastic	250 SF	Intact
<u>Hall (ESL 124 to 1L)</u>			
	9" x 9" Gray Floor Tile	1075 SF	5 chipped tiles
	9" x 9" Gray Floor Tile Mastic	1075 SF	5 chipped tiles
<u>Hall 1 at Library</u>			
	9" x 9" Gray Floor Tile	550 SF	Intact, very light cracking, 2 chipped tiles
	9" x 9" Gray Floor Tile Mastic	550 SF	Intact, very light cracking, 2 chipped tiles
<u>Hall 1A</u>			
	9" x 9" Gray Floor Tile	550 SF	Intact, very light cracking
	9" x 9" Gray Floor Tile Mastic	550 SF	2 worn tiles
<u>Hall 2</u>			
	9" x 9" Gray Floor Tile	380 SF	Intact
	9" x 9" Gray Floor Tile Mastic	380 SF	Intact
<u>Hall 3</u>			
	9" x 9" Gray Floor Tile	430 SF	4 worn by door
	9" x 9" Gray Floor Tile Mastic	430 SF	4 worn by door

Location	Material Description	Amount	Condition
<u>HVAC at Cafeteria (220)</u>			
	9" x 9" Tan Floor Tile	400 SF	Intact (limited visibility)
	9" x 9" Tan Floor Tile Mastic	400 SF	Intact (limited visibility)
	Flex Connector	6 Each	Intact
<u>Incinerator Room</u>			
	Fire Door	1 Each	Intact
	Incinerator Interior Insulation	40 SF	Intact
<u>Kitchen</u>			
	9" x 9" Tan Floor Tile	320 SF	Minor damage (13 nicked & 3 chipped)
	9" x 9" Tan Floor Tile Mastic	320 SF	Minor damage (13 nicked & 3 chipped)
<u>Landing</u>			
	9" x 9" Gray Floor Tile	70 SF	2 chipped tiles
	9" x 9" Gray Floor Tile Mastic	70 SF	2 chipped tiles
<u>Learning Disabilities Room</u>			
	9" x 9" White w\Black Floor Tile	300 SF	Intact
	9" x 9" White w\Black Floor Tile Mastic	300 SF	Intact
<u>Library Work Room</u>			
	9" x 9" Tan Floor Tile	850 SF	Intact. Covered with carpet
	9" x 9" Tan Floor Tile Mastic	850 SF	Intact. Covered with carpet
<u>Main Office</u>			
	9" x 9" Tan Floor Tile	520 SF	Intact
	9" x 9" Tan Floor Tile Mastic	520 SF	2 minor chipped tiles by desk, 1 by copier; 4 cracking tiles
<u>Occup. Therapy 257</u>			
	9" x 9" White w\Black Floor Tile	300 SF	Intact
	9" x 9" White w\Black Floor Tile Mastic	300 SF	Intact
<u>Office 233</u>			
	9" x 9" Tan Floor Tile	100 SF	Intact
	9" x 9" Tan Floor Tile Mastic	100 SF	Intact


Location	Material Description	Amount	Condition
<u>Office Server Room</u>			
	9" x 9" Tan w\Brown Floor Tile	200 SF	No Access (Previous - Intact)
	9" x 9" Tan w\Brown Floor Tile Mastic	200 SF	No Access (Previous - Intact)
<u>Office Storage</u>			
	9" x 9" Orange w\Brown Floor Tile	70 SF	Intact
	9" x 9" Orange w\Brown Floor Tile Mastic	70 SF	Intact
<u>Preschool 1H</u>			
	9" x 9" Tan Floor Tile	1300 SF	Intact
	9" x 9" Tan Floor Tile Mastic	1300 SF	Intact
<u>Room 116</u>			
	9" x 9" Tan w\Beige Floor Tile	240 SF	Intact
	9" x 9" Tan w\Beige Floor Tile Mastic	240 SF	Intact
<u>Room 117</u>			
	9" x 9" Tan w\Beige Floor Tile	600 SF	7 chipped tiles throughout room
	9" x 9" Tan w\Beige Floor Tile Mastic	600 SF	7 chipped tiles throughout room
	9" x 9" White w\Black Floor Tile	400 SF	3 nicked tiles
	9" x 9" White w\Black Floor Tile Mastic	400 SF	Intact
<u>Room 118</u>			
	9" x 9" White w\Black Floor Tile	260 SF	Intact (2 nicked tiles)
	9" x 9" White w\Black Floor Tile Mastic	260 SF	Intact
<u>Room 121</u>			
	9" x 9" Tan w\Beige Floor Tile	500 SF	9 nicked tiles, 2 cracking
	9" x 9" Tan w\Beige Floor Tile Mastic	500 SF	Intact
<u>Room 123</u>			
	9" x 9" Tan w\Beige Floor Tile	450 SF	6 nicked tiles
	9" x 9" Tan w\Beige Floor Tile Mastic	450 SF	Intact
<u>Room 128</u>			
	9" x 9" Tan w\Beige Floor Tile	500 SF	3 nicked tiles. Intact
	9" x 9" Tan w\Beige Floor Tile Mastic	500 SF	No Access (Previous - Intact)

Location	Material Description	Amount	Condition
<u>Room 201</u>			
	9" x 9" Beige w\White Floor Tile	750 SF	Minor chipped tiles
	9" x 9" Beige w\White Floor Tile	750 SF	5 chipped/ 13 nicked tiles throughout
<u>Room 203</u>			
	9" x 9" Beige w\White Floor Tile	800 SF	14 nicked tiles throughout
<u>Room 205</u>			
	9" x 9" Beige w\White Floor Tile	750 SF	18 nicked tiles throughout
<u>Room 211</u>			
	9" x 9" Green Floor Tile	750 SF	8 nicked tiles
	9" x 9" Green Floor Tile Mastic	750 SF	Intact
<u>Room 212</u>			
	9" x 9" Green Floor Tile	750 SF	9 nicked tiles, 27 cracking tiles
	9" x 9" Green Floor Tile Mastic	750 SF	Intact
<u>Room 215</u>			
	9" x 9" Green Floor Tile	750 SF	11 nicked tiles
	9" x 9" Green Floor Tile Mastic	750 SF	Intact
<u>Room 216</u>			
	9" x 9" Green Floor Tile	750 SF	1 cracked in center, 15 nicked tiles
	9" x 9" Green Floor Tile Mastic	750 SF	Intact
<u>Room 216 Storage</u>			
	9" x 9" Orange w\Brown Floor Tile	100 SF	30 missing /never present were shelves were located
	9" x 9" Orange w\Brown Floor Tile Mastic	100 SF	30 missing /never present were shelves were located
<u>Room 301</u>			
	9" x 9" Beige w\White Floor Tile	750 SF	14 chipped tiles throughout, 11 nicked tiles
<u>Room 303</u>			
	9" x 9" Beige w\White Floor Tile	750 SF	Covered with laminate

Location	Material Description	Amount	Condition
<u>Room 305</u>			
	9" x 9" Beige w\White Floor Tile	750 SF	9 chipped tiles throughout, 1 missing in center
<u>Room 308</u>			
	9" x 9" Tan w\Beige Floor Tile	750 SF	Covered with laminate
	9" x 9" Tan w\Beige Floor Tile Mastic	750 SF	Covered with laminate
<u>Room 311</u>			
	9" x 9" Green Floor Tile	750 SF	13 chipped tiles, 7 nicked
	9" x 9" Green Floor Tile Mastic	750 SF	13 chipped tiles
<u>Room 312</u>			
	9" x 9" Green Floor Tile	750 SF	8 chipped tiles, 5 nicked, 1/2 missing tile
	9" x 9" Green Floor Tile Mastic	750 SF	8 chipped tiles, 1/2 missing tile
<u>Room 315</u>			
	9" x 9" Green Floor Tile	750 SF	7 chipped tiles throughout
	9" x 9" Green Floor Tile Mastic	750 SF	7 chipped tiles throughout, 2 nicked
<u>Room 316</u>			
	9" x 9" Green Floor Tile	750 SF	12 chipped tiles throughout, 2 nicked
	9" x 9" Green Floor Tile Mastic	750 SF	12 chipped tiles throughout
<u>Speech 254</u>			
	9" x 9" Brown Floor Tile	120 SF	Intact
	9" x 9" Brown Floor Tile Mastic	120 SF	Intact
<u>Stairwell</u>			
	9" x 9" Gray Floor Tile	380 SF	Intact
	9" x 9" Gray Floor Tile Mastic	380 SF	Intact
<u>Stairwell 1</u>			
	9" x 9" White w\Gray Floor Tile	360 SF	4 chipped tiles
	9" x 9" White w\Gray Floor Tile Mastic	360 SF	4 chipped tiles

Location	Material Description	Amount	Condition
<u>Storage 256</u>			
	9" x 9" Brown Floor Tile	120 SF	Intact
	9" x 9" Brown Floor Tile Mastic	120 SF	Intact
<u>Storage by 1H</u>			
	9" x 9" White w\Black Floor Tile	150 SF	2 missing
	9" x 9" White w\Black Floor Tile Mastic	150 SF	2 missing
<u>Teacher's Lounge</u>			
	9" x 9" Tan Floor Tile	500 SF	2 chipped tiles
	9" x 9" Tan Floor Tile Mastic	500 SF	2 chipped tiles
<u>Teacher's Lounge Storage</u>			
	9" x 9" Tan Floor Tile	100 SF	1 nicked tile
	9" x 9" Tan Floor Tile Mastic	100 SF	Intact
<u>Teacher's Room</u>			
	9" x 9" Gray Floor Tile	500 SF	2 nicked tiles. Intact
	9" x 9" Gray Floor Tile Mastic	500 SF	Intact
<u>Top Stair at Ramp</u>			
	9" x 9" Gray Floor Tile	150 SF	Intact
	9" x 9" Gray Floor Tile Mastic	150 SF	Intact

Inspector: Justin Levesque



Date: 1/23/2024

Union Hill School - Periodic Survey Report - Fall/Winter 2023

Location	Material Description	Amount	Condition
<u>Building #1, Basement Common Area/Hall</u>			
	Pipe Insulation	65 LF	Minor cracking, 1 exposed end
<u>Building #1, Basement Electrical Rm.</u>			
	Pipe Insulation	30 LF	Intact
<u>Building #1, Basement Hallway</u>			
	Pipe Insulation	40 LF	Minor cracking, 1 exposed end
<u>Building #1, Girl's Room</u>			
	6" Black Cove Base	12 LF	Intact
	Pipe Insulation	63 LF	Minor cracking
<u>Building #1, Boy's Room</u>			
	Flex Connector	4 Each	Locked
	Pipe Insulation	18 LF	Minor gouging
<u>Building #1, Room #103</u>			
	Blackboard Adhesive	152 SF	Intact
<u>Building #1, Room #104</u>			
	2' x 4' Ceiling Tile	836 SF	Intact
<u>Building #1, Room #102</u>			
	Blackboard Adhesive	232 SF	Intact
<u>Building #1, Room #101</u>			
	Blackboard Adhesive	76 SF	Intact
<u>Building #1, 1st Floor, West Stairs (Front)</u>			
	12" x 12" Tan Floor Tile	72 SF	4 chipped
	12" x 12" Tan Floor Tile Mastic	72 SF	4 chipped
<u>Building #1, 1st Floor, East Stairs</u>			
	12" x 12" Tan Floor Tile Mastic	84 SF	5 chipped tiles
<u>Building #1, 1st Floor, East Stairs (Rear)</u>			
	12" x 12" Tan Floor Tile	84 SF	5 chipped tiles
<u>Building #1, 2nd Floor, Room #203</u>			
	Blackboard Adhesive	152 SF	Intact
<u>Building #1, 2nd Floor, Room #202</u>			
	12" x 12" Beige Mottled Floor Tile	910 SF	3 chipped tiles
	12" x 12" Beige Mottled Floor Tile Mastic	910 SF	3 chipped tiles
	Blackboard Adhesive	152 SF	Intact
<u>Building #1, 2nd Floor, Room #201</u>			
	Blackboard Adhesive	76 SF	Intact

Location	Material Description	Amount	Condition
<u>Building #1, 2nd Floor, Room #204</u>			
	2' x 4' Ceiling Tile	836 SF	Intact
	Blackboard Adhesive	128 SF	Intact
<u>Building #2, Lobby/Lobby Hall</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	840 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	840 SF	Intact
<u>Building #2, Main Office</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	154 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	154 SF	Intact
<u>Building #2, Main Office Conference Rm.</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	210 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	210 SF	Intact
<u>Building #2, Main Office Hallway</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	95 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	95 SF	Intact
<u>Building #2, Main Office Hall Closet</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	16 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	16 SF	Intact
<u>Building #2, Principal's Office</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	195 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	195 SF	Intact
<u>Building #2, Guidance Office</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	175 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	175 SF	Intact
	Pipe Fitting Insulation	2 Each	Intact
<u>Building #2, Room #1 (SPED)</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	660 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	660 SF	Intact
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Room #1B</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	630 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	630 SF	Intact (exposed in closet)
<u>Building #2, Room #2</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	924 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	924 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	4 Each	Intact
<u>Building #2, Alarm\Fire Closet</u>			
	Pipe Fitting Insulation	4 Each	1 damaged


Location	Material Description	Amount	Condition
<u>Building #2, Room #3</u>			
	12" x 12" White Floor Tile	924 SF	Intact
	12" x 12" White Floor Tile Mastic	924 SF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	924 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	924 SF	Intact
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	12 Each	Intact
<u>Building #2, Room 3/2 Exit</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	24 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	24 SF	Intact
<u>Building #2, Nurses' Center Rm.</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	247 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	247 SF	Intact
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Nurses's Rooms</u>			
	4" Dark Brown Cove Base	100 LF	Intact
	4" Dark Brown Cove Base Adhesive	100 LF	Intact
<u>Building #2, Nurses' Right Rm.</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	105 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	105 SF	Intact
<u>Building #2, Nurses' Left Rm.</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	120 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	120 SF	Intact
<u>Building #2, Room #5</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	924 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	924 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Room #4</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	924 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	924 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Room #5/4 Exit</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	24 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	24 SF	Intact
<u>Building #2, Asst. Principal's Rm./Classroom</u>			
	2' x 4' Ceiling Tile	300 SF	2 tile with a minor gouge
	4" Dark Brown Cove Base	35 LF	Intact
	4" Dark Brown Cove Base Adhesive	35 LF	Intact
	Pipe Insulation	44 LF	Intact

Location	Material Description	Amount	Condition
<u>Building #2, Asst. Principal's Stairs/Side Stage Entrance</u>			
	2' x 4' Ceiling Tile	40 SF	Intact
	9" x 9" Beige Floor Tile	40 SF	Intact
	9" x 9" Beige Floor Tile Mastic	40 SF	Intact
<u>Building #2, All Purpose Room</u>			
	12" x 12" Beige Mottled Floor Tile	2700 SF	Intact
	12" x 12" Beige Mottled Floor Tile Mastic	2700 SF	Intact
<u>Building #2, Kitchen</u>			
	4" Brown Cove Base	52 LF	Intact
	4" Brown Cove Base Adhesive	52 LF	Intact
	9" x 9" Beige Floor Tile	160 SF	Intact
	9" x 9" Beige Floor Tile Mastic	160 SF	Intact
	Flex Connector	1 Each	Intact
	Gray Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	10 LF	1 damaged by sink
<u>Building #2, Room #13</u>			
	4" Light Brown Cove Base	120 LF	Intact
	4" Light Brown Cove Base Adhesive	120 LF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Room #12</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	5 Each	Intact
<u>Building #2, Room #11</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	6 Each	Intact
<u>Building #2, Room #10</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact
	Black Sink Undercoat	1 Each	Intact

Location	Material Description	Amount	Condition
<u>Building #2, Room #9</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	8 Each	Intact
<u>Building #2, Room #8</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	3 missing in closet
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	4 Each	Intact
<u>Building #2, Room #7</u>			
	4" Light Brown Cove Base	120 LF	Intact
	4" Light Brown Cove Base Adhesive	120 LF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
	Pipe Fitting Insulation	6 Each	1 missing with debris
<u>Building #2, Room #6</u>			
	4" Light Brown Cove Base	120 LF	Intact
	4" Light Brown Cove Base Adhesive	120 LF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	875 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	875 SF	Intact (exposed in closet)
	Black Sink Undercoat	1 Each	Intact
<u>Building #2, Computer Room</u>			
	2' x 4' Ceiling Tile	500 SF	Intact
<u>Building #2, Room #14</u>			
	12" x 12" Blue Floor Tile	500 SF	Intact
	12" x 12" Blue Floor Tile Mastic	500 SF	Intact
<u>Building #2, Electrical Room</u>			
	Pipe Fitting Insulation	4 Each	1 damaged
<u>Building #2, Custodial Closet</u>			
	9" x 9" Beige Floor Tile	20 SF	Cracking throughout
	9" x 9" Beige Floor Tile Mastic	20 SF	Cracking throughout
	Pipe Fitting Insulation	12 Each	2 damaged
<u>Building #2, Front Hall by Room 5/4</u>			
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	18 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	18 SF	Intact

Location	Material Description	Amount	Condition
<u>Building #2, Hall by Room #9</u>			
	12" x 12" Brown Floor Tile	74 SF	Intact
	12" x 12" Brown Floor Tile Mastic	74 SF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	110 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	110 SF	Intact
<u>Building #2, Hall by Room #11</u>			
	12" x 12" Brown Floor Tile	492 SF	Intact
	12" x 12" Brown Floor Tile Mastic	492 SF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	740 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	740 SF	Intact
<u>Building #2, Hall by Room #6</u>			
	12" x 12" Brown Floor Tile	510 SF	Intact
	12" x 12" Brown Floor Tile Mastic	510 SF	Intact
	9" x 9" Tiles Mastic (under 12" x 12" tiles)	770 SF	Intact
	9" x 9" Tiles under 12" x 12" tiles	770 SF	Intact
<u>Building #2, Hallway</u>			
	Pipe Fitting Insulation	113 Each	Spot damage (12 each)

Inspector: Justin Levesque



Date: 1/4/2024