

Pine Hill Dam

Project Update #1 - Summer 2014

The City contracted with an engineering company to inspect, test and survey the dam in order to identify repairs that will be needed at Pine Hill Dam. That work included:

- Surveying the land around the dam as well as the entire face of the dam
- Surface inspections of the concrete
- Analysis to determine the ability of the dam spillway to convey floodwaters
- Soil borings to determine quality and condition of the soil and bedrock that supports the structure
- Corings that were drilled and tested to determine quality of the concrete and condition of the interior concrete
- Underwater sections of the dam were inspected by divers.

Below: Upstream Side



Below: Downstream Side

