



## CITY OF WORCESTER, MASSACHUSETTS



Administration & Finance  
Purchasing Division  
455 Main Street – Room 201  
Worcester, MA 01608  
(508) 799-1220  
[www.worcesterma.gov](http://www.worcesterma.gov)

May 24, 2022

To All Bidders:

Subject: **Bid No. 7814-W2, Indian Hill Park Improvements – Phase II / DPWP**

### **ADDENDUM NO. 2**

To Whom It May Concern:

With reference to our bid request relative to the above subject, please refer to the changes/modifications/clarifications to the original proposal request.

- **PLEASE SEE BELOW GENERAL BID CLARIFICATIONS INCLUDING QUESTIONS RECEIVED AND RESPONSES FROM CITY**

Q. The Communications, and Electrical handholes depicted in the electrical drawings do not match the city standards for all other parks. Can you please verify what size, and type of handholes will be required on this project?

A. The Communications, and Electrical hand holes are to be Precast concrete with cast iron frames and covers as per the contract specifications.

Q. The pedestrian pathway light poles on the drawings call out one handhole at each pole. Should there be a Communications box located at each pole getting a camera including the athletic poles?

A. Pedestrian pathway light poles require an electrical handhole at each pole and a Communication hand hole at every other pole. The camera locations will determine which pole the communication handholes will be located at. The sports poles require an electrical handhole at each pole and a Communication hand hole at every other pole. The camera locations will determine which pole the communication handholes will be located at.

Q. The pedestrian pathway light poles that will have cameras mounted on them require two Stahlin boxes for the equipment. Is it possible to have one step down transformer that services the parks camera system power circuitry? Or can



## CITY OF WORCESTER, MASSACHUSETTS



Administration & Finance  
Purchasing Division  
455 Main Street – Room 201  
Worcester, MA 01608  
(508) 799-1220  
[www.worcesterma.gov](http://www.worcesterma.gov)

the circuit originate from power panel PP in the new load center? This would eliminate the need for two Stahlin boxes on the poles making a much better appearance.

A. We have never needed to have two stahlin boxes on any light pole that was servicing cameras. When the stahlin boxes get mounted there is a backplane inside the cabinet which siemens has already mounted a power tap with a 110 duplex outlet. Generally, the electrical subcontractor for this project takes the constant 110 power from the light pole and brings it into the Stahlin and to the power tap to light up the outlet.

Q. Special Conditions Article 40 calls for an allowance for the security cameras. Does this mean the cameras will be supplied under the allowance of the article?

A. Yes

### General Bid Clarification

1. In SECTION 116813 PLAYGROUND EQUIPMENT – ADD ALTERNATE # 1, PART 1- GENERAL, 1.03 RELATED SECTIONS, Add the following: D. Article 37 – Playground Equipment.

Bidders are requested to acknowledge and/or include this addendum with bid. All other terms, conditions and specifications remain unchanged.

Very truly yours,

Christopher J. Gagliastro  
Purchasing Director