

December 11, 2024

To All Bidders:

Subject: Bid No. 8331-M5 Door & Hardware Replacement / WPS

ADDENDUM NO. 3

To Whom It May Concern:

With reference to our bid request relative to the above subject, please refer to the changes/modifications/clarifications to the original proposal request.

Questions received by our office and answers from the City:

- 1. We will need the measurements of the solid wood interior doors for the following schools:
 - a) Union Hill School bldg1, 1 Chapin Street, Worcester, MA. 01604 = 1 each This will be eliminated. A door will NOT be installed in this opening, leaving the lift readily accessible.
 - b) Grafton Street School, 311 Grafton Street, Worcester, MA. 01604 = 2 each **Boiler room in building #1** -

Door - 35-1/2" x 83-3/4" x 1-7/8" thick Hinge size - 1-1/2" wide x 4-3/8" long

Custodians' office door building #2 -

Door - 36" x 79-3/4" x 1-7/8" - no existing door Hinge Size - 1-1/2" wide x 4-3/8" long

just the cut outs - no hinges

c) May Street School, 265 May Street, Worcester, MA. 01602 = 2 each

Dimensions are same for both doors

Double doors by the cafe -

Doors - 35-1/2" x 84" x 1-7/8" thick

Hinge size - 1-3/4" wide x 4-3/8" long

- d) Lake View School, 133 Coburn Avenue, Worcester, MA. 01604 = 2 each
- 2 door on the stage. (left and right side)

Doors - 36" x 79-1/2" x 1-3/8" thick

Same for both doors

Hinge size 1-1/2" w x 3-1/2" L

Same for both doors

Note: All measurements shall be field verified by the vendor awarded the contract prior to ordering new door slabs.



Administration & Finance – Purchasing Division
Christopher J. Gagliastro, MCPPO – Purchasing Director
455 Main Street, Room 201, Worcester, MA 01608
P | 508-799-1220

purchasing@worcesterma.gov

- 2. We will need the hinge cutout size on the frame side of these 7 doors to match the new doors being installed. *See above*.
- 3. For Union Hill Building 1, the new Door 19 has a 5-foot opening with no existing doors. Would this require building a new partition with a 3' x 80" door? *This installation of a door in this area has been eliminated. There will not be a need to build out a partition wall and install a new door and frame.*
- 4. Are continuous hinges permitted for any new door installations? *Only if the existing hinge openings are non-functionable.*
- 5. Regarding Vernon Hill School, Door #13 is currently equipped with an exit device and a rim cylinder on the outside (always locked). Would it be acceptable to replace only the rim cylinder to match the new keying while keeping the existing exit device in place? *Yes.*

Bidders are requested to acknowledge and/or include this addendum with submission. All other terms, conditions and specifications remain unchanged.

Very truly yours,

Stephen R. McDonald Assistant Purchasing Director