



The City of **WORCESTER**

Administration & Finance – Purchasing Division
Christopher J. Gagliastro, MCPPO – Purchasing Director
455 Main Street, Room 201, Worcester, MA 01608
P | 508-799-1220
purchasing@worcesterma.gov

December 13, 2024

To All Bidders:

Subject: **Bid No. 8331-M5 Door & Hardware Replacement / WPS**

ADDENDUM NO. 4

To Whom It May Concern:

With reference to our bid request relative to the above subject, please refer to the changes/modifications/clarifications to the original proposal request.

Questions received by our office and answers from the City:

- 1) For Tatnuck Door #39, Goddard Building 1 Door #12 and 8, and Chandler Elementary Doors 1 and 2, the specifications call for a lever where an exit device is currently in place. Is this correct?

Tatnuck Door #39: A crash bar with an indicator locking system should be installed.

Goddard Building 1 Door #12: A crash bar with an indicator locking system should be installed.

Goddard Building 1 Door #8: A crash bar with an indicator locking system should be installed.

Chandler Elementary Doors 1 & 2: Crash bars with indicator locking systems should be installed.

- 2) Tatnuck Door #49 is currently screwed shut with shelves mounted on the interior of the classroom. Does this door require a new lock?

No, it will be eliminated from the bid

- 3) Tatnuck Door #6 currently has an exit device. The hardware sets specify an office lock; would it be acceptable to install a new rim cylinder while keeping the exit device in place?

Yes, a rim cylinder will be fine; leaving the existing exit device in place.

- 4) Tatnuck door # 11 is currently missing the door slab. Will this door be rehung before installation?

This door should be replaced. The door opening measures 34-1/8" x 83-7/8" x 1-3/4". The lockset & keying specifications remain the same.



The City of WORCESTER

Administration & Finance – Purchasing Division
Christopher J. Gagliastro, MCPPO – Purchasing Director
455 Main Street, Room 201, Worcester, MA 01608
P | 508-799-1220
purchasing@worcesterma.gov

- 5) Goddard Building 1 Door #17 has a panel attached to the door, making it 3 inches thick. Will this panel be removed prior to installation?

This door should be replaced. The door measures 36" x 83-7/8" x 1-7/8". The lockset & keying specifications remain the same.

- 6) Goddard Building 2 door # 9 would a rim exit device fitted with a rim cylinder on outside be acceptable for this application?

Yes, a rim cylinder will be fine; leaving the existing exit device in place.

Bidders are requested to acknowledge and/or include this addendum with submission. All other terms, conditions and specifications remain unchanged.

Very truly yours,

Stephen R. McDonald
Assistant Purchasing Director