

**LEAD PAINT INSPECTION SERVICES PRICING PAGE**  
**BID # CR-8734-M7**

| Item #                                                                            | Description                                                 | Est. Quantity | Unit Cost | Extended Cost     |
|-----------------------------------------------------------------------------------|-------------------------------------------------------------|---------------|-----------|-------------------|
| 1                                                                                 | Initial Lead Inspection/Surface Assessment (per unit)       | 150           | \$ 450    | \$67,500          |
| 2                                                                                 | Post-Compliance Assessment Determination (per unit)         | 50            | \$ 450    | \$22,500          |
| 3                                                                                 | Visual Re-inspection (per unit)                             | 25            | \$ 0      | \$ 0              |
| 4                                                                                 | Re-inspection for Re-occupancy (per unit)                   | 200           | \$270     | \$54,000          |
| 5                                                                                 | Re-inspections for Full Compliance (per unit)               | 200           | \$275     | \$55,000          |
| 6                                                                                 | Clearance Dust Wipes (per wipe)                             | 1000          | \$ 28     | \$28,000          |
| 7                                                                                 | Soil Risk Assessment (per property)                         | 100           | \$ 0      | \$ 0              |
| 8                                                                                 | Soil Sampling (per composite sample)                        | 300           | \$ 30     | \$9,000           |
| 9                                                                                 | Federal Risk Assessment (per unit)                          | 250           | \$400     | \$100,000         |
| 10                                                                                | Pre-dust Wipes (per wipe)                                   | 1000          | \$ 28     | \$28,000          |
| 11                                                                                | Apprenticeship cost per inspection by Master Lead Inspector | 15            | \$ 250    | \$ 3,750          |
| 12                                                                                | Site Visit fee for Soil Samples*                            | 10            | \$ 0      | \$ 0              |
| <b>Total (Items 1-12)</b>                                                         |                                                             |               |           | <b>\$367,750.</b> |
| * If Soil Samples were not taken at initial inspection due to snow-covered ground |                                                             |               |           |                   |