

# ASAP Environmental, Inc.

## LEAD PAINT INSPECTION SERVICES PRICING PAGE

BID # CR-8043-M4

Item #	Description	Est. Quantity	Unit Cost	Extended Cost
1	Initial Lead Inspection/Surface Assessment (per unit)	150	\$400	\$60,000
2	Post-Compliance Assessment Determination (per unit)	50	\$250	\$12,500
3	Visual Re-inspection (per unit)	25	\$250	\$6,250
4	Re-inspection for Re-occupancy (per unit)	200	\$250	\$50,000
5	Re-inspections for Full Compliance (per unit)	200	\$250	\$50,000
6	Clearance Dust Wipes (per wipe)	1400	\$30	\$42,000
7	Soil Risk Assessment (per property)	100	\$75	\$7,500
8	Soil Sampling (per composite sample)	300	\$75	\$22,500
9	Federal Risk Assessment (per unit)	250	\$100	\$25,000
10	Pre-dust Wipes (per wipe)	1400	\$30	\$42,000
11	Site Visit for Re-inspection Pre-dust Wipes	10	\$250	\$2,500
12	Site Visit fee for Soil Samples*	10	\$250	\$2,500
13	Apprenticeship cost per inspection by Master Lead Inspector	15	\$400	\$6,000
<b>Total (Items 1-13)</b>				<b>\$328,750</b>
* If Soil Samples were not taken at initial inspection due to snow-covered ground				

**LEAD PAINT INSPECTION SERVICES PRICING PAGE**  
**BID # CR-8043-M4**

Item #	Description	Est. Quantity	Unit Cost	Extended Cost
1	Initial Lead Inspection/Surface Assessment (per unit)	150	\$ 425	\$ 63,750
2	Post-Compliance Assessment Determination (per unit)	50	\$ 395	\$ 19,750
3	Visual Re-inspection (per unit)	25	\$ 295	\$ 7,375
4	Re-inspection for Re-occupancy (per unit)	200	\$ 295	\$ 59,000
5	Re-inspections for Full Compliance (per unit)	200	\$ 295	\$ 59,000
6	Clearance Dust Wipes (per wipe)	1400	\$ 25	\$ 35,000
7	Soil Risk Assessment (per property)	100	\$ 325	\$ 32,500
8	Soil Sampling (per composite sample)	300	\$ 30	\$ 9,000
9	Federal Risk Assessment (per unit)	250	\$ 475	\$ 118,750
10	Pre-dust Wipes (per wipe)	1400	\$ 25	\$ 35,000
11	Site Visit for Re-inspection Pre-dust Wipes	10	\$ 295	\$ 2,950
12	Site Visit fee for Soil Samples*	10	\$ 325	\$ 3,250
13	Apprenticeship cost per inspection by Master Lead Inspector	15	\$ 250	\$ 3,750
<b>Total (Items 1-13)</b>				<b>\$ 449,075</b>
* If Soil Samples were not taken at initial inspection due to snow-covered ground				

John Risko

**LEAD PAINT INSPECTION SERVICES PRICING PAGE**

**BID # CR-8043-M4**

Item #	Description	Est. Quantity	Unit Cost	Extended Cost
1	Initial Lead Inspection/Surface Assessment (per unit)	150	\$ 450	\$ 67,500
2	Post-Compliance Assessment Determination (per unit)	50	\$ 450	\$ 22,500
3	Visual Re-inspection (per unit)	25	\$ 0.00	\$ 0.00
4	Re-inspection for Re-occupancy (per unit)	200	\$ 300	\$ 60,000
5	Re-inspections for Full Compliance (per unit)	200	\$ 300	\$ 60,000
6	Clearance Dust Wipes (per wipe)	1400	\$ 25	\$ 35,000
7	Soil Risk Assessment (per property)	100	\$ 200	\$ 20,000
8	Soil Sampling (per composite sample)	300	\$ 35	\$ 10,500
9	Federal Risk Assessment (per unit)	250	\$ 250	\$ 62,500
10	Pre-dust Wipes (per wipe)	1400	\$ 25	\$ 35,000
11	Site Visit for Re-inspection Pre-dust Wipes	10	\$ 0.00	\$ 0.00
12	Site Visit fee for Soil Samples*	10	\$ 0.00	\$ 0.00
13	Apprenticeship cost per inspection by Master Lead Inspector	15	\$ 0.00	\$ 0.00
<b>Total (Items 1-13)</b>				<b>\$ 373,000</b>
* If Soil Samples were not taken at initial inspection due to snow-covered ground				