

Devon Kurtz, Chair
Diane Long, Vice-Chair
Janet Theerman, Clerk
Randolph Bloom
Tomi Stefani
Erika Helnarski, Alternate
Steven Taylor, Alternate

MINUTES OF THE PROCEEDINGS OF THE HISTORICAL COMMISSION OF THE CITY OF WORCESTER

Thursday, February, 17, 2022

Webex online at https://cow.webex.com/meet/historicalncommissionwebex and call-in number 415-655-0001 (Access Code: 1608081191).

Commissioners Present: Devon Kurtz, Chair

Diane Long, Vice-Chair Janet Theerman, Clerk Randolph Bloom Tomi Stefani

Erika Helnarski, Alternate Steven Taylor, Alternate

Commissioners Absent: None

Staff Present: Michelle Johnstone, Division of Planning & Regulatory Services (DPRS)

Stephen S. Rolle, Division of Planning & Regulatory Services (DPRS)

The February 17, 2022 Historical Commission meeting was held remotely

Call Commission to Order - 5:30 PM

Other Business

A. Review of properties recommended for inclusion in the proposed Elm Park Local Historic District preliminary study report.

Ms. Johnstone gave an overview of the intent of the evening's meeting, which was to review the integrity ratings of properties recommended for inclusion in the proposed Elm Park Local Historic District.

The Commission evaluated the properties in slides 5–84 (labeled as 113–192 given that the slides were a continuation of an earlier meeting) in Exhibit A. They agreed with the recommendations of staff for most properties, but recommended the following amendments to ratings:

Address	Rating Recommended by Staff	Rating Recommended by Commission
152 Russell Street	Good	Very Good
9 Somerset Street	Fair to Good	Good
15 Somerset Street	Very Good	Excellent
16 Somerset Street	Fair	Fair to Good
58 West Street	Good	Fair
56 William Street	Very Good	Excellent

60 William Street	Very Good	Very Good to Excellent
-------------------	-----------	------------------------

After completion of review of the properties, Ms. Johnstone described the next steps in the process to create the proposed local historic district.

List of Exhibits

Exhibit A. Slide deck shown at meeting.

Adjournment

Upon a roll call vote the Commission voted 7-0 to adjourn the meeting at approximately 7:10 p.m.

EXHIBIT A

WORCESTER HISTORICAL COMMISSION

February 17, 2022



Remote Participation Options

- To participate remotely during the public comment portion of the meeting, please call 415-655-0001 (Access Code: 160 808 1191). If you have difficulty accessing the call, please e-mail planning@worcesterma.gov.
- If you're participating via phone, you may mute, or unmute, your phone line by dialing *6 and you may raise, or lower, your hand by dialing *3.
- You may also join via WebEx at: https://cow.webex.com/meet/historicalcommissionwebex.

Rating Descriptions*

Excellent: No permanent, irreversible changes to historic core of building; no non-copacetic additions.


Very Good: Generally, buildings have experienced minimal alterations or alterations with aesthetically historically sensitive materials. Examples might include buildings with replaced porch supports, or one or two major exterior elements, like roof and/or windows, having been replaced while still retaining character-defining decorative features and at least one major exterior element, such as siding.

Good: Generally, buildings have experienced alterations up to and including replacement of siding, windows, and roof, while still being easily recognizable as a historic building of a particular style and retaining at least one original or historic exterior building element, such as lintels, cornice, etc.

Fair: Generally, buildings have had all exterior historic fabric replaced, but still are recognizable as a particular architectural style.


Poor: Generally altered beyond recognition.

*In addition to retention of original or historic fabric, condition of the building is also taken into consideration when assigning an appropriate rating.





113. 124 Russell Street, looking northeast. Integrity rating: good



114. 128 Russell Street, house and garage, looking northeast. Integrity rating: good



115. 132 Russell Street, house and garage, looking northeast. Integrity rating: good



116. 136 Russell Street house and garage, looking northeast. Integrity rating: fair



117. 140 Russell Street house and garage, looking northeast. Integrity rating: fair



118. 144 Russell Street house and garage, looking northeast. Integrity rating: good



119. 148 Russell Street, house and garage, looking northeast. Integrity rating: fair



120. 152 Russell Street, house and garage, looking northeast. Integrity rating: good



121. 156 Russell Street, looking east. Integrity rating: very good



122. 160 Russell Street, looking northeast. Integrity rating: very good



123. 164 Russell Street, looking east. Integrity rating: very good



124. 25 Sever Street, looking southeast. Integrity rating: fair



125. 26 Sever Street, looking northeast. Integrity rating: good



126. 27 Sever Street, looking west. Integrity rating: very good



127. 28 Sever Street, looking northeast. Integrity rating: very good



128. Parking lot at 29 Sever Street, looking northwest. Integrity rating: N/A



129. 30 Sever Street, looking southeast. Integrity rating: very good



130. 36 Sever Street, looking east. Integrity rating: very good



131. 38 Sever Street, looking northwest. Integrity rating: very good



132. 41 Sever Street, looking northwest. Integrity rating: very good



133. 47 Sever Street, looking southwest. Integrity rating: excellent



134. 48 Sever Street, looking southeast. Integrity rating: very good



135. 51 Sever Street, looking south from quad. Integrity rating: Excellent (non-historic)



136. 61 Sever Street, looking northwest from quad. Integrity rating: very good



137. 61 Sever Street, looking southwest. Integrity rating: very good



138. Commemorative marker, quad between 51 and 61 Sever Street, looking southwest.



139. 69 Sever Street, looking northeast. Integrity rating: very good



140. 7 Somerset Street, looking southwest. Integrity rating: fair to good



141. 9 Somerset Street, looking southwest. Integrity rating: fair to good



142. 12 Somerset Street, looking east. Integrity rating: very good



143. 15 Somerset Street, looking northwest. Integrity rating: very good



144. 16 Somerset Street, looking northeast. Integrity rating: fair



145. 17–19 Somerset Street, house and garage, looking southwest. Integrity rating: fair




146. 20 Somerset Street, looking southeast. Integrity rating: fair to good



147. 22 Somerset Street, looking east. Integrity rating: fair



148. 23 Somerset Street, looking southwest. Integrity rating: fair to good



149. 24 Somerset Street, looking southeast. Integrity rating: fair



150. 25 Somerset Street, looking southwest. Integrity rating: very good



151. 26-28 Somerset Street, house and garage, looking northeast. Integrity rating: good



152. 27 Somerset Street, looking southwest. Integrity rating: fair to good



153. 30 Somerset Street, looking northeast. Integrity rating: poor



154. 32 Somerset Street, looking southeast. Integrity rating: very good



155. 33 Somerset Street, looking southwest. Integrity rating: poor to fair



156. 34 Somerset Street, looking east. Integrity rating: fair



157. 35 Somerset Street, looking west. Integrity rating: good



158. 36 Somerset Street, looking southeast. Integrity rating: poor



159. 37 Somerset Street, house and garage, looking northwest. Integrity rating: very good



160.41 Somerset Street, looking southwest. Integrity rating: very good



161. 42 Somerset Street, looking southeast. Integrity rating: very good



162. 44 Somerset Street, looking southeast. Integrity rating: good




163. 45 Somerset Street, house and garage, looking southeast. Integrity rating: very good



164. 44 West Street, looking southwest. Integrity rating: excellent (non-historic)



165. 54 West Street, looking northwest. Integrity rating: excellent



166. 58 West Street, looking northwest. Integrity rating: good



167. Parking lot at 62 West & 49 William Street, looking south from William Street. Integrity rating: N/A



168. 72 West Street, looking west. Integrity rating: fair



169. 48 William Street (L) and 72 West Street (R), looking northwest. Integrity rating: Good, Fair



170. 50 William Street, looking north. Integrity rating: good



171. 51 William Street, looking southwest. Integrity rating: good



172. 52 William Street, house and carriage house, looking north. Integrity rating: good



173. 53 William Street, house and garage, looking southwest. Integrity rating: fair



174. 54 William Street, looking north. Integrity rating: good



175. 56 William Street, looking north. Integrity rating: very good



176. 60 William Street, looking northwest. Integrity rating: very good



177. 61 William Street, looking southwest. Integrity rating: very good



178. 62–64 William Street, looking northeast. Integrity rating: very good



179. 66 William Street, looking north. Integrity rating: very good



180. 74 William Street, looking northwest. Integrity rating: excellent



181. 75 William Street, looking south. Integrity rating: good



182. 79 William Street, house and garage, looking southeast. Integrity rating: very good



183. 80 William Street, looking northwest from William Street. Integrity rating: excellent



184. 80 William Street, looking west from Roxbury Street. (Well differentiated and reversible addition)



185. 81 William Street, looking southeast. Integrity rating: excellent



186. 84 William Street, looking northeast. Integrity rating: very good



187. 85 William Street, looking southwest. Integrity rating: excellent



188. 87 William Street, looking south. Integrity rating: excellent




189. 89 William Street, looking south. Integrity rating: good



190. 93 William Street, house and garage, looking southwest. Integrity rating: very good



191. 96 William Street, looking northwest.
Integrity rating: very good (assuming fire damage mitigation measures)



192. 98 William Street, looking northeast. Integrity rating: very good

Sample Motions

If no changes are requested: The Commission hereby approves the properties and their associated ratings recommended by city staff for inclusion in the preliminary study report for the proposed Elm Park Local Historic District.

If changes are requested: The Commission hereby approves the properties and their associated ratings for inclusion in the preliminary study report for the proposed Elm Park Local Historic District, as recommended by city staff and further amended by the Worcester Historical Commission during the course of this meeting.