

Appendix D:

Site Assessment Forms

This page left blank intentionally

City of Worcester Department of Public Works & Parks: Parks, Recreation & Cemetery Division:
For the Open Space and Recreation Plan

1	denotes lighting
1	denotes overlay
1	to confirm

[illegible]

This page left blank intentionally

District 1

Site Assessment Forms

Burncoat Street Playground

Greater Brook Valley Playground

Indian Hill Park

Indian Hill Lake Beach

Kendrick Field

Morgan Landing

Salisbury Park

Shore Park

Tacoma Street Playground

Wetherell Estate Park (Duffy Field)

This page left blank intentionally



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Burncoat Street Playground

ADDRESS: 496 Burncoat Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☐ commercial
☐ industrial district: 1 acreage: 1.26

notes: Playground section has been recently
renovated and seems to be well in use by
adjacent school and community.

USER GROUPS

☒ neighborhood ☒ city ☐ regional
☒ kids/families ☐ teens ☐ adults/elderly
☐ sports leagues
☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	1
Handball	
Volleyball	1
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	_____
☒ concrete	<u>1</u>
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	<u>1</u>
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☐ water
☐ cameras for security	☐ electric
☒ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☒ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☐ trails
☐ public lot	
☒ street	
☒ other:	<u>At school</u>

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☒ benches 4
☐ interpretive signage	☒ trash 1
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure ☒ 5-12 age structure
☐ water elements ☒ seating for caregivers
☐ drinking fountain ☒ shade
☒ swings
☐ ADA ☒ infant
☒ belt ☐ standard

- ☒ slides
- ☒ 2-5 age
- ☒ 5-12 age

Material: _____

- ☒ Individual elements:
Granite rock outcrop.

SURFACING:

material

- ☐ PIP rubber
☒ wood fiber
☐ sand
☐ other: _____

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

☐ other: _____

PLAY VALUE

motor skills

- ☐ rocking
- ☐ swinging

☐ spinning

☐ climbing

☐ sliding

- ☐ balancing

cognitive skills

- ☐ manipulative
- ☐ interactive

☐ exploratory

☐ engagement with peers

- problem solving

- ☐ other unstructured play:

PLAYGROUND NOTES:

Although playground is fairly new, mulch needs to be flush to precast concrete edging in order to be accessible.

RECOMMENDED STRATEGIES AND ACTIONS:

Maintain mulch flush with edging so that it is accessible by wheelchair.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches

☐ dugouts

☐ bleachers

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐ court surface condition

☐ good

☐ fair

☒ poor

☐ color surfacing/lines condition

☐ good

☐ fair

☒ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>3 (broken)</u>
☐ sports	_____

☐ seating

☐ team benches

☐ dugouts

☐ cleachers

☐ shade

☒ court lighting

manufacturer/condition: poor

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition
☐ good
☐ fair
☐ poor
☐ irrigation

☐ synthetic turf condition
☐ good
☐ fair
☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches ☐ bleachers
☐ dugouts ☐ shade

☐ field lighting
manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐ court surface condition
☐ good
☐ fair
☒ poor

☐ color surfacing/lines condition
☐ good
☐ fair
☒ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>3 (painted, rusted)</u>
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches ☐ cleachers
☐ dugouts ☐ shade

☒ court lighting
manufacturer/condition: poor

☐ skate park condition

☐ concrete ☐ good
☐ surface mount ☐ fair
 ☐ poor

COURT NOTES:

No accessible entrance (ADA) to courts.

ACCESSIBILITY FOR: Burncoat Street Playground

PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

School parking lot could be used as a drop off area if no cars are parked. Stalls are not painted.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☒ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Only 2-5 year old structure provides same experience for a person with a wheel chair.

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Basketball and tennis courts ☐ yes ☐ no

☐ yes ☐ no

Volleyball court (in poor condition) ☐ yes ☒ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☒ yes ☐ no
fishing piers, ect.) and equipment (i.e.
Benches, pools, shade shelters)
located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	<u>4</u>	<u>2</u>
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Need to provide defined accessible drop off and HC parking stall whether it is in school parking lot or street.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Volleyball court is in poor condition and should be renovated or removed. Next phasing of project should take into consideration court renovation with accessible route of travel to seating. Seating should be under shade for courts.



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Greater Brook Valley Playground and Roberto Clemente Field

ADDRESS: 89 Tacoma Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 13.75

notes: Undeveloped land across from street and connection to Worcester Housing Authority.

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other: Permitted use

NEIGHBORHOOD CONTEXT

River/stream could be maintained and monitored for the enjoyment of the public.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	2
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	1
Multipurpose Field	
Little League	
Softball	1
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	1
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	1
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt 2

☐ concrete

☐ pavers

☒ aggregate/ stonedust 3

☐ other:

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting☐ pedestrian☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route☐ sidewalk

☒ parking

☒ public lot☐ street

☐ trails

☐ other:

SITE FURNISHINGS

☐ picnic area

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Gravel parking lot with paved HC stalls.

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Paths are not fully accessible per ADA standards. See accessibility section.

ACCESSIBILITY FOR: Greater Brook Valley Playground

PARKING

	Lot	On-Site
Total # parking spaces:	<u> </u>	<u> </u>
# Accessible parking spaces:	<u> 2 </u>	<u> </u>
Signage ☒ Aisle 5' ☒ Aisle 8' ☐	Curbscut ☒ Min. 3', 1:12 slopes textured or painted	Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

Ramp to field is not close to HC stall.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Softball field. ☒ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☒ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Potential to have a connection to the river

edge. Need for some ADA compliant

accessible benches with shade.

Picnic Facilities

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Total # # Accessible

0

0

0

1 (poor cond.)

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☒ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

Trails along river could be improved to meet ADA standards.

CIRCULATION & CONNECTIVITY NOTES:

Staircase connecting to WHA dead-ends and doesn't connect to the park. Not all sidewalk, driveway, and parking lots are ADA compliant. No ADA pedestrian connections to and from Worcester Housing Authority (WHA).

PLANT MATERIAL NOTES:

Recent tree planting is ineffective – maintenance is required.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:


Views to the brook are needed – evident by the pedestrian desired lines.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Brook edges are eroded. Need for cleaning and vegetation management at edges of brook.

RECOMMENDED STRATEGIES & ACTIONS:

Pave parking lots and make sure cross pitch is ADA compliant. Improve paths so they are also ADA compliant. Add benches under shade of trees. Improve brook edges and provide circulation and seating to view natural resource.



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Indian Hill Park

ADDRESS: Ararat Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☒ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 3.89

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☐ teens ☐ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Fields in low density residential neighborhood and wooded backdrop.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

1	Parking Lot	
1	Park Support Bldgs.	
	ACTIVE USE	
1	Football	
1	Soccer	
	Multipurpose Field	
2	Little League	
	Softball	
	Baseball	
	Basketball	
	Tennis	
	Handball	
	Volleyball	
	Roller Hockey	
	Playground	
	Ice Skating Area	
	Sledding	
	Spray Park	
	Pool Complex	
	PASSIVE USE	
	Water Resources	
	Bathing Beach	
	Boating	
	Fishing	
	Historic Resources	
1	Monument/Memorial	
	Gazebo/Pavilion/Picnic Shelter	
	Amphitheater	
	Interpretive Signs & Kiosk	
1	Paths & Trails	
	Unprogrammed Open Lawns	
	Picnicking	
	Woodlands	
	Other: café seating area	
	Other: community gardens	
	Other: Zoo, golf	

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☒ aggregate/ stonedust	<u>2/3</u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	<u>3</u>
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☒ water
☐ cameras for security	☒ electric
☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

No benches near shade. No trash receptacles. There is a memorial for the 2002 death of teenage boys due to a fire at log cabin. Memorial is fenced off and off limits. Sign has a detail of this memorial.

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☐ trails
☒ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☒ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Gravel parking lot with no paved HC stall. Only a HC stall sign is provided. No curb cut, etc. See accessible notes.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|---|-----------------------|
| ☐ chain link | _____ |
| ☒ vinyl-coated c.l. | <u>1 (too small?)</u> |
| ☐ sports netting | _____ |

☒ seating

- | | |
|--|---|
| ☒ team benches | ☒ bleachers |
| ☒ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

Bleachers: One new has no ADA compliant access and
other old bleacher is rusted. There is a scoreboard and
just the backstop is fenced. (Note: whole park is
fenced off with CLF). No evidence of football or soccer
field overlay, except for in the aerial photos

RECOMMENDED STRATEGIES & ACTIONS:

Park support building is not fully accessible per ADA standards. Bleacher should be replaced and shade trees planted.

COURT NOTES:

BUILDINGS AND FACILITIES

BUILDING TYPE

☒ concessions

☐ comfort station

☐ community facility

☐ restrooms

☒ equipment storage

☐ changing/locker rooms

☒ press box

☐ other:_____

☐ filter building

BUILDING/FACILITIES NOTES:

ROOF

material	condition
☒ asphalt shingle	☐ good
☐ metal/standing seam	☐ fair
☐ concrete	☐ poor
☐ other: _____	

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	_____
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3-=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

Provide universal accessibility.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	16	_____
# Accessible parking spaces:	1	_____
Signage ☒	Aisle 5' ☐	Curbcut ☐
	Aisle 8' ☐	Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

Curb cuts needed to access the fields from parking lot.

Only access is from sidewalk and path is bumpy.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Little league fields (2) ☐ yes ☒ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☒ no

Note dimension and height of equipment at game areas

No access to building and to amenities – bleachers

needed and HC spots are not on concrete pad.

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	0	_____
Drinking Fountains:	0	_____
Tables:	0	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☒ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

Trails and pathways could improve to meet ADA standards.

CIRCULATION & CONNECTIVITY NOTES:

Improve ADA standards for pathways and amenities, especially around bleachers and support buildings.

PLANT MATERIAL NOTES:

Need vegetation management around edges of parks. Community was involved doing this.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Implement Master Plan.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E






CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Indian Lake Beach

ADDRESS: 20 Clason Road



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 1.76

notes: Beach seems abandoned and closed off. Sign says it in 3 languages: English, Spanish, and Vietnamese.

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☐ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: cafe seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting

 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☒ aggregate/ stonedust	<u>3 (sand)</u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☒ water
☐ cameras for security	☒ electric
☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

No benches near shade. No trash receptacles. There is a memorial for the 2002 death of teenage boys. Fire at log cabin. Memorial is fenced off and off limits. Sign has detail of this memorial.

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☐ trails
☒ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Unpaved parking lot with no HC stall is blocked by boulders, therefore only local resident might make use of it.

BUILDINGS AND FACILITIES

BUILDING TYPE

- ☐ concessions
- ☐ community facility
- ☐ equipment storage
- ☐ filter building
- ☐ comfort station
- ☒ restrooms
- ☒ changing/locker rooms
- ☐ other: _____

BUILDING/FACILITIES NOTES:

Building is closed off and in need of repair/renovation is needed if it is to be used.

ROOF

- material

condition I
- ☒ asphalt shingle

☐ good
- ☐ metal/standing seam

☐ fair
- ☐ concrete

☒ poor
- ☐ other: _____

EXTERIOR WALLS

- Material

condition rating
(1-2-3=good-fair-poor)
- ☒ CMU block

3
- ☐ concrete
- ☐ wood/vinyl/siding
- ☐ other:

FILTER BUILDING/AREA

- Material

condition rating
(1-2-3=good-fair-poor)
- ☐ fans
- ☐ louvres
- ☐ pipe conditions
- ☐ filter system
- ☐ other

RECOMMENDED STRATEGIES & ACTIONS:

Building is closed off and in need of repair/renovation if it is to be used.

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, yes, no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, yes, no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, yes, no. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☒ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☒ no
Is shade provided?	☐ yes	☒ no
Are handrails provided where necessary?	☐ yes	☒ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

Beach steps down and there is no universal access to the waterfront. There should be a handrail for safety reasons at the minimum. There is also an exposed drain manhole which is a tripping hazard.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Water quality should be tested. It is probable that the beach is in use regardless of the sign.

RECOMMENDED STRATEGIES & ACTIONS:

Fence off the site until further improvements. Develop a feasibility plan according to water quality results and probability of maintaining a clean and safe beach for the use of neighborhood.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Kendrick Field

ADDRESS: West Boylston Street to Brooks Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☒ other: During season

CONTEXT

☒ residential ☒ mixed-use ☒ commercial

☒ industrial district: 1 acreage: 14.98

notes: Front of park looking at residential area.

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

A mixed-use location, but with a definite front and back side.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	3	Park Support Bldgs.	1	ACTIVE USE		Football	1	Soccer	1	Multipurpose Field		Little League	2	Softball	1	Baseball	1	Basketball	1	Tennis		Handball		Volleyball		Roller Hockey		Playground	2	Ice Skating Area		Sledding	1	Spray Park		Pool Complex		PASSIVE USE		Water Resources		Bathing Beach		Boating		Fishing		Historic Resources		Monument/ Memorial		Gazebo/ Pavilion/ Picnic Shelter		Amphitheater		Interpretive Signs & Kiosk		Paths & Trails	1	Unprogrammed Open Lawns		Picnicking		Woodlands		Other: café seating area		Other: community gardens		Other: Zoo, golf	
-------------	---	---------------------	---	------------	--	----------	---	--------	---	--------------------	--	---------------	---	----------	---	----------	---	------------	---	--------	--	----------	--	------------	--	---------------	--	------------	---	------------------	--	----------	---	------------	--	--------------	--	-------------	--	-----------------	--	---------------	--	---------	--	---------	--	--------------------	--	--------------------	--	----------------------------------	--	--------------	--	----------------------------	--	----------------	---	-------------------------	--	------------	--	-----------	--	--------------------------	--	--------------------------	--	------------------	--

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

1

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☒ chain link

2

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas☐ blocked structures☐ ADA compliant grates

☐ utilities

☐ gas☒ water☒ electric

☐ cameras for security

☒ lighting☐ pedestrian

☒ sports☐ other

manufacturer/ model: In good condition.

PARK ACCESS

☐ public transportation

☐ bike route

☐ sidewalk

☒ parking

☒ public lot☐ street

☐ other:

SITE FURNISHINGS

☒ picnic area

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>1 (near parking at rear)</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	<u>1-2</u>

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security _____

☐ lighting ☐ pedestrian

☒ sports ☐ other

manufacturer/ model: In good condition.

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☐ benches

☐ interpretive signage ☐ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Although this parking is paved towards the bleachers
and building, it is not graded per ADA guidelines and
therefore is not fully accessible. There is no HC
designated stall either.

PLAYGROUND ASSESSMENT

COMPONENTS

☒ 2-5 age structure

☐ 5-12 age structure

☐ water elements

☐ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☒ infant

☒ belt

☐ standard

☒ slides

☒ 2-5 age

☐ 5-12 age

Material: _____

☐ Individual elements: _____

PLAY VALUE

motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other: _____

compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment:

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

No benches or shade for caregivers. To close to road and parking lot.

RECOMMENDED STRATEGIES AND ACTIONS:

Wood fiber mulch needs to be flush at edge of playground. Benches under shade could be beneficial for adult supervision.

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☐ swings

☐ ADA

☐ infant

☐ belt

☐ standard

☒ slides

☐ 2-5 age

☒ 5-12 age

Material: plastic

☐ Individual elements:

PLAY VALUE

motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

material

☐ PIP rubber

☐ wood fiber

☐ sand

☐ other

compliance

☐ meets requirements

☐ does NOT meet the requirements

manufacturer/condition of equipment

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

No ADA access or platform structure.

RECOMMENDED STRATEGIES AND ACTIONS:

Shade and seating for caregivers.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS #1 (Football/Softball)

☒ natural turf ☐ synthetic turf
condition condition
☒ good ☐ good
☐ fair ☐ fair
☐ poor ☐ poor
☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☒ sports netting	<u>1</u>

☐ seating

☐ team benches	☒ bleachers (3)
☐ dugouts	☐ shade

☒ field lighting

manufacturer/condition: good

COURTS (Basketball)

☐ court surface	☐ color surfacing/lines
condition	condition
☐ good	☒ good
☐ fair	☐ fair
☒ poor	☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>2</u>
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches	☐ cleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition: Not functional

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

ATHLETIC FIELD NOTES:

2 of 3 bleachers have a space allocated for a
wheelchair. Trash bins were close by.

COURT NOTES:

No benches, shade, or player's seating/resting area.

RECOMMENDED STRATEGIES & ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS #2 (Baseball)

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☒ irrigation | |

- ☐ dimensions meet MIAA/NFHS standards
- ☒ field fencing

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☒ chain link | <u>1 & 3 (next to LL*)</u> |
| ☐ vinyl-coated c.l. | _____ |
| ☒ sports netting | <u>1</u> |
- ☐ seating
- | | |
|---------------------------------------|---|
| ☐ team benches | ☒ bleachers (1 new) |
| ☐ dugouts | ☐ shade |
- ☐ field lighting
- manufacturer/condition: _____

ATHLETIC FIELD NOTES:

*Chain link is in good condition except for section
near the little league.

RECOMMENDED STRATEGIES & ACTIONS:

Get rid of old bleachers.

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

- ☐ dimensions meet MIAA/NFHS standards
- ☐ court fencing

- | material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |
- ☐ seating
- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |
- ☐ court lighting
- manufacturer/condition: _____

- ☐ skate park condition
- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS #3 (Little League)

- ☒ natural turf ☐ synthetic turf
condition condition
☒ good ☐ good
☐ fair ☐ fair
☐ poor ☐ poor
☒ irrigation

- ☐ dimensions meet MIAA/NFHS standards
☒ field fencing
Material condition rating
(1-2-3=good-fair-poor)
☐ chain link _____
☒ vinyl-coated c.l. 2
☒ sports netting 3

- ☐ seating
☒ team benches ☒ bleachers
☒ dugouts ☐ shade
☐ field lighting
manufacturer/condition: _____

ATHLETIC FIELD NOTES:

Batting cage and scoreboard present
Backstop in bad condition

COURTS

- ☐ court surface ☐ color surfacing/lines
condition condition
☐ good ☐ good
☐ fair ☐ fair
☐ poor ☐ poor

- ☐ dimensions meet MIAA/NFHS standards
☐ court fencing
material condition rating
(1-2-3=good-fair-poor)
☐ chain link _____
☐ vinyl-coated c.l. _____
☐ sports netting _____

- ☐ seating
☐ team benches ☐ cleachers
☐ dugouts ☐ shade
☐ court lighting
manufacturer/condition: _____

- ☐ skate park condition
☐ concrete ☐ good
☐ surface mount ☐ fair
 ☐ poor

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Bleachers are not bolted and not ADA compliant. Other bleacher is old and not ADA compliant.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS #4 (Little League)

- ☒ natural turf ☐ synthetic turf
- condition condition
- ☒ good ☐ good
- ☐ fair ☐ fair
- ☐ poor ☐ poor
- ☐ irrigation

- ☐ dimensions meet MIAA/NFHS standards
- ☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- ☐ chain link _____
- ☒ vinyl-coated c.l. 1
- ☐ sports netting _____

- ☐ seating
- ☐ team benches ☒ bleachers
- ☒ dugouts ☒ shade

- ☒ field lighting
- manufacturer/condition: good

ATHLETIC FIELD NOTES:

Bleacher hasn't returned and no ADA designated

space there is a scoreboard. Lots of community

involvement.

COURTS

- ☐ court surface ☐ color surfacing/lines
- condition condition
- ☐ good ☐ good
- ☐ fair ☐ fair
- ☐ poor ☐ poor

- ☐ dimensions meet MIAA/NFHS standards
- ☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- ☐ chain link _____
- ☐ vinyl-coated c.l. _____
- ☐ sports netting _____

- ☐ seating
- ☐ team benches ☐ cleachers
- ☐ dugouts ☐ shade

- ☐ court lighting
- manufacturer/condition: _____

- ☐ skate park condition
- ☐ concrete ☐ good
- ☐ surface mount ☐ fair
- ☐ poor

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Accessibility issues at parking lot, no painted spaces. Pathway from parking lot to field needs to be redone. 2 picnic

tables not well sited.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	2	_____
Signage ☐	Aisle 5' ☐	Curbscut ☒ Min. 3', 1:12 slopes textured or painted
	Aisle 8' ☒	Striping ☒

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

New ADA stalls at new lot. Other parking lot is not ADA compliant.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Little league 2 ☐ yes ☒ no

baseball ☐ yes ☒ no

Football/softball ☒ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☒ yes ☒ no

Note dimension and height of equipment at game areas

Some bleachers are ADA compliant.

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Park edge improvements

Accessibility improvements

Site amenities with shade (benches and bleachers)



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E







CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Morgan Landing Park

ADDRESS: Grove Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☒ low

☐ other: seasonal

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 2.89

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	1
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	1
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	1
Bathing Beach	
Boating	1
Fishing	1
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	
Other: cafe seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security _____

☐ lighting ☐ pedestrian

☒ sports ☐ other

manufacturer/ model: Fair condition

SITE INFRASTRUCTURE NOTES:

No shade trees.

SITE AMENITIES NOTES:

Need for shade trees and accessible paths.

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☒ benches

☒ interpretive signage ☐ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

All parking is permitted (8) boat trailers.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☒ good | ☐ good |
| ☐ fair | ☒ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|---------|
| ☒ chain link | 1 _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | 2 _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☒ court lighting

manufacturer/condition: poor

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

Small pavement cracks; repair fence over gate;
needs color sealcoat.

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	?
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☒ yes ☐ no

Parking Notes: No assigned/ sign / aisle or painted HC stall.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☒ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☐ yes	☒ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☒ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

No accessibility to benches/fishing pier

Picnic Facilities

Benches:

Total # 3 # Accessible 0

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

There are picnic tables but not accessible.

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Provide accessible route to some elements:

Waterfront, picnic tables, and benches.

Accessible route to fishing pier would also be beneficial.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E








CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Salisbury Park

ADDRESS: Massachusetts Avenue to Bancroft Tower Road



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☐ medium ☒ low
- ☐ other: _____

CONTEXT

- ☒ residential ☐ mixed-use ☐ commercial
- ☐ industrial district: 1 acreage: 11.98

notes: _____

USER GROUPS

- ☒ neighborhood ☒ city ☐ regional
- ☐ kids/families ☐ teens ☒ adults/elderly
- ☐ sports leagues
- ☐ other: _____

NEIGHBORHOOD CONTEXT

Single family residential, low density

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	Cracks to tower (3)
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☐ vinyl coated c.l.	
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage
☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates
☐ utilities
☐ gas ☐ water ☐ electric
☐ cameras for security
☐ lighting ☐ pedestrian
☐ sports ☐ other
manufacturer/ model: _____

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	

SITE FURNISHINGS

☐ picnic area	☒ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☒ trash (2)
☒ regulatory signage *	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

15 minute parking (5:00am – 1:00pm)

SITE INFRASTRUCTURE NOTES:

Access to the tower is through private unpaved roads.

SITE AMENITIES NOTES:

No park signage or interpretive signage which would be good because this is a beautiful historical resource.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	12	_____
# Accessible parking spaces:	?	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☒ yes ☐ no

Parking Notes:

15 minute parking from 5am – 1pm

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☒ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☒ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities

☐ yes ☒ no

Is surface material accessible?

☐ yes ☐ no

Trail dimensions and slope gradients meet all ADA requirements?

☐ yes ☐ no

Is there a handrail?

☐ yes ☐ no

Is there signage for visually impaired?

☐ yes ☐ no

Boat Docks & Fishing Facilities

☐ yes ☐ no

Is there a handrail?

☐ yes ☐ no

Are there arm rests, bait shelves, and fish cleaning tables?

☐ yes ☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Excellent 360-degree view of city (when trees have no leaves).

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Saw volunteer cleaning up vegetation and debris from park edges.

RECOMMENDED STRATEGIES & ACTIONS:

Would be nice to formalize some trails

Pavement cracks and pavement repair should be addressed around historical tower.

ADA compliant accessibility and parking around tower would allow for universal inclusion in this historical landmark.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Shore Park

ADDRESS: 115 Shore Drive



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: seasonal

CONTEXT

☐ residential ☐ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 7.04

notes: institutional

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	2 *
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☐ vinyl coated c.l.	
☐ ornamental	
☒ wood guard rail	1-2

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

*Pathway is not ADA compliant.

SITE AMENITIES NOTES:

Picnic grove appears to be popular. Tables are moveable. Some are burnt / vandalized.

PARK ACCESS

☒ public transportation

☐ bike route ☒ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☐ benches

☐ interpretive signage ☐ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	80	_____
# Accessible parking spaces:	?	_____
Signage ☐	Aisle 5' ☒ Aisle 8' ☐	Curbscut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

No assigned HC stall.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Access beach/water

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities

	☒ yes	☐ no
Is surface material accessible?	☒ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

Needs maintenance, especially at picnic area

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Lake views

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Bank erosion issues.

Trees look dry (especially around picnic grove area).

RECOMMENDED STRATEGIES & ACTIONS:

Volleyball is in poor condition (maybe over used). Building and pathways could be improved.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Tacoma Street Playground

ADDRESS: Tacoma Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 1 acreage: 18.90

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☐ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	1
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	3 (cracks)
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	3
☐ vinyl coated c.l.	
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

3 picnic tables, 1 accessible with space and accessible route up to it. 8 benches, none accessible.

SITE AMENITIES NOTES:

Sign for this park is outdated (not the Worcester Parks sign).

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☐ parking ☐ trails

☐ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☒ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☒ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA☐ infant

☐ belt☐ standard

☒ slides

☐ 2-5 age

☐ 5-12 age

Material:

☐ Individual elements:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:

compliance

☐ meets requirements

☒ does NOT meet the requirements

PLAY VALUE

motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

RECOMMENDED STRATEGIES AND ACTIONS:

Playground is non-compliant and some pieces are broken/loose. It is unsafe (from a liability standpoint).

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---------------------------------------|---|
| ☐ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☒ fair |
| ☒ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-----------|
| ☒ chain link | 3/4 _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

Hoops in good condition except for rusting of the pole. No benches or shade trees.

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	?	_____
Signage ☐	Aisle 5' ☐	Curbcut ☒ Min. 3', 1:12 slopes textured or painted
	Aisle 8' ☐	Striping ☐

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

No stripping, signage. Curb cut is not ADA compliant.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☒ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Basketball court ☐ yes ☒ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	8	0
Drinking Fountains:	_____	_____
Tables:	3	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Sidewalk not ADA accessible everywhere.

PLANT MATERIAL NOTES:

Could get rid of 3 pavement areas and make them lawn for sledding.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Some vistas.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Need better shade trees around courts and playground.

? Asphalt areas

RECOMMENDED STRATEGIES & ACTIONS:

Playground is unsafe and non-compliant.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Wetherell Estate Park (Duffy Field)

ADDRESS: Pleasant Street to Newton Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 1 acreage: 6.78

notes: Institutional (Jewish school)

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☐ teens ☐ adults/elderly

☐ sports leagues

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☒ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

SITE INFRASTRUCTURE NOTES:

No/few amenities: benches

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route

☐ parking

☐ public lot

☒ street

☐ sidewalk

☐ trails

☐ other:

SITE FURNISHINGS

☐ picnic area

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☐ benches

☐ trash

☐ bike rack

PARKING ACCESS NOTES:

Off street parking is limited. No bus stops visibility

near park.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard
- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

- ☐ Individual elements:
- _____
- In construction
- _____

SURFACING:

material

- ☐ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☐ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

Could not assess playground because it was under construction.

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|---------------|
| ☒ chain link | _____ 1 _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|---|
| ☐ team benches | ☒ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

No paved circulation. 2 bleachers are in poor
conditions.

RECOMMENDED STRATEGIES & ACTIONS:

Trees may need to be replaced.

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|---|
| ☐ team benches | ☒ bleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

COURT NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☒ yes ☐ no

Parking Notes:

No parking loan.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☐ yes	☒ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☒ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Total # # Accessible

Trail Amenities	☐ yes	☒ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Woodland in need of maintenance.

RECOMMENDED STRATEGIES & ACTIONS:

Clean up woodland.

Potential natural resource: trail connections, as evidence by desired lines



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



This page left blank intentionally

District 2

Site Assessment Forms

Bell (Chandler) Hill Park
Betty Price Playground
Burncoat (North) Park
City Hall Common
Cristoforo Colombo (East) Park
Dodge Park
Farimont Park
Grant Square
Green Hill Park
Harrington Field
Holland Rink Playground
Holmes Field
Institute Park
Korean War Memorial
Lake View Playground
Ramshorn Island Park

This page left blank intentionally



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Bell Hill Park

ADDRESS: Belmont Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☒ high
- ☒ medium
- ☐ low
- ☐ other: _____

USER GROUPS

- ☒ neighborhood
- ☒ city
- ☐ regional
- ☒ kids/families
- ☒ teens
- ☒ adults/elderly
- ☐ sports leagues
- ☐ other: _____

CONTEXT

- ☒ residential
- ☐ mixed-use
- ☐ commercial
- ☐ industrial
- district: 2
- acreage: 23.12

NEIGHBORHOOD CONTEXT

notes: _____

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	3
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	1
Boating	
Fishing	1
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☒ concrete	_____
☒ pavers	_____
☒ aggregate/ stonedust	<u>2</u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	<u>1</u>

☐ grading / drainage	☐ low/wet areas	☐ blocked structures
	☐ ADA compliant grates	

☐ utilities	☒ gas	☒ water	☒ electric
	☐ cameras for security	_____	

☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

PARK ACCESS

☒ public transportation	
☐ bike route	☒ sidewalk
☒ parking	☐ trails
☒ public lot	
☐ street	
☒ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☒ regulatory signage	☒ bike rack
☒ drinking fountain	

PARKING ACCESS NOTES:

3 HC spaces

Bus stop at entrance

SITE INFRASTRUCTURE NOTES:

No full loop around pond but a viewing platform and access to pond.

SITE AMENITIES NOTES:

Sign needs repair

Old pavilion removed, soccer fields have a concrete pad

Need for more benches (accessible near pond)

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure ☐ 5-12 age structure
☐ water elements ☒ seating for caregivers
☒ drinking fountain ☐ shade
☐ swings
☐ ADA ☐ infant
☐ belt ☐ standard

- ☐
- slides

- ☒
- 2-5 age

- ☐
- 5-12 age

Material: plastic

- ☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
☒ wood fiber
☐ sand
☐ other:

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

☐ other: _____

PLAY VALUE

motor skills

- ☐ rocking
- ☐ swinging

- ☐ spinning
☒ climbing

- ☒
- sliding

- ☒
- balancing

cognitive skills

- ☐ manipulative
- ☐ interactive

- ☐
- exploratory

- ☐ engagement with peers

- problem solving

- ☐ other unstructured play:

PLAYGROUND NOTES:

Some paint chips on balance beam, water on slide

1 ADA bench (out of 3 benches)

Playground equipment may need detail

Inspection, paint chipping evidence of old/worn out

RECOMMENDED STRATEGIES AND ACTIONS:

Add mulch to top of edge so it can be accessible by a wheelchair.

[illegible]

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☒ fair | ☐ fair |
| ☒ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

☐ chain link _____

☐ vinyl-coated c.l. _____

☐ sports netting _____

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☒ good | ☒ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

☒ chain link _____

☐ vinyl-coated c.l. _____

☐ sports _____

☐ seating

☐ team benches

☐ cleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐ poor

ATHLETIC FIELD NOTES:

Goals are in poor condition
Access by trail not ADA, no other access
Total of 1 large field and 2 practice fields

COURT NOTES:

No seating for spectators
No shaded area

RECOMMENDED STRATEGIES & ACTIONS:

Seating for players and spectators
Manage vegetation to improve trail access to the field

BUILDINGS AND FACILITIES

BUILDING TYPE

☐ concessions	☒ comfort station
☐ community facility	☒ restrooms
☐ equipment storage	☒ changing/locker rooms
☐ filter building	☐ other: _____

BUILDING/FACILITIES NOTES:

Outdoor showers (2), cross pitch is greater than 2% to access to building, therefore it is not compliant with ADA guidelines.

ROOF

material	condition I
☒ asphalt shingle	☐ good
☒ metal/standing seam	☒ fair
☐ concrete	☒ poor
☐ other: _____	

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	2-3
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	37	_____
# Accessible parking spaces:	3	_____
Signage ☒	Aisle 5' ☒	Curbcut ☒ Min. 3', 1:12 slopes textured or painted
	Aisle 8' ☒	Striping ☒

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☒ no

Parking Notes:

Need to move boulder at curb cut

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☒ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

beach ☒ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Pond has no accessible piers for fishing.

Fishing only by able peoples.

Picnic Facilities	Total #	# Accessible
Benches:	2	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☒ yes	☐ no
Is surface material accessible?	☐ yes	☒ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☒ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR:

SWIMMING FACILITIES

Beaches:	☒ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☒ yes	☒ no
Is shade provided?	☒ yes	☐ no
Are handrails provided where necessary?	☐ yes	☒ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS: DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☒ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements for accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: 1 1

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:



ADDITIONAL NOTES

More benches were requested by park user with wheelchair.

Picnic tables could be added.

Cross pitch and slopes. Building and beach seem steep.



CIRCULATION & CONNECTIVITY NOTES:

Needs cleaning and improving. Person with wheelchair using park mentioned full loop would be preferable.

PLANT MATERIAL NOTES:

Needs management.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

To the pond.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Stormwater management – existence of erosion to the pond.
Pond edge with trash and little planting.

RECOMMENDED STRATEGIES & ACTIONS:

Trash removal, benches, and site amenities.
Bathhouse in fair-poor condition, needs to be made fully accessible, as well as the beach.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photos G



Existing Conditions Photos H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Betty Price Playground

ADDRESS: Laurel Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☒ low

☐ other: Maybe high at some point

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 0.48

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	1
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	2-3
☒ concrete	w/pattern 2
☐ pavers	
☐ aggregate/ stonedust	
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	1
☒ vinyl coated c.l.	2
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☒ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Need shade around picnic tables.

Sign needs repair.

Site amenities should be prepared or replaced (circular bench is too low, picnic table is missing- only benches are in place, etc.)

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☐ parking ☐ trails

☐ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☒ trash

☐ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☒ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☐ swings

☐ ADA

☐ infant

☐ belt

☐ standard

☒ slides

☒ 2-5 age

☒ 5-12 age

Material: plastic

☐ Individual elements: pieces broken

PLAY VALUE

motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:

compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment:

Landscape Structure

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Not compliant: wood fiber has significantly worn out. Footings are exposed, play equipment has been vandalized, (Similar to Fairmont Square playground) Some pieces are unsafe (exposed bolts, etc.), picnic table near playground is broken and missing table.

RECOMMENDED STRATEGIES AND ACTIONS:

This playground has fundamental installation issues (posts are not plumb leaving unsafe gaps and which can potentially deteriorate with time). Remote unsafe elements (broken swings & exposed brackets, loose parts near slide). Consider replacing the playground in the future. In the meantime, add new wood fiber and remove broken elements/ expose fasteners, broken pieces, etc.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☒ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☒ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☒ no

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	6	2
Drinking Fountains:		
Tables:	2	1
5% of tables must be accessible		
Grill:		
Note the height of cooking surface		
Picnic Shelters:		

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Pavement needs repair in some areas

PLANT MATERIAL NOTES:

Trees planted around seating area and entrance should have a min. 3’ diameter mulch bed – as they present damage at base of trunk, probably from weed whacking.



VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Nice view of city.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Look at replacing playground structure if there is a lot of use and need from current neighborhood and adjacent communities. Consider ADA access and participation on the play activities.



Existing Conditions Photo A, B & C



Existing Conditions Photo D



Existing Conditions Photo E




Existing Conditions Photo F-I



NAME OF PARK: Burncoat Park (North Park)

An aerial photograph showing a park area with a baseball field, a pond, and surrounding residential and commercial buildings. The baseball field is located in the upper left quadrant, surrounded by trees. A large pond is situated in the center of the image. To the right of the pond are several large commercial buildings, including a prominent one with a white roof. A multi-lane highway runs horizontally across the bottom of the image, with a bridge crossing over it on the left side. Residential neighborhoods with houses and streets are visible on the left and top edges of the image.



Locus Map

USER GROUPS

☒ neighborhood ☐ city ☐ regional☐ kids/families ☐ teens ☐ adults/elderly

- sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

(list number of existing amenities)

	denotes lighting
	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	2 (cracks) _____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	2 _____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage
☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates
☐ utilities
☐ gas ☐ water ☐ electric
☐ cameras for security _____
☐ lighting ☐ pedestrian
☐ sports ☐ other
manufacturer/ model: _____

PARK ACCESS

☒ public transportation
☐ bike route ☐ sidewalk
☐ parking ☐ trails
☒ public lot
☒ street
☐ other: _____

SITE FURNISHINGS

☐ picnic area ☐ monuments
☐ shade shelter ☒ benches
☐ interpretive signage ☒ trash
☒ regulatory signage ☐ bike rack
☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

Parkview drive has ADA access and street a HC stall. Limited parking (off-street is resident permit only).

SITE AMENITIES NOTES:

Needs sign and benches around pond.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☒ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☒ chain link

_____3_____

☐ vinyl-coated c.l.

☐ sports netting

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐ court surface condition

☐ good

☐ fair

☐ poor

☐ color surfacing/lines condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports

☐ seating

☐ team benches

☐ cleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐

☐ poor

COURT NOTES:

ATHLETIC FIELDS

- ATHLETIC FIELD NOTES:**

COURTS

- COURT NOTES:**

RECOMMENDED STRATEGIES & ACTIONS:

Field needs to be reconstructed (built up).

Backstop could be replaced.

Players benches - new

ACCESSIBILITY FOR: _____

PARKING

Lot

On-Site

Total # parking spaces: 5? _____

Accessible parking spaces: ? _____

Signage ☐ Aisle 5' ☐ Aisle 8' ☐ Curbscut ☐ Min. 3', 1:12 slopes textured or painted Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☒ yes ☐ no

Parking Notes:
Accessible parking and entrances can be improved.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☒ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no
If yes, specify facility and check for accessibility
Baseball and little league ☒ yes ☐ no

Soccer, football ☒ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas
No bleachers found.

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☒ no

If no please specify:
Fishing platforms/potential lookout areas around pond.

Picnic Facilities

Benches: 6

Drinking Fountains: 0

Tables: _____

5% of tables must be accessible

Grill: _____

Note the height of cooking surface

Picnic Shelters: _____

Trail Amenities	☒ yes	☐ no
Is surface material accessible?	☒ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☒ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Need for ADA access and circulation. Pathway is too wide and has cracks with grass growing through them.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

To pond – may need improvement.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Erosion needs to be controlled. Some animals observed: turtles & bass

RECOMMENDED STRATEGIES & ACTIONS:

Potential crosswalk to viewing platforms and fishing platform. Parking small and not ADA compliant at Hanover.
Planting Edge needs to be maintained
15' pathway within park can be reconstruction throughout.
Culvert is broken on historic bridge, stream could be daylighted.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: City Hall Common

ADDRESS: 455 Main Street (behind City Hall)



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 4.37

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☒ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	1
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	1
Monument/ Memorial	6
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	1
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	1
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>2</u>
☒ concrete	<u>1</u>
☒ pavers	<u>1</u>
☐ aggregate/ stonedust	_____
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☒ ornamental	<u>1</u>
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☒ ADA compliant grates	
☐ utilities	
☒ gas	☒ water
☐ cameras for security	☒ electric
☒ lighting	☐ pedestrian
☒ sports	☐ other
manufacturer/ model: <u>Nusco lights around skating area</u>	

SITE INFRASTRUCTURE NOTES:

City Hall Common is still under renovation (Phase 3B)

SITE AMENITIES NOTES:

Café tables and skating rink are popular and well used, seasonally. Sidewalk repairs needed.

PARK ACCESS

☒ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☐ trails
☐ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☒ monuments
☐ shade shelter	☒ benches
☒ interpretive signage	☒ trash
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Limited parking underground

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	25	_____
# Accessible parking spaces:	2	_____
Signage ☐	Aisle 5' ☐	Curbscut ☒
	Aisle 8' ☐	Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☒ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Ice skating rink ☒ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no



If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Common has a total of 6 historical monuments. It would be beneficial to the public to have visually appealing interpretive signage, for visually impaired.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

More tree planting need.

RECOMMENDED STRATEGIES & ACTIONS:

Support structure for skating rink.

Follow master plan and streetscape improvements implementations that consider accessible stalls and sidewalks.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D




Existing Conditions Photo E



NAME OF PARK: Cristoforo Columbo Park (East Park)

ADDRESS: Shrewsbury Street and East Park Terrace



Aerial Oblique Photograph

Locus Map

USER GROUPS

☒high ☐medium ☐low

☐ other:☒ neighborhood ☒ city ☐ regional☐ kids/families ☐ teens ☐ adults/elderly☒ sports leagues☐ other:

NEIGHBORHOOD CONTEXT

☐residential ☒ mixed-use ☒commercial

☐ industrial district: 2 acreage: 22.95

notes:

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

	Park Support Bldgs.
	ACTIVE USE
1	Football
	Soccer
	Multipurpose Field
1	Little League
	Softball
1	Baseball
2	Basketball
1	Tennis
	Handball
	Volleyball
	Roller Hockey
	Playground
	Ice Skating Area
	Sledding
1	Spray Park
	Pool Complex
	PASSIVE USE
	Water Resources
	Bathing Beach
	Boating
	Fishing
	Historic Resources
1	Monument/Memorial
	Gazebo/Pavilion/Picnic Shelter
	Amphitheater
	Interpretive Signs & Kiosk
1	Paths & Trails
	Unprogrammed Open Lawns
	Picnicking
	Woodlands
	Other: café seating area
	Other: community gardens
	Other: Zoo, golf

 denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>2</u>
☐ concrete	<u>1</u>
☐ pavers	
☐ aggregate/ stonedust	
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	<u>1</u>
☐ vinyl coated c.l.	
☒ ornamental	<u>1</u>
☒ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security

☒ lighting ☒ pedestrian

☒ sports ☐ other

manufacturer/ model: Nusco (old/rusted pole in park)

SITE INFRASTRUCTURE NOTES:

4 picnic tables near shade shelter conditions.

SITE AMENITIES NOTES:

Amphitheater is used as a skateboard rink. (Kids coming down steps of amphitheater with bikes and skateboards)

PARK ACCESS

☒ public transportation

☐ bike route ☒ sidewalk

☒ parking ☐ trails

☒ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☒ monuments

☒ shade shelter ☒ benches

☒ interpretive signage ☒ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☒ 2-5 age structure

☐ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☒ shade

☒ swings

☐ ADA

☐ infant

☐ belt

☐ standard

☒ slides

☒ 2-5 age

☒ 5-12 age

Material: metal

☐ Individual elements: Boulders and embankment slide on PIP mound.

PLAY VALUE

motor skills

cognitive skills

☐ rocking

☐ manipulative

☒ swinging

☐ interactive

☐ spinning

☐ exploratory

☒ climbing

☐ engagement with peers

☒ sliding

☐ problem solving

☒ balancing

☐ other unstructured play:

SURFACING:

material

☒ PIP rubber

☐ wood fiber

☐ sand

☐ other:

compliance

☒ meets requirements

☐ does NOT meet the requirements

manufacturer/condition of equipment:

Little Tykes

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

New playground swings are very low (for a 5-12 year old).

RECOMMENDED STRATEGIES AND ACTIONS:

Raise swings and add an ADA swing?

Add trash receptacles near benches and picnic tables.

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☒ infant (4)

☐ belt

☐ standard

☒ slides

☐ 2-5 age

☒ 5-12 age

Material: plastic

☐ _____

☐ _____

SURFACING:

material	compliance
☐ PIP rubber	☐ meets requirements
☒ wood fiber	☒ does NOT meet the
☐ sand	requirements
☐ other: _____	

PLAYGROUND NOTES:

3 benches with spaces for wheelchair.

RECOMMENDED STRATEGIES AND ACTIONS:

Raise swings and add an ADA swing?

Change walls at old playground (there are wasps inside it.)

Add wood fiber to edge of playground.

PLAY VALUE

motor skills	cognitive skills
☐ rocking	☐ manipulative
☒ swinging	☐ interactive
☐ spinning	☐ exploratory
☒ climbing	☐ engagement with peers
☒ sliding	☐ problem solving
☒ balancing	☐ other unstructured play:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☒natural turf

☐synthetic turf

condition

☐good

☐fair

☒poor

☐irrigation

condition

☐good

☐fair

☐poor

☐dimensions meet MIAA/NFHS standards☒field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>2-3</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☒seating

☒team benches

☒bleachers

☐dugouts

☐shade

☒field lightingmanufacturer/condition: Nusco (2)

ATHLETIC FIELD NOTES:

Court light poles are rusted.

COURTS

☒court surface

☒color surfacing/lines

condition

☐good

☐fair

☒poor

condition

☐good

☒fair

☒poor

☐dimensions meet MIAA/NFHS standards☐court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	<u></u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☐seating

☐team benches

☐cleachers

☐dugouts

☐shade

☐court lightingmanufacturer/condition: ☐skate park condition

☐concrete

☐surface mount

☐good

☐fair

☐poor

COURT NOTES:

Basketball sides are missing/broken

RECOMMENDED STRATEGIES & ACTIONS:

This field is in poor condition. Fence of backstop and player’s benches are broken and should be replaced.

ACCESSIBILITY FOR: _____

PARKING

Lot

On-Site

35

Total # parking spaces:

2

Accessible parking spaces:

Signage

☐

Aisle 5'

☒

Curbcut

☒

Min. 3', 1:12 slopes textured or painted

Striping

☒

Aisle 8'

☒

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☒ yes	☐ no
Meets standards?	☒ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

baseball ☒ yes ☒ no

Little league ☐ yes ☒ no

tennis and basketball ☒ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☒ yes ☐ no

Note dimension and height of equipment at game areas

Bleachers for baseball are ADA compliant but no direct path to them. However, there is seating around with shade.

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total #

Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Could be improved to comply with ADA guidelines.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Good views from top of amphitheater.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Add trash receptacles to avoid trash accumulation under seating benches and bleachers. Remove and replace wall at old playground. Implement master plan improvements. Consider a skateboard area to avoid misuse of amphitheater. Repair broken player benches, bleachers, light poles, BB court pavement and hoops.



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C



Existing Conditions Photo E & F-I below





Existing Conditions Photo J-M



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Dodge Park

ADDRESS: [53-81] Randolph Road



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 9.09

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☐ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Established in 1890. Rededicated May 30, 2001.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Park Support Bldgs.	ACTIVE USE	Football	Soccer	Multipurpose Field	Little League	Softball	Baseball	Basketball	Tennis	Handball	Volleyball	Roller Hockey	Playground	Ice Skating Area	Sledding	Spray Park	Pool Complex	PASSIVE USE	Water Resources	Bathing Beach	Boating	Fishing	Historic Resources	Monument/ Memorial	Gazebo/Pavilion/Picnic Shelter	Amphitheater	Interpretive Signs & Kiosk	Paths & Trails	Unprogrammed Open Lawns	Picnicking	Woodlands	Other: café seating area	Other: community gardens	Other: Zoo, golf

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

- ☒ pathways material condition rating (1-2-3 = good-fair-poor)
- ☐ asphalt _____
- ☐ concrete _____
- ☒ pavers 1 _____

☒ aggregate/ stonedust 1-2 _____ ☐ other: _____

☐ fencing material condition rating (1-2-3 = good-fair-poor)

- ☐ chain link _____
- ☐ vinyl coated c.l. _____
- ☐ ornamental _____
- ☐ wood guard rail _____

- ☐ grading / drainage
- ☐ low/wet areas ☐ blocked structures
- ☐ ADA compliant grates

- ☐ utilities
- ☐ gas ☐ water ☐ electric
- ☐ cameras for security _____
- ☐ lighting ☐ pedestrian
- ☐ sports ☒ other
- manufacturer/ model: street _____

PARK ACCESS

- ☐ public transportation
- ☐ bike route ☒ sidewalk
- ☐ parking ☐ trails
- ☐ public lot
- ☒ street

SITE FURNISHINGS

- ☒ picnic area (4) ☐ monuments
- ☒ shade shelter ☒ benches
- ☒ interpretive signage ☒ trash
- ☒ regulatory signage ☒ bike rack
- ☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

No bus stop visibility near park. Sidewalk is asphalt. Path into park looks like they are more than 5%. There are 5+ benches. Some tree plantings have a sign with species name.

SITE AMENITIES NOTES:

Benches are not ADA accessible with space for a wheelchair. Some do not have an accessible route to them.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☒ no

If no please specify:

Site amenities around trails and some site furnishings at entrance.

Picnic Facilities

	Total #	# Accessible
Benches:	<u>5</u>	<u>0</u>
Drinking Fountains:	_____	_____
Tables:	<u>4</u>	<u>1</u>
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☒ yes	☐ no
Is surface material accessible?	☐ yes	☒ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

Arthur Spring Trail

CIRCULATION & CONNECTIVITY NOTES:

Bus stop may be beneficial?

Circulation within park is not all ADA accessible.

PLANT MATERIAL NOTES:

Some trees may need pruning.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Since park is uphill – good views of valley and vegetation. Interested abandoned building close to park (Odd Fellow’s Home and Memorial Building). Two pedestrian bridges cross stream within park.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

- Community built
- Intermitten stream
- Diverse bird community

RECOMMENDED STRATEGIES & ACTIONS:

Overall a nice passive park that would benefit all residents if it had better accessibility, especially at entrance area.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C-F



Existing Conditions Photo G




Existing Conditions Photo H





NAME OF PARK: Fairmont Park

An aerial photograph of a park area. In the center, there is a basketball court with a blue outer half and a red inner half. To the left of the basketball court is a sand volleyball court. The park is surrounded by green grass and numerous trees. Residential houses are visible around the perimeter of the park, including a large house on the left and several smaller houses on the right and bottom. A paved road runs along the top of the park, and a dirt path or driveway runs along the bottom. Several cars are parked on the streets and in driveways.



Locus Map

☐ high ☒ medium ☒ low

☐ other:

☒residential ☐ mixed-use ☐commercial
☐ industrial district: 2 acreage: 0.92

notes: _____

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

(list number of existing amenities)

denotes lighting
denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	2 _____

☐ grading / drainage
☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates
☐ utilities
☐ gas ☐ water ☐ electric
☐ cameras for security _____
☒ lighting ☐ pedestrian
☐ sports ☐ other
manufacturer/ model: Street Cobra

PARK ACCESS

☐ public transportation	
☐ bike route	☒ sidewalk
☐ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	<u>No parking – side streets are not paved</u>

SITE FURNISHINGS

☒ picnic area	☐ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☒ regulatory signage	☒ bike rack
☒ drinking fountain (broken)	

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

DMH exposed – very dangerous.

Problems with erosion/run off. Stormwater management needed. Problems with drainage and grading throughout site. Drinking fountain is broken, limited parking permitted on street.

SITE AMENITIES NOTES:

Benches have accessible route but no 4' space for wheelchair.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☒ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☒ belt
- ☐ standard

☒slides

☒2-5 age

☒5-12 age

Material: _____

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☐ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

Footing foundations and gravel exposed in areas with no mulch. Floor installation and grading of playground equipment color is also fading out.

RECOMMENDED STRATEGIES AND ACTIONS:

Re-design?- regrade

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS Basketball

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☒ good | ☒ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|---|--------------|
| ☐ chain link | _____ |
| ☒ vinyl-coated c.l. | <u> 1 </u> |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

May need more shade trees around play equipment.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Great views, almost 360 degrees.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Stormwater management, erosion of steep areas.

RECOMMENDED STRATEGIES & ACTIONS:

Re-design playground? Safety issues with surfacing.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C




Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Grant Square

ADDRESS: Corner of Northampton and Windsor Streets



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 1.66

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☐ adults/elderly

☐ sports leagues

NEIGHBORHOOD CONTEXT

Some housing improvements carried around the

vicinity of the park.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	1
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>2-3</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	<u>3 – very poor</u>
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☐ electric

☐ cameras for security _____

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

“Youthgrow Campus” Community Gardens

Need park sign, better definition of seating areas of paths connecting to community gardens and basketball court.

SITE AMENITIES NOTES:

Need for more benches and picnic tables around community gardens. Park looks tired but with hope from community involvement. New signage and stonedust path around community garden plot would greatly improve the look.

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☐ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☐ benches

☐ interpretive signage ☐ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS basketball

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☐ good | ☐ good |
| ☒ fair | ☒ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|----------|
| ☒ chain link | <u>3</u> |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

Lots of trash around the court area.

RECOMMENDED STRATEGIES & ACTIONS:

Fix fencing and repaint (sealcoat)

ACCESSIBILITY FOR: PARKING

Lot On-Site

Total # parking spaces: _____

Accessible parking spaces: _____

Signage ☐ Aisle 5' ☐ Curbcut ☒ Striping ☐
Aisle 8' ☐ Min. 3', 1:12 slopes
textured or painted

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

basketball ☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Community gardens

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Poor – does not connect to facilities/amenities.

PLANT MATERIAL NOTES:

Good shade trees along edges, opportunity to plant along paths or in potential seating areas.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Erosion due to lack of planting and lack of connectivity and amenities.

RECOMMENDED STRATEGIES & ACTIONS:

Improve edges, entrance, stormwater management, and make it ADA compliant. Needs design and purpose.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F





CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Green Hill Park

ADDRESS: 264 Green Hill Parkway



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☒ commercial

☐ industrial district: 2 acreage: 452.01

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☒ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	6
Park Support Bldgs.	6
ACTIVE USE	
Football	1
Soccer	2
Multipurpose Field	
Little League	1
Softball	2
Baseball	1
Basketball	
Tennis	
Handball	1
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	1
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	1
Bathing Beach	
Boating	
Fishing	
Historic Resources	1
Monument/ Memorial	2
Gazebo/Pavilion/Picnic Shelter	4
Amphitheater	
Interpretive Signs & Kiosk	1
Paths & Trails	1
Unprogrammed Open Lawns	3
Picnicking	7
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	2

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☒ aggregate/ stonedust	_____
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	1 _____

☐ grading / drainage

☐ low/wet areas ☒ blocked structures

☐ ADA compliant grates

☒ utilities

☒ gas ☒ water ☒ electric

☒ cameras for security _____

☒ lighting ☒ pedestrian

☒ sports ☒ other

manufacturer/ model: _____

PARK ACCESS

☒ public transportation

☒ bike route ☒ sidewalk

☒ parking ☒ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☒ monuments

☒ shade shelter ☒ benches

☒ interpretive signage ☒ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Need to pave parking lot at rear of softball and
baseball fields and at Skyline Drive entrance. Bus
stops closer to park would benefit other users- since
park is >450 ac

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Add benches, picnic tables, and grills/bbq.

Add shade trees

Add accessibility paths/trails

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☒ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard
- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements:

2 trash receptacles and bike racks

PLAY VALUE

- motor skills

☐ rocking

☒ swinging

☐ spinning

☒ climbing

☒ sliding

☒ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other: _____
- compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment:

Landscape Structures

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Footings are exposed.

Edges of PIP exposed.

Parts are loose and missing bolts. Slide has a crack and PIP has crack. Loose parts at climbing ladder.

RECOMMENDED STRATEGIES AND ACTIONS:

Parking needs HC signs on stalls (not compliant as it is). Fix priority hazards in playground: it is used by children younger than 5 years old.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS -Connie Mack Little League

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

- | | |
|--|---|
| ☒ team benches | ☒ bleachers (2) |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS

- | |
|--|
| ☐ court surface |
| condition |
| ☒ good |
| ☐ fair |
| ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports	_____

☒ seating (not ADA)

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☒ skate park condition

- | | |
|--|--|
| ☒ concrete | ☐ good |
| ☐ surface mount | ☒ fair |
| | ☐ poor |

Handball

- | |
|--|
| ☐ color surfacing/lines |
| condition |
| ☐ good |
| ☒ fair |
| ☐ poor |

ATHLETIC FIELD NOTES:

Edging needs maintenance. Skinned infield and
warning track needs skinned infield mat. Some
bleachers are metal.

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Bulding needs repainting (sanding) – see building notes.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS - Soccer next to LL

☒natural turf

☐synthetic turf

condition

☐good

☒fair

☐poor

☒irrigation

condition

☐good

☐fair

☐poor

☐dimensions meet MIAA/NFHS standards☐field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐chain link

☐vinyl-coated c.l.

☐sports netting

☐seating

☐team benches

☐bleachers

☐dugouts

☐shade

☐field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

COURTS

☐court surface

☐color surfacing/lines

condition

☐good

☐fair

☐poor

condition

☐good

☐fair

☐poor

☐dimensions meet MIAA/NFHS standards☐court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐chain link

☐vinyl-coated c.l.

☐sports netting

☐seating

☐team benches

☐cleachers

☐dugouts

☐shade

☐court lighting

manufacturer/condition: _____

☐skate park condition

☐concrete

☐good

☐surface mount

☐fair

☐

☐poor

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS-Softball across skating area

☒ natural turf	☐ synthetic turf
condition	condition
☐ good	☐ good
☐ fair	☐ fair
☐ poor	☐ poor
☐ irrigation	
☐ dimensions meet MIAA/NFHS standards	
☐ field fencing	
Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1-2</u>
☐ sports netting	_____
☐ seating	
☒ team benches	☒ bleachers
☐ dugouts	☐ shade
☒ field lighting	
manufacturer/condition: <u>Musco</u>	

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Plant trees.

COURTS

☐ court surface	☐ color surfacing/lines
condition	condition
☐ good	☐ good
☐ fair	☐ fair
☐ poor	☐ poor
☐ dimensions meet MIAA/NFHS standards	
☐ court fencing	
material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____
☐ seating	
☐ team benches	☐ cleachers
☐ dugouts	☐ shade
☐ court lighting	
manufacturer/condition: _____	
☐ skate park condition	
☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS-baseball next to softball

☒natural turf

☐ synthetic turf

condition

☒good

☐ fair

☐ poor

condition

☐ good

☐ fair

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports netting	_____

☒ seating

☒ team benches

☒ dugouts

☒ bleachers

☒ shade

☒ field lightingmanufacturer/condition: Musco (good)

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐court surface

☐ color surfacing/lines

condition

☐ good

☐ fair

☐ poor

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches

☐ dugouts

☐ cleachers

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS-softball

- ☒ natural turf ☐ synthetic turf
condition condition
☒ good ☐ good
☐ fair ☐ fair
☐ poor ☐ poor
☐ irrigation
☒ skinned infield (2)

- ☐ dimensions meet MIAA/NFHS standards
☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	_____ 1-2 _____
☐ sports netting	_____

- ☒ seating

- | | |
|--|------------------------------------|
| ☒ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

- ☐ field lighting
manufacturer/condition: _____

ATHLETIC FIELD NOTES:

_____ No shade at seating.
_____ No ADA access/seating

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

- ☐ dimensions meet MIAA/NFHS standards
☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

- ☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |

- ☐ court lighting
manufacturer/condition: _____

- ☐ skate park condition
- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

BUILDINGS AND FACILITIES

BUILDING TYPE-little league and soccer

- ☒ concessions
- ☐ comfort station
- ☐ community facility
- ☐ restrooms
- ☒ equipment storage
- ☐ changing/locker rooms
- ☐ filter building
- ☐ other: _____

BUILDING/FACILITIES NOTES:

Dent, some areas are rusted (concessions counter).
No sign at two HC stalls (30 total stalls). Lighting at parking in good condition. Pathway not ADA at some points.

ROOF

- material

condition I
- ☐ asphalt shingle
- ☒ good
- ☒ metal/standing seam
- ☐ fair
- ☐ concrete
- ☐ poor
- ☐ other: _____

EXTERIOR WALLS

- Material

condition rating
(1-2-3=good-fair-poor)
- ☐ CMU block
- _____
- ☐ concrete
- _____
- ☐ wood/vinyl/siding
- _____
- ☒ other: metal
- 2

FILTER BUILDING/AREA

- Material

condition rating
(1-2-3-=good-fair-poor)
- ☐ fans
- _____
- ☐ louvres
- _____
- ☐ pipe conditions
- _____
- ☐ filter system
- _____
- ☐ other
- _____

RECOMMENDED STRATEGIES & ACTIONS:

Repaint parking lot, fix lighting.

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping

Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:
These are general notes for parking lot accessibility:

ACCESS & CIRCULATION

Table with 3 columns: Question, Yes, No. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, Yes, No. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility
Soccer fields

Little league
Softball
Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:
Most activities are accessible.

Picnic Facilities
Total # # Accessible
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:
Need for more accessible site furnishings.

Table with 3 columns: Trail Amenities, Yes, No. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E




Existing Conditions Photo D



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H-J




Existing Conditions Photo K



Existing Conditions Photo L



Existing Conditions Photo M



Existing Conditions Photo N



Existing Conditions Photo O



Existing Conditions Photo P



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Harrington Field

ADDRESS: 720 Franklin Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 6.17

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	2
Baseball	
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	2
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage
☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates

☐ utilities
☐ gas ☐ water ☐ electric
☐ cameras for security _____

☐ lighting ☐ pedestrian
☐ sports ☐ other
manufacturer/ model: _____

PARK ACCESS

☐ public transportation	
☐ bike route	☒ sidewalk
☒ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☒ picnic area	☐ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Needs to be paved.

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Need to invest in new amenities with shade trees and access routes.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☒ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☒ infant
- ☒ belt
- ☐ standard
- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements:

PLAY VALUE

- motor skills

☐ rocking

☒ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☒ other: lawn (swing areas)
- compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment:

Iron Mountain Forge, Farmington, MO

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Other swing area has 7 swings of which 3 are not useable.

Area behind field has 3 infant swings and 3 belt swings; both very old

RECOMMENDED STRATEGIES AND ACTIONS:

Invest on playground and swings. Add shade, universal access. Bus stops.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS- Little league (1)

☐ natural turf condition

☒ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>1</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☐ seating

☒ team benches	☒ bleachers
☒ dugouts	☐ shade

☐ field lighting

manufacturer/condition:

ATHLETIC FIELD NOTES:

Batting cage. Backstop could be improved.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Basketball

☐ court surface condition

☐ good

☐ fair

☒ poor

☐ color surfacing/lines condition

☐ good

☐ fair

☒ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>2-3</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports	<u></u>

☐ seating

☐ team benches	☒ bleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition:

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

Not ADA accessible.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS -Softball (2)

- ☐ natural turf condition
- ☒ good
- ☐ fair
- ☐ poor
- ☐ irrigation
- ☐ synthetic turf condition
- ☐ good
- ☐ fair
- ☐ poor
- ☐ dimensions meet MIAA/NFHS standards
- ☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____
☐ seating	
☐ team benches	☐ bleachers
☐ dugouts	☐ shade
☐ field lighting	
manufacturer/condition: _____	

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

- ☐ court surface condition
- ☐ good
- ☐ fair
- ☐ poor
- ☐ color surfacing/lines condition
- ☐ good
- ☐ fair
- ☐ poor
- ☐ dimensions meet MIAA/NFHS standards
- ☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____
☐ seating	
☐ team benches	☐ bleachers
☐ dugouts	☐ shade
☐ court lighting	
manufacturer/condition: _____	

- ☐ skate park condition
- ☐ concrete
- ☐ surface mount
- ☐ good
- ☐ fair
- ☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS -Softball (3)

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |
-
- | | |
|--|---|
| ☐ dimensions meet MIAA/NFHS standards | |
| ☐ field fencing | |
| Material | condition rating (1-2-3=good-fair-poor) |
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |
-
- | | |
|--|---|
| ☐ seating | |
| ☒ team benches | ☒ bleachers |
| ☒ dugouts | ☐ shade |
-
- | | |
|---|-------|
| ☐ field lighting | |
| manufacturer/condition: | _____ |

COURTS

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
-
- | | |
|--|---|
| ☐ dimensions meet MIAA/NFHS standards | |
| ☐ court fencing | |
| material | condition rating (1-2-3=good-fair-poor) |
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |
-
- | | |
|---------------------------------------|------------------------------------|
| ☐ seating | |
| ☐ team benches | ☐ cleachers |
| ☐ dugouts | ☐ shade |
-
- | | |
|---|-------|
| ☐ court lighting | |
| manufacturer/condition: | _____ |
-
- | | |
|---|-------------------------------|
| ☐ skate park condition | |
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Improve benches and shade.

CIRCULATION & CONNECTIVITY NOTES:

ADA access to playground and fields

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Stormwater improvements

RECOMMENDED STRATEGIES & ACTIONS:

Playground improvements and universal access



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E-G



Existing Conditions Photo H-J



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Holland Rink Playground

ADDRESS: [2-14] Bates Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 3.89

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☐ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
1 Little League	
Softball	
Baseball	
2 Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
1 Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
1 Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting

 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	<u>2-3</u>
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage
☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates

☐ utilities
☐ gas ☐ water ☐ electric
☐ cameras for security _____

☐ lighting ☐ pedestrian
☐ sports ☐ other

manufacturer/ model: _____

PARK ACCESS

☒ public transportation

☐ bike route ☒ sidewalk

☐ parking ☐ trails
☐ public lot
☒ street

☐ other: _____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

There is no park sign. Access to site and parking is a problem

SITE AMENITIES NOTES:

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

2

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☒ water

☒ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route

☒ parking

☐ public lot

☒ street

☒ sidewalk

☐ trails

☐ other:

SITE FURNISHINGS

☐ picnic table

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☐ benches

☒ trash

☐ bike rack

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☐ 5-12 age structure

☐ water elements

☐ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☒ ADA 0

☒ infant 3

☒ belt 5

☐ standard

☐ slides

☐ 2-5 age

☐ 5-12 age

Material: _____

☐ Individual elements: _____

PLAY VALUE

motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

material

☐ PIP rubber

☐ wood fiber

☐ sand

☐ other: _____

compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment:

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Not compliant.

RECOMMENDED STRATEGIES AND ACTIONS:

If field becomes improved, new playground equipment may be required. As it is- no proper surfacing, old equipment, it is not compliant

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS little league

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☒ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|---|-----------------|
| ☐ chain link | _____ |
| ☒ vinyl-coated c.l. | <u>3 broken</u> |
| ☐ sports netting | _____ |

☐ seating

- | | |
|--|---|
| ☒ team benches | ☒ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☒ poor | ☒ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|---|----------|
| ☐ chain link | _____ |
| ☒ vinyl-coated c.l. | <u>3</u> |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☒ court lighting

manufacturer/condition: poor

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

No lighting. Fence is broken (some sections), stands
are broken.

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:
Limited parking

ACCESS & CIRCULATION

Table with 3 columns: Question, yes, no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, yes, no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility
Little league

basketball
Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Total # # Accessible
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Question, yes, no. Rows include: Trail Amenities, Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:


ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

ADA access and circulation is lacking.

Park is exposed to a wide avenue with high traffic that is fast flowing.

Parking / public transportation should be resolved



Existing Conditions Photo A-C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Holmes Field

ADDRESS: 140 Orient Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☒ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 2 acreage: 7.96

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☐ kids/families ☐ teens ☐ adults/elderly
☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	1
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	1
Playground	2
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

2

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

☐ grading / drainage

☐ low/wet areas☐ blocked structures☐ ADA compliant grates

☐ utilities

☐ gas☒ water☒ electric

☐ cameras for security

☐ lighting☐ pedestrian☐ sports☐ other

manufacturer/ model:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route

☒ sidewalk

☒ parking

☐ trails

☐ public lot

☒ street

☐ other:

SITE FURNISHINGS

☒ picnic table

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☐ infant

☐ belt

☒ standard

☒ slides

☐ 2-5 age

☒ 5-12 age

Material: plastic

☐ Individual elements:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:

compliance

☐ meets requirements

☒ does NOT meet the requirements

PLAY VALUE

motor skills

☐ rocking

☒ swinging

☒ spinning

☒ climbing

☒ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

Bike track around playground or tennis, sledding hill.

RECOMMENDED STRATEGIES AND ACTIONS:

Keep park open during construction. Maybe phase in construction.

ATHLETIC FIELDS

ATHLETIC FIELD NOTES:

COURT NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
		10
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	?
Signage ☐	Aisle 5' ☐	Curbscut ☒
	Aisle 8' ☐	Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☐ yes	☒ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Playground, roller hockey, baseball ☐ yes ☒ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Master plan for park



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G-I



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Institute Park

ADDRESS: 82 Salisbury Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☒ medium ☐ low

☐ other: seasonal

CONTEXT

☒ residential ☒ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 44.86

notes: Institutional

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☒ other: Worcester Polytechnic Institute

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	1
Soccer	1
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	3
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	1
Monument/Memorial	2
Gazebo/Pavilion/Picnic Shelter	2
Amphitheater	1
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>2-3</u>
☒ concrete	<u>1</u>
☒ pavers	<u>1</u>
☐ aggregate/ stonedust	<u></u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	<u></u>
☐ vinyl coated c.l.	<u></u>
☐ ornamental	<u></u>
☐ wood guard rail	<u></u>
☐ grading / drainage	
☒ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☒ utilities	
☐ gas	☒ water
☐ cameras for security	☒ electric
☒ lighting	☐ pedestrian
☐ sports	☒ other
manufacturer/ model: <u>Street cobra lights</u>	

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation	☐ sidewalk
☐ bike route	☐ trails
☒ parking	☐ public lot
	☒ street
☐ other:	<u></u>

SITE FURNISHINGS

☐ picnic area	☒ monuments
☒ shade shelter	☐ benches
☐ interpretive signage	☒ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---------------------------------------|---|
| ☐ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

COURTS 3 tennis

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☒ fair | ☒ fair |
| ☒ poor | ☒ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|---|------------|
| ☐ chain link | _____ |
| ☒ vinyl-coated c.l. | <u>2-3</u> |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☒ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

COURT NOTES:

Accessibility not defined (no paved paths or seating areas adjacent to the courts).

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted Striping ☐
Accessible parking closest to accessible entrance? ☐		
OR is there a drop off area? ☒ yes ☐ no		
Parking is by permit only? ☐ yes ☐ no		
Parking Notes:		

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☒ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no
If yes, specify facility and check for accessibility
Tennis courts ☐ yes ☒ no

Pond	☐ yes ☒ no
	☐ yes ☐ no
Are there berm cuts onto the courts?	☐ yes ☒ no
Bleachers are ADA compliant?	☐ yes ☐ no
Note dimension and height of equipment at game areas	

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☒ no

If no please specify:

No seating or fully accessible paths around the pond.

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface		
Picnic Shelters:	2	_____

Trail Amenities

	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Implement other Master plan phases



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Korean War Memorial

ADDRESS: Foster Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 0.44

notes: _____

USER GROUPS

☐ neighborhood ☒ city ☐ regional

☐ kids/families ☐ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

condition rating
(1-2-3 = good-fair-poor)

☐ asphalt

☒ concrete

1

☒ pavers

1

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☒ lighting

☐ pedestrian

☐ sports

☒ other

manufacturer/ model:

uplights for

memorial plaque

PARK ACCESS

☒ public transportation

☐ bike route

☒ sidewalk

☐ parking

☐ trails

☐ public lot

☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area

☒ monuments

☐ shade shelter

☒ benches

☒ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:



Existing Conditions Photo A



Existing Conditions Photo B



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Lake Park

ADDRESS: Lake Avenue and Hamilton Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☐ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 74.26

notes: _____

USER GROUPS

☐ neighborhood ☒ city ☒ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	3
Park Support Bldgs.	2
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	1
Baseball	1
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	1
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	1
Paths & Trails	1
Unprogrammed Open Lawns	
Picnicking	1
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material condition rating (1-2-3 = good-fair-poor)

☒ asphalt 1

☐ concrete _____

☐ pavers _____

☒ aggregate/ stonedust trails

☒ fencing material condition rating (1-2-3 = good-fair-poor)

☐ chain link _____

☐ vinyl coated c.l. _____

☐ ornamental _____

☒ wood guard rail _____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security _____

☒ lighting ☒ pedestrian

☒ sports ☐ other

manufacturer/ model: 2-3 Some are not fixed

PARK ACCESS

☒ public transportation

☒ bike route ☒ sidewalk

☒ parking ☒ trails

☒ public lot -4

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☒ shade shelter ☒ benches

☒ interpretive signage ☒ trash

☒ regulatory signage ☒ bike rack

☒ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Need some amenities improvements – benches and picnic tables.

ATHLETIC FIELDS -baseball

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>1</u>
☐ vinyl-coated c.l.	<u> </u>
☐ sports netting	<u> </u>
☒ seating	
☒ team benches	☒ bleachers
☒ dugouts	☒ shade
☒ field lighting	
manufacturer/condition: good	

Parking lot to this prime field is small (used regionally)

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>1</u>
☐ vinyl-coated c.l.	_____
☐ sports	_____
☐ seating	
☐ team benches	☐ cleachers
☐ dugouts	☐ shade
☐ court lighting	
manufacturer/condition:	

- ☐ concrete
- ☐ surface mount
- ☐ good
- ☐ fair
- ☐ poor

Parking lot is unpaved. HC stall not stripped/paved –
only sign and curb cut.

ATHLETIC FIELDS -softball

BUILDINGS AND FACILITIES

BUILDING TYPE

- ☐ concessions
- ☒ community facility
- ☒ equipment storage
- ☐ filter building
- ☐ comfort station
- ☐ restrooms
- ☐ changing/locker rooms
- ☐ other: _____

BUILDING/FACILITIES NOTES:

Building NR BB = meeting room

Building NR at other = restrooms and stone masonry (no ADA access)

ROOF

- material

☒ asphalt shingle

☐ metal/standing seam

☐ concrete

☐ other: _____
- condition I

☐ good

☒ fair

☐ poor

EXTERIOR WALLS

- Material

☐ CMU block

☐ concrete

☒ wood/vinyl/siding

☐ other: _____
- condition rating
(1-2-3=good-fair-poor)

3

stone

FILTER BUILDING/AREA

- Material

☐ fans

☐ louvres

☐ pipe conditions

☐ filter system

☐ other
- condition rating
(1-2-3=good-fair-poor)

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☒ Aisle 5' ☐ Aisle 8' ☐	Curbside ☒ Min. 3', 1:12 slopes textured or painted	Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:
Off street

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

Management

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Lake and city

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

CB direct discharge

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D




Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L-M



Existing Conditions Photo N



Existing Conditions Photo O



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Ramshorn Island

ADDRESS: 422 Belmont Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 2 acreage: 1.54

notes: _____

USER GROUPS

☐ neighborhood ☒ city ☐ regional

☐ kids/families ☐ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

There was no accessibility to this site. The only means of access is by boat.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting

☐ denotes overlay

This page left blank intentionally

District 3

Site Assessment Forms

Ball Property

Banis Street Playlot

Blackstone Gateway (Middle River) Park

Blithewood Park

Greenwood Park

Lake Park

Mulcahy Field

Oakland Heights Playground

Providence Street Playground

Vernon Hill Park

This page left blank intentionally



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Ball Property

ADDRESS: Svenson Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☐ medium ☒ low
- ☐ other: _____

CONTEXT

- ☐ residential ☒ mixed-use ☐ commercial
- ☐ industrial district: 3 acreage: 15.90

notes: _____

USER GROUPS

- ☐ neighborhood ☐ city ☐ regional
- ☐ kids/families ☐ teens ☐ adults/elderly
- ☐ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting

 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	<u>2-3</u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☐ water
☐ cameras for security	☐ electric
☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

Trail system not ADA.

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☐ parking	☒ trails
☐ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Vegetation management

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Banis Street PlayLot

ADDRESS: Dorchester and Banis Streets



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 3 acreage: 0.47

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☐ kids/families ☐ teens ☐ adults/elderly
☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Multi family

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	1
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	1
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	3 stamped
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☒ vinyl coated c.l.	2
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☐ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☒ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☒ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☒ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☐ infant

☒ belt

☐ standard

☐ slides

☐ 2-5 age

☒ 5-12 age

Material: plastic

☐ Individual elements:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:

compliance

☐ meets requirements

☒ does NOT meet the requirements

PLAY VALUE

motor skills

☐ rocking

☒ swinging

☒ spinning

☒ climbing

☒ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

In need of repair: seat wall around center island.

RECOMMENDED STRATEGIES AND ACTIONS:

manufacturer/condition of equipment:

Play World Systems

NOTE: see ADA checklist for accessibility assessment

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☒ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	2	
Drinking Fountains:		
Tables:		
5% of tables must be accessible		
Grill:		
Note the height of cooking surface		
Picnic Shelters:		

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Blackstone Gateway Park (Middle River Park)

ADDRESS: McKeon Road



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low
☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial
☐ industrial district: 3 acreage: 30

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☐ regional
☐ kids/families ☐ teens ☐ adults/elderly
☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	
Picnicking	
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☒ aggregate/ stonedust	<u>2-3</u>
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☐ water
☐ cameras for security	☐ electric
☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

Trail system not ADA.

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☐ parking	☒ trails
☐ public lot	☒ street
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Vegetation management

RECOMMENDED STRATEGIES & ACTIONS:




Existing Conditions Photo A

Existing Conditions Photo B



NAME OF PARK: Blithewood Avenue Park

An aerial photograph of a suburban neighborhood. A large, rectangular grassy field is the central feature, with a yellowish-brown patch in the lower-left corner. To the left of the field is a multi-lane road. Surrounding the field and road are numerous houses with various roof colors (grey, brown, orange) and green trees. A winding road is visible in the upper right portion of the image.



Locus Map

☒high ☐medium ☐low

☐other:

☒residential ☐ mixed-use ☐commercial
☐ industrial district: 3 acreage: 3.47

notes: _____

☒ neighborhood
 ☐ city
 ☐ regional

☐ kids/families
 ☒ teens
 ☐ adults/elderly

☐ sports leagues

(list number of existing amenities)

1	Parking Lot	
2	Park Support Bldgs.	
3	ACTIVE USE	
4	Football	
5	Soccer	
6	Multipurpose Field	
7	Little League	
8	Softball	
9	Baseball	
10	Basketball	
11	Tennis	
12	Handball	
13	Volleyball	
14	Roller Hockey	
15	Playground	
16	Ice Skating Area	
17	Sledding	
18	Spray Park	
19	Pool Complex	
20	PASSIVE USE	
21	Water Resources	
22	Bathing Beach	
23	Boating	
24	Fishing	
25	Historic Resources	
26	Monument/ Memorial	
27	Gazebo/Pavilion/Picnic Shelter	
28	Amphitheater	
29	Interpretive Signs & Kiosk	
30	Paths & Trails	
31	Unprogrammed Open Lawns	
32	Picnicking	
33	Woodlands	
34	Other: café seating area	
35	Other: community gardens	
36	Other: Zoo, golf	

denotes lighting
denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

2

☐ concrete

☒ pavers

3

☒ aggregate/stonedust

2

☐ other:

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☒ chain link

2

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting☐ pedestrian

☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route

☐ sidewalk

☐ parking

☐ trails

☐ public lot☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area

☐ monuments

☐ shade shelter

☒ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

7 benches

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☒ standard

☒ slides

☐ 2-5 age

☒ 5-12 age

Material: Metal, plastic

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
- ☒ wood fiber
- ☐ sand
- ☐ other:

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAY VALUE

- motor skills

☒ rocking

☒ swinging

☒ spinning

☒ climbing

☒ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☐ irrigation

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>3</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☒ seating

☒ team benches	☐ bleachers
☐ dugouts	☐ shade

☐ field lighting

manufacturer/condition:

ATHLETIC FIELD NOTES:

Picnic tables in poor condition

Need scooter track

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☒court surface

☒ color surfacing/lines

condition

☐ good

☐ good

☐ fair

☐ fair

☒ poor

☒ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>3</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports	<u></u>

☐ seating

☐ team benches	☐ cleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition:

☐ skate park condition

☐concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

In poor condition

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces: 19
Accessible parking spaces:
Signage Aisle 5' Curbcut Striping
Aisle 8' Min. 3', 1:12 slopes textured or painted

Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, Yes, No. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, Yes, No. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, Yes, No. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



Existing Conditions Photo M



Existing Conditions Photo N



Existing Conditions Photo O



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Greenwood Park

ADDRESS: 1-19 Forsberg Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 3 acreage: 14.08

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☐ kids/families ☐ teens ☐ adults/elderly

☐ sports leagues

☒ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	1
Park Support Bldgs.	4
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	1
Baseball	
Basketball	1
Tennis	1
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	1
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting☐ pedestrian☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route

☐ parking

☐ public lot☐ street

☐ other:

☐ sidewalk

☐ trails

SITE FURNISHINGS

☐ picnic area

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☐ benches

☐ trash

☐ bike rack

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

Planted buffer along property to east.

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☒ standard

- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: plastic

☐ Individual elements:

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:
- compliance

☐ meets requirements

☒ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☒ swinging

☒ spinning

☒ climbing

☒ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

5 benches, 2 trash

RECOMMENDED STRATEGIES AND ACTIONS:

manufacturer/condition of equipment:

NOTE: see ADA checklist for accessibility assessment

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS –LL, Softball & Baseball

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

☐ chain link _____

☐ vinyl-coated c.l. _____

☐ sports netting _____

☒ seating

☒ team benches ☒ bleachers

☐ dugouts ☐ shade

☐ field lighting

manufacturer/condition: _____

COURTS -Tennis

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☒ poor | ☒ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material condition rating
(1-2-3=good-fair-poor)

☒ chain link 2 _____

☐ vinyl-coated c.l. _____

☐ sports _____

☒ seating

☒ team benches ☒ bleachers

☐ dugouts ☐ shade

☒ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete ☐ good

☐ surface mount ☐ fair

☐ poor

ATHLETIC FIELD NOTES:

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

Lot On-Site

Total # parking spaces: _____

Accessible parking spaces: _____

Signage ☐ Aisle 5' ☐ Curbcut ☐ Striping ☐
Aisle 8' ☐ Min. 3', 1:12 slopes
textured or painted

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☒ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☒ yes	☐ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Ball fields ☐ yes ☒ no

Sparry park ☒ yes ☐ no

Tennis and Basketball ☐ yes ☒ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, etc.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

POOLS AND SPLASHPAD ASSESSMENT

POOL

☐ zero entry

☐ wading pool

X

max depth

X

max depth

☐ diving board

☒ lap lanes

☐ slide

☒ spray features

☐ shade

☐seating

☐ individual elements:

☐ pool wall

☐good

☐ fair

☐poor

☐ pool floor

☐ good

☐ fair

☐ poor

VGBA symbol on Main Drain grate

☐ yes

☐ no

If no, engineer certification documents:

SPLASHPAD

☒ overhead features

☒ ground sprays

quantity

quantity

☒ 2-5 age group

☒ 5-12 age group

☒ zero depth

☒ activators

if no max depth

☒ recirculated

☐ flow-through

☒ shade

☐ seating

☒ individual elements:

condition of splash pad:

New

SPLASH PAD SURFACING

material

condition

☒ concrete

☒ good

☐ asphalt

☐ fair

☐ PIP rubber

☐ poor

☐ other:

POOL AND SPLASH PAD NOTES

RECOMMENDED STRATEGIES AND ACTIONS

BUILDINGS AND FACILITIES

BUILDING TYPE

- ☐ concessions
- ☐ community facility
- ☐ equipment storage
- ☐ filter building
- ☐ comfort station
- ☐ restrooms
- ☐ changing/locker rooms
- ☐ other: _____

BUILDING/FACILITIES NOTES:

ROOF

- | material | condition |
|--|-------------------------------|
| ☐ asphalt shingle | ☐ good |
| ☐ metal/standing seam | ☐ fair |
| ☐ concrete | ☐ poor |
| ☐ other: _____ | |

EXTERIOR WALLS

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ CMU block | _____ |
| ☒ concrete | _____ |
| ☐ wood/vinyl/siding | _____ |
| ☐ other: | _____ |

FILTER BUILDING/AREA

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ fans | _____ |
| ☐ louvres | _____ |
| ☐ pipe conditions | _____ |
| ☐ filter system | _____ |
| ☐ other | _____ |

RECOMMENDED STRATEGIES & ACTIONS:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



Existing Conditions Photo M



Existing Conditions Photo N



Existing Conditions Photo O



Existing Conditions Photo P



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Mulcahy Field

ADDRESS: 442 Grafton Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 3 acreage: 3.42

notes: Public school next door.

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☐ kids/families ☒ teens ☐ adults/elderly

☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	2
Softball	
Baseball	
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting

 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☐ asphalt

☒ concrete

☐ pavers

☒ aggregate/ stonedust

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☒ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☒ water

☒ electric

☐ cameras for security

☒ lighting

☐ pedestrian

☒ sports

☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route

☒ parking

☒ public lot

☐ street

☐ other:

☐ sidewalk

☐ trails

SITE FURNISHINGS

☐ picnic area

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☒ benches

☒ trash

☒ bike rack

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

No ADA, site in poor condition.

SITE AMENITIES NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☒natural turf

☐ synthetic turf

condition

☐good

☒ fair

☐ poor

☒ irrigation

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>2</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☒ seating

☐ team benches	☒ bleachers
☒ dugouts	☐ shade

☐ field lighting

manufacturer/condition:

ATHLETIC FIELD NOTES:

Infield needs grading.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☒court surface

☐ color surfacing/lines

condition

☐ good

☐ fair

☒ poor

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>3</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports	<u></u>

☐ seating

☐ team benches	☐ bleachers
☐ dugouts	☐ shade

☒ court lighting

manufacturer/condition:

☐ skate park condition

☐concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure ☒ 5-12 age structure
☐ water elements ☐ seating for caregivers
☐ drinking fountain ☐ shade
☐ swings
☐ ADA ☐ infant
☐ belt ☐ standard

☒ slides☐ 2-5 age☒ 5-12 age

Material: plastic

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
☒ wood fiber
☐ sand
☐ other:

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

☐ other: _____

PLAY VALUE

motor skills

- ☐ rocking
- ☐ swinging

☒ spinning☒ climbing☒ sliding☒ balancing

cognitive skills

- ☐ manipulative
- ☐ interactive

☐ exploratory

☐ engagement with peers

- problem solving

- ☐ other unstructured play:

PLAYGROUND NOTES:

RECOMMENDED STRATEGIES AND ACTIONS:

[illegible]

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces: 9
Accessible parking spaces: 1
Signage Aisle 5' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Aisle 8'

Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, Yes, No. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, Yes, No. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, Yes, No. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Oakland Heights Playground

ADDRESS: Garnet Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☐ medium ☒ low
- ☐ other: _____

CONTEXT

- ☒ residential ☒ mixed-use ☐ commercial
- ☐ industrial district: 3 acreage: 1.47

notes: Open space – no access, undeveloped

USER GROUPS

- ☐ neighborhood ☐ city ☐ regional
- ☐ kids/families ☐ teens ☐ adults/elderly
- ☐ sports leagues
- ☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting

☐ denotes overlay



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Providence Street Playground

ADDRESS: Providence Street, next to Vernon Hill School



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed use ☐ commercial

☐ industrial district: 3 acreage: 4.59

notes: School next to fields and playground

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☐ adults/elderly

☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Park Support Bldgs.	ACTIVE USE	Footbal	Soccer	Multipurpose Field	Little League	Softball	Baseball	Basketball	Tennis	Handball	Volleyball	Roller Hockey	Playground	Ice Skating Area	Sledding	Spray Park	Pool Complex	PASSIVE USE	Water Resources	Bathing Beach	Boating	Fishing	Historic Resources	Monument/ Memorial	Gazebo/Pavilion/Picnic Shelter	Amphitheater	Interpretive Signs & Kiosk	Paths & Trails	Unprogrammed Open Lawns	Picnicking	Woodlands	Other: café seating area	Other: community gardens	Other: Zoo, golf

☐ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

- ☒ pathways material condition rating (1-2-3 = good-fair-poor)
- ☐ asphalt _____
- ☐ concrete _____
- ☐ pavers _____

☒ aggregate/ stonedust 2-3 ☐ other: _____

☐ fencing material condition rating (1-2-3 = good-fair-poor)

☒ chain link Around soccer fields

☒ vinyl coated c.l. Around playground

☐ ornamental _____

☐ wood guard rail _____

☐ grading / drainage

☒ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security _____

☒ lighting ☐ pedestrian

☐ sports ☒ other

manufacturer/ model: _____

PARK ACCESS

- ☐ public transportation
- ☐ bike route ☐ sidewalk
- ☒ parking ☐ trails
- ☐ public lot
- ☒ street

SITE FURNISHINGS

- ☐ picnic area ☒ monuments
- ☒ shade shelter ☐ benches
- ☐ interpretive signage ☒ trash
- ☐ regulatory signage ☐ bike rack
- ☐ drinking fountain

PARKING ACCESS NOTES:

No parking along Providence St. Parking at school or
at residential streets is very limited for the use of this
park

SITE INFRASTRUCTURE NOTES:

No ADA compliant connection between playground and fields

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure ☒ 5-12 age structure
- ☐ water elements ☒ seating for caregivers
- ☐ drinking fountain ☐ shade
- ☒ swings
- ☒ belt ☒ standard
- ☐ ADA ☒ infant
- ☒ slides
- ☒ 2-5 age
- play: ☒ 5-12 age
- material: metal
- ☐ Individual elements: _____
- _____

PLAY VALUE

- motor skills cognitive skills
- ☐ rocking ☐ manipulative
- ☒ swinging ☐ interactive
- ☒ spinning ☐ exploratory
- ☒ climbing ☐ engagement with peers
- ☒ sliding ☐ problem solving
- ☒ balancing ☒ other unstructured

Community built path between playground and school. Some poison ivy has been reported.

SURFACING:

material

- ☒ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other _____

compliance

- ☒ meets requirements
- ☐ does NOT meet the requirements

manufacturer/condition of equipment

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Play equipment is fairly new. PIP rubber surfacing gets warm due to the high % of color black mixed in. Also metal sides.

RECOMMENDED STRATEGIES AND ACTIONS:

Fix fence that divides 2-5 and 5-12 area

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Soccer/ Multipurpose field

- ☒ natural turf ☐ synthetic turf
- condition condition
- ☐ good ☐ good
- ☒ fair ☐ fair
- ☐ poor ☐ poor
- ☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- ☒ chain link _____
- ☐ vinyl-coated c.l. _____
- ☐ sports netting _____

☐ seating

- ☐ team benches ☐ bleachers
- ☐ dugouts ☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

Fields are overused- some bare patched of grass /
not so good shape.

RECOMMENDED STRATEGIES & ACTIONS:

Review use of field? Upgrade lawn

COURTS

- ☐ court surface ☐ color surfacing/lines
- condition condition
- ☐ good ☐ good
- ☐ fair ☐ fair
- ☐ poor ☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- ☐ chain link _____
- ☐ vinyl-coated c.l. _____
- ☐ sports netting _____

☐ seating

- ☐ team benches ☐ bleachers
- ☐ dugouts ☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- ☐ concrete ☐ good
- ☐ surface mount ☐ fair
- ☐ poor

COURT NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3'; 1:12 slopes textured or painted
		Striping ☐
Accessible parking closest to accessible entrance? ☐		
OR is there a drop off area? ☒ yes ☐ no		
Parking is by permit only? ☐ yes ☐ no		
Parking Notes:		

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☒ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☒ yes	☐ no
Meets standards?	☒ yes	☐ no
Is the same experience provided to ALL?	☒ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no
 If yes, specify facility and check for accessibility
 Soccer/ Multi-purpose fields ☐ yes ☒ no

_____ ☐ yes ☐ no

_____ ☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Needs to be improved- connection between playground and field is through the school’s driveway which is busy and not safe at all times.

PLANT MATERIAL NOTES:

Manage areas around / in between fields and playground, as it is explored by children using these facilities

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Vegetation management.

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C-E



Existing Conditions Photo F-H



Existing Conditions Photo G



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



Existing Conditions Photo M



Existing Conditions Photo N



Existing Conditions Photo O



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Vernon Hill Park

ADDRESS: 160-168 Providence Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 3 acreage: 15.15

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☐ kids/families ☐ teens ☐ adults/elderly
☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Multi-family development

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	3
ACTIVE USE	
Football	
Soccer	1
Multipurpose Field	
Little League	1
Softball	2
Baseball	1
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	1
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

 denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	1
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	1
☐ vinyl coated c.l.	
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☒ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security

☒ lighting ☐ pedestrian

☒ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

Loose equipment - playground components.

SITE AMENITIES NOTES:

PARK ACCESS

☒ public transportation

☐ bike route ☒ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☐ picnic area ☐ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☒ trash

☐ regulatory signage ☐ bike rack

☒ drinking fountain

PARKING ACCESS NOTES:

Bituminous pathway at playground, needs repair.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☒ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports netting	_____

☒ seating

☒ team benches	☒ bleachers
☒ dugouts	☐ shade

☒ field lighting

manufacturer/condition: good

ATHLETIC FIELD NOTES:

No ADA path between basketball courts and
playground/little league

COURTS

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☒ good | ☒ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☒ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports	_____

☒ seating

☐ team benches	☒ bleachers
☐ dugouts	☐ shade

☒ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

Bleachers are inadequate

RECOMMENDED STRATEGIES & ACTIONS:

BUILDINGS AND FACILITIES

BUILDING TYPE

☒ concessions

☐ comfort station

☐ community facility

☒ restrooms

☐ equipment storage

☐ changing/locker rooms

☐ filter building

☐ other: _____

ROOF

material	condition I
☒ asphalt shingle	☒ good
☐ metal/standing seam	☐ fair
☒ concrete	☐ poor
☐ other: _____	

BUILDING/FACILITIES NOTES:

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	_____
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3-=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces: 43
Accessible parking spaces: 3
Signage [x] Aisle 5' [] Aisle 8' [] Curbcut [] Min. 3', 1:12 slopes textured or painted Striping [x]

Accessible parking closest to accessible entrance? [x]
OR is there a drop off area? [] yes [] no
Parking is by permit only? [] yes [] no
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, [x] yes, [] no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, [x] yes, [] no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site? [x] yes [] no
If yes, specify facility and check for accessibility
Basketball and playground [x] yes [x] no

[] yes [] no
[] yes [] no
Are there berm cuts onto the courts? [] yes [] no
Bleachers are ADA compliant? [] yes [] no
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? [] yes [] no
If no please specify:

Picnic Facilities
Benches: Total # 4 # Accessible
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:
Picnic table 1

Table with 3 columns: Trail Amenities, [] yes, [] no. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



Existing Conditions Photo M



Existing Conditions Photo N



Existing Conditions Photo O



Existing Conditions Photo P



Existing Conditions Photo Q



Existing Conditions Photo R



Existing Conditions Photo S



Existing Conditions Photo T



Existing Conditions Photo U



Existing Conditions Photo V



Existing Conditions Photo W



Existing Conditions Photo X



Existing Conditions Photo Y



Existing Conditions Photo Z



Existing Conditions Photo AA



Existing Conditions Photo BB



Existing Conditions Photo CC



Existing Conditions Photo DD



Existing Conditions Photo EE



Existing Conditions Photo FF



Existing Conditions Photo GG



Existing Conditions Photo HH



Existing Conditions Photo II



Existing Conditions Photo JJ



Existing Conditions Photo KK



Existing Conditions Photo LL



Existing Conditions Photo MM

This page left blank intentionally

District 4

Site Assessment Forms

Cookson Field

Crompton Park

Elm Park

Harry Sherry Field (South Worcester Playground)

Oread Castle Park

University (Crystal) Park

Winslow & Pleasant (Peace) Park

This page left blank intentionally



NAME OF PARK: Cookson Park

Locus Map

USER GROUPS

☒ neighborhood ☐ city ☐ regional☒ kids/families ☒ teens ☒ adults/elderly

- sports leagues

☒ other: Holy Cross

NEIGHBORHOOD CONTEXT

(list number of existing amenities)

	denotes lighting
	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating (1-2-3 = good-fair-poor)

☐ asphalt

☐ concrete

☐ pavers

☒ aggregate/ stonedust

trail

☐ fencing material

condition rating (1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

2

☐ grading / drainage

☒ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

SITE INFRASTRUCTURE NOTES:

Poor draining in parking lot.

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route

☒ parking

☒ public lot

☐ street

☐ other:

☐ sidewalk

☐ trails

SITE FURNISHINGS

☐ picnic area

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☐ benches

☐ trash

☐ bike rack

PARKING ACCESS NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard
- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
- ☒ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☒ climbing

☐ sliding

☒ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

Play mulch needs to be flush with precast concrete edging to be in compliance with ADA guidelines for accessibility and also with playground safety surfacing depth requirements.

RECOMMENDED STRATEGIES AND ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	11	_____
# Accessible parking spaces:	2	_____
Signage ☒ Aisle 5' ☐	Curbcut ☒	Striping ☒
Aisle 8' ☒	Min. 3', 1:12 slopes textured or painted	

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☒ yes	☐ no
Meets standards?	☒ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☐ yes ☒ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, etc.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities

	☒ yes	☐ no
Is surface material accessible?	☐ yes	☒ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☒ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E-G



Existing Conditions Photo H



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Crompton Park

ADDRESS: Harding Street to Endicott Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☒ commercial
☒ industrial district: 4 acreage: 12.42

notes: Very diverse context: offices, residential,
industrial and commercial

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly
☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Community very involved with this park: youth
groups to volunteering groups, persons living in
the neighborhood for many years.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	1
Soccer	
Multipurpose Field	
Little League	
Softball	2
Baseball	1
Basketball	1
Tennis	2
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	1
Spray Park	1
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	3
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

2-3

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☒ chain link

3

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

1-2

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☒ gas

☒ water

☒ electric

☒ cameras for security

☒ lighting

☒ pedestrian

☒ sports

☐ other

manufacturer/ model:

PARK ACCESS

☒ public transportation

☒ bike route

☒ sidewalk

☒ parking

☒ trails

☒ public lot

☒ street

☐ other:

SITE FURNISHINGS

☐ picnic area

☒ monuments

☐ shade shelter

☒ benches

☒ interpretive signage

☐ trash

☒ regulatory signage

☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

☒ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☐ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☒ infant

☒ belt

☐ standard

☒ slides

☒ 2-5 age

☒ 5-12 age

Material:

☐ Individual elements:

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:

compliance

☒ meets requirements

☐ does NOT meet the requirements

PLAY VALUE

motor skills

☐ rocking

☒ swinging

☒ spinning

☒ climbing

☒ sliding

☒ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☒ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

RECOM MENDED STRATEGIES AND ACTIONS:

Phase I of the master plan has been implemented. Need for more universally engaging play components, seating for caregivers and exploratory/ interactive play through the incorporation of natural play components.

Shade required if metal slides are used and at seating areas

POOLS AND SPLASHPAD ASSESSMENT

POOL

☒ zero entry

☒ wading pool

X

max depth

X

max depth

☐ diving board

☒ lap lanes

☒ slide

☒ spray features

☒ shade

☐seating

☐ individual elements:

☒ pool wall

☒good

☐ fair

☐poor

☒ pool floor

☒ good

☐ fair

☐ poor

VGBA symbol on Main Drain grate

☒ yes

☐ no

If no, engineer certification documents:

SPLASHPAD

☐ overhead features

☐ ground sprays

quantity

quantity

☐ 2-5 age group

☐ 5-12 age group

☐ zero depth

☐ activators

X'

if no max depth

☐ recirculated

☐ flow-through

☐ shade

☐ seating

☐ individual elements:

condition of splash pad:

New

SPLASH PAD SURFACING

material	condition
☐ concrete	☐ good
☐ asphalt	☐ fair
☐ PIP rubber	☐ poor
☐ other:	

POOL AND SPLASH PAD NOTES

RECOMMENDED STRATEGIES AND ACTIONS

ATHLETIC FIELDS Softball, baseball and football overlay

Softball, baseball and football overlay

manufacturer/condition: Musco/fair conditions

Fields are heavily use. Backstops are in fair- poor conditions, Football goal posts are in fair conditions.

- ☐ skate park condition
 - ☐ concrete
 - ☐ surface mount
- ☐ good
- ☐ fair
- ☐ poor

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches

☐ dugouts

☐ bleachers

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Tennis

☒ court surface condition

☒ color surfacing/lines condition

☒ good

☐ fair

☐ poor

☒ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>3</u>
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches

☐ dugouts

☐ bleachers

☐ shade

☒ court lighting

manufacturer/condition: Condition: 2

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

BUILDINGS AND FACILITIES

BUILDING TYPE –Community Building

- ☐ concessions
- ☒ community facility
- ☐ equipment storage
- ☐ filter building
- ☐ comfort station
- ☒ restrooms
- ☐ changing/locker rooms
- ☐ other: _____

BUILDING/FACILITIES NOTES:

Building is use for community meetings. Has admin. staff member.

ROOF

- | material | condition |
|--|-------------------------------|
| ☐ asphalt shingle | ☐ good |
| ☐ metal/standing seam | ☐ fair |
| ☐ concrete | ☐ poor |
| ☐ other: _____ | |

EXTERIOR WALLS

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ CMU block | _____ |
| ☐ concrete | _____ |
| ☐ wood/vinyl/siding | _____ |
| ☐ other: | _____ |

FILTER BUILDING/AREA

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ fans | _____ |
| ☐ louvres | _____ |
| ☐ pipe conditions | _____ |
| ☐ filter system | _____ |
| ☐ other | _____ |

RECOMMENDED STRATEGIES & ACTIONS:

BUILDINGS AND FACILITIES

BUILDING TYPE

- ☐ concessions
- ☐ comfort station
- ☐ community facility
- ☒ restrooms
- ☒ equipment storage
- ☒ changing/locker rooms
- ☒ filter building
- ☐ other: _____

BUILDING/FACILITIES NOTES:

New filter building and Support building for splashpad

ROOF

- | material | condition |
|---|--|
| ☐ asphalt shingle | ☒ good |
| ☒ metal/standing seam | ☐ fair |
| ☐ concrete | ☐ poor |
| ☐ other: _____ | |

EXTERIOR WALLS

- | Material | condition rating
(1-2-3=good-fair-poor) |
|---|--|
| ☒ CMU block | <u>1</u> |
| ☐ concrete | _____ |
| ☐ wood/vinyl/siding | _____ |
| ☐ other: | _____ |

FILTER BUILDING/AREA

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ fans | _____ |
| ☐ louvres | _____ |
| ☐ pipe conditions | _____ |
| ☐ filter system | _____ |
| ☐ other | _____ |

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, yes, no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, yes, no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility
Tennis courts, basketball court

Fields
Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, yes, no. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☒ yes	☐ no
Is there an accessible path of travel from parking to pool?	☒ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☒ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☒ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☒ yes	☐ no

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☒ yes	☐ no
5' turning space measured 12" from floor?	☒ yes	☐ no
At least one accessible sink*?	☒ yes	☐ no
At least one accessible stall*?	☒ yes	☐ no
Accessible dispensers & mirrors*?	☒ yes	☐ no

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Implement other mater plan phasing efforts.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C-E



Existing Conditions Photo F-H



Existing Conditions Photo I-K





CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Elm Park

ADDRESS: Highland Street to Park Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒high

☒medium

☐low

☐other: _____

CONTEXT

☒residential

☒ mixed-use

☒commercial

☐ industrial

district: 4-5

acreage: 58.38

notes: Low Density, School, Institution, Multi-family

USER GROUPS

☒ neighborhood

☒ city

☐ regional

☒ kids/families

☒ teens

☒adults/elderly

☐ sports leagues

☒ other:

NEIGHBORHOOD CONTEXT

Greek Orthodox Community

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	2
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	4
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	3
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	1
Monument/Memorial	3
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	1
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

- ☐ pathways material condition rating (1-2-3 = good-fair-poor)
- ☒ asphalt Sidewalks-2
- ☒ concrete _____
- ☐ pavers _____
- ☐ aggregate/ stonedust 2-3

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

- ☐ chain link _____
- ☐ vinyl coated c.l. _____
- ☐ ornamental _____
- ☐ wood guard rail _____

☐ grading / drainage

☒ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security _____

☒ lighting ☒ pedestrian

☒ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

Period pedestrian lights need repair. Wiring Exposed at Base

Paths are mostly accessible, erosion and settling evident

SITE AMENITIES NOTES:

Pathways need definition and are not ADA compliant

Benches need replacement,

Trash in poor-fair condition

Some benches are not accessible

PARK ACCESS

☒ public transportation: Bus Stop Highland Ave.

☒ bike route

☐ sidewalk

☒ parking

☐ trails

☐ public lot

☒ street*

☐ other: _____

SITE FURNISHINGS

☐ picnic area

☒ monuments

☐ shade shelter

☒ benches

☐ interpretive signage

☒ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

*Russell Street only

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☐ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA ☐ infant
- ☐ belt ☐ standard
- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements: _____

SURFACING:

material

- ☐ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☐ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

manufacturer/condition of equipment: _____

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

UNDER CONSTRUCTION

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---------------------------------------|---|
| ☐ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
----------	--

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS (4)Tennis Courts

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☒ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
----------	--

- | | |
|--|--------------------------|
| ☒ chain link | <u>Black painted 1-2</u> |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☒ court lighting

manufacturer/condition: 1-2

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

COURT NOTES:

*Near bus stop

Net poles rusted

Surfacing needs color sealant

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports netting

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Basketball

☐ court surface condition

☒ good

☒ fair

☐ poor

☐ color surfacing/lines condition

☐ good

☒ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☒ vinyl-coated c.l.

Needs Ties

☐ sports

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐

☐ poor

COURT NOTES:

Needs paint and Sealant

BUILDINGS AND FACILITIES

BUILDING TYPE

☐ concessions condition

☐ comfort station

☐ community facility

☐ restrooms

☐ equipment storage

☐ changing/locker rooms

☐ filter building

☐ other: _____

BUILDING/FACILITIES NOTES:

Under construction- fenced (in fenced-off area)

ROOF

material

☒ asphalt shingle

☒ good

☐ metal/standing seam

☐ fair

☐ concrete

☐ poor

☐ other: _____

EXTERIOR WALLS

Material

condition rating
(1-2-3=good-fair-poor)

☒ CMU block

1

☐ concrete

☐ wood/vinyl/siding

☐ other:

FILTER BUILDING/AREA

Material

condition rating
(1-2-3=good-fair-poor)

☐ fans

☐ louvres

☐ pipe conditions

☐ filter system

☐ other

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, Yes, No. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, Yes, No. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, Yes, No. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

Paths not ADA compliant and in need of refurbishment

PLANT MATERIAL NOTES:

Needs management. Tree roots exposed

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Bridges inaccessible

State of long wear/decay across the park

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Pond Edges littered with debris/trash

Trees need to be pruned, vegetation managed

RECOMMENDED STRATEGIES & ACTIONS:

Take out old/broken benches

Repair Tennis and Basketball courts (high demand)

Prune trees and manage vegetation

Restore paths to ADA compliance



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Harry Sherry Field

ADDRESS: Cambridge Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☒ medium ☐ low
☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial
☐ industrial district: 4 acreage: 4.89

notes: Close to Holy Cross.

USER GROUPS

☒ neighborhood ☒ city ☐ regional
☒ kids/families ☒ teens ☐ adults/elderly
☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Adjacent from railroad.
Mixed-use: adjacent to St. John cemetery.
Across from college hill.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	
Baseball	1
Basketball	1
Tennis	
Handball	1
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>1</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____

☒ fencing material

	condition rating (1-2-3 = good-fair-poor)
☒ chain link	_____
☒ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security _____

☐ lighting

☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☐ picnic area ☐ monuments

☐ shade shelter ☐ benches

☐ interpretive signage ☒ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

2 lots—15 spaces (2 handicapped)

5 spaces (1 handicapped)

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☒ infant
- ☒ belt
- ☐ standard
- ☒ slides
- ☒ 2-5 age
- ☒ 5-12 age
- Material: plastic
- ☐ Individual elements:
-
-

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other:
- compliance

☐ meets requirements

☒ does NOT meet the requirements
- manufacturer/condition of equipment:

LSI poor to fair

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

1 broken infant swing, 4 swings with belts

Swings are overused/need replacement/repair

Surfacing needs replacement—gravel base footings exposed

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

Baseball and Little League

☒ natural turf

☐ synthetic turf

condition

condition

☐ good

☐ good

☒ fair

☐ fair

☐ poor

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☒ chain link

3

☒ vinyl-coated c.l.

1/2

☐ sports netting

☒ seating

☒ team benches

☒ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

-Infield MH at baseball

-Stone dust at Little League

-pitcher's mound

-Need mallet

ATHLETIC FIELD NOTES:

Irrigation only at Little League. No shade at benches
Baseball back stop, benches, and bleachers need to
be replaced. Bleachers at little league need to be
repaired.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

Basketball and Handball

☒ court surface

☒ color surfacing/lines

condition

condition

☒ good

☐ good

☒ fair

☒ fair

☐ poor

☒ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☒ chain link

3

☒ vinyl-coated c.l.

3

☐ sports

☒ seating

☒ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

-Handball walls in fair/good shape
-Need color resurfacing at both courts
-Basketball goals are fair (have nets)
-No accessible route to handball. Benches at handball.

BUILDINGS AND FACILITIES

BUILDING TYPE

☒ concessions

☐ comfort station

☒ community facility

☐ restrooms

☐ equipment storage

☐ changing/locker rooms

☐ filter building

☐ other: _____

ROOF

material	condition
☒ asphalt shingle	☒ good
☐ metal/standing seam	☐ fair
☐ concrete	☐ poor
☒ other: <u>Flat roof-conc. – poor</u>	

BUILDING/FACILITIES NOTES:

-concessions look unused.

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	<u>1-Comm. Center, 3-conc.</u>
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	<u>15/16</u>	<u>31</u>
# Accessible parking spaces:	<u>2/1</u>	<u>3</u>
Signage ☒	Aisle 5' ☐	Curbscut ☒ Min. 3', 1:12 slopes textured or painted
	Aisle 8' ☒	Striping ☒

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

Not conc.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☒ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Ball fields ☐ yes ☐ no

Handball and basketball court ☐ yes ☒ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☒ no

Bleachers are ADA compliant? ☐ yes ☒ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Oread Castle Park

ADDRESS: Castle Street to Alden Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☒ low

☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☐ commercial

☐ industrial district: 4 acreage: 3.24

notes: Residential, hospital

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☐ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Difficult to access

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	1
Handball	2
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	2
☐ concrete	
☐ pavers	
☒ aggregate/ stonedust	2

☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☒ chain link	Perimeter is 3
☐ vinyl coated c.l.	
☐ ornamental	
☒ wood guard rail	

☐ grading / drainage	☐ low/wet areas	☐ blocked structures
	☐ ADA compliant grates	
☒ utilities	☐ gas	☐ water
	☒ electric	
	☐ cameras for security	
☒ lighting	☒ pedestrian	
	☒ sports	☐ other
	manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

Pedestrian lights probably don't work.

SITE AMENITIES NOTES:

-Benches are poor/fair.

-Trash needs replacement.

-Picnic

PARK ACCESS

☒ public transportation	
☐ bike route	☐ sidewalk
☐ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☒ picnic area	☐ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

No access!

No parking.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☐ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☒ infant
- ☒ belt
- ☐ standard

- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☒ Individual elements:
climber _____

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other: _____
- compliance

☐ meets requirements

☒ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

manufacturer/condition of equipment:
LSI fair

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

2 infant swings, 4 swings with belts.

Fiber needs maintenance.

Belts, chains, and hooks need replacement.

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---------------------------------------|---|
| ☐ natural turf | ☐ synthetic turf |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

☐ chain link _____

☐ vinyl-coated c.l. _____

☐ sports netting _____

☐ seating

☐ team benches ☐ bleachers

☐ dugouts ☐ shade

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|---|---|
| ☒ court surface | ☒ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☒ fair | ☒ fair |
| ☒ poor | ☒ poor |

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material condition rating
(1-2-3=good-fair-poor)

☒ chain link _____

☒ vinyl-coated c.l. _____

☐ sports _____

☒ seating

☒ team benches ☐ bleachers

☐ dugouts ☐ shade

☒ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete ☐ good

☐ surface mount ☐ fair

☐ poor

ATHLETIC FIELD NOTES:

COURT NOTES:

Basketball—Has benches. Court lighting at doesn't work. Needs paving and nets.

Tennis court now soccer—paving/fencing need replacement.

Handball court—paving is fair, wall is fair (cracking at the back), fencing is fair.

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	<u>0</u>	<u> </u>
# Accessible parking spaces:	<u>0</u>	<u> </u>
Signage ☐	Aisle 5' ☐	Curbcut ☐
	Aisle 8' ☐	Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☒ yes ☐ no

Parking Notes:

No public parking close to park.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☒ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☐ yes	☒ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☒ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☒ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☒ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Handball, baseball ☐ yes ☒ no

Football painted ☐ yes ☒ no

court ☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	<u> </u>	<u> </u>
Drinking Fountains:	<u> </u>	<u> </u>
Tables:	<u> </u>	<u> </u>
5% of tables must be accessible		
Grill:	<u> </u>	<u> </u>
Note the height of cooking surface	<u> </u>	<u> </u>
Picnic Shelters:	<u> </u>	<u> </u>

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☒ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☒ no
Is there a handrail?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

Needs park edge management. Community is involved in community gardens close to park and may be willing to participate in keeping up with park vegetation.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Good views of the city.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Beautiful rock OVTC ROPS and surrounding tree vegetation.

RECOMMENDED STRATEGIES & ACTIONS:

Improve ADA accessibility.

Redesign Playground to safety standards.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: University Park (Crystal Park)

ADDRESS: Main Street to Gates Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☒ commercial

☐ industrial district: 4 acreage: 14.27

notes: Universities, churches.

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	2
Tennis	1
Handball	
Volleyball	1
Roller Hockey	
Playground	1
Ice Skating Area	1
Sledding	1
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1	denotes lighting
1	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>2</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____

☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	<u>1</u>
☐ ornamental	_____
☐ wood guard rail	_____

☒ grading / drainage	☐ low/wet areas	☐ blocked structures
	☐ ADA compliant grates	☒ erosion

☒ utilities	☐ gas	☐ water	☒ electric
	☐ cameras for security	_____	

☒ lighting	☒ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

-Fencing at play area

-Pond undergoing construction/new wall

-Wood benches need replacement

-Pathway improvements underway. Some paths need replacement.

SITE AMENITIES NOTES:

-Tables in poor shape.

-Lawn in fair-good condition.

PARK ACCESS

☒ public transportation	
☐ bike route	☒ sidewalk
☒ parking	☐ trails
☒ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☒ picnic area	☒ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Diagonal parking at Illinois Street.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure ☒ 5-12 age structure
☐ water elements ☒ seating for caregivers
☐ drinking fountain ☒ shade
☒ swings
☐ ADA ☐ infant
☒ belt ☐ standard
☒ slides
☐ 2-5 age
☒ 5-12 age

Material: metal

- ☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
☒ wood fiber
☐ sand
☐ other:

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

☐ other: _____

PLAY VALUE

motor skills

☐ rocking☐ swinging

☐ spinning

☐ climbing☐ sliding

- ☐ balancing

cognitive skills

☐ manipulative

☐ interactive☐ exploratory

- ☐ engagement with peers

- problem solving

- ☐ other unstructured play:

PLAYGROUND NOTES:

Shade provided by trees.

3 swings with belts.

RECOMMENDED STRATEGIES AND ACTIONS:

[illegible]

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☐ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

☐ chain link _____

☐ vinyl-coated c.l. _____

☐ sports netting _____

☐ seating

☐ team benches ☐ bleachers

☐ dugouts ☐ shade

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

☐ chain link _____

☐ vinyl-coated c.l. _____

☐ sports _____

☐ seating

☐ team benches ☐ bleachers

☐ dugouts ☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete ☐ good

☐ surface mount ☐ fair

☐ poor

ATHLETIC FIELD NOTES:

COURT NOTES:

Under construction

Tennis and Basketball.

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: _____

PARKING

Lot

On-Site

Total # parking spaces: _____

Accessible parking spaces: _____

Signage ☐ Aisle 5' ☐ Curbcut ☐ Striping ☐

Aisle 8' ☐

Min. 3'; 1:12 slopes
textured or painted

Accessible parking closest to accessible entrance? ☐OR is there a drop off area? ☐ yes ☐ noParking is by permit only? ☐ yes ☐ noParking Notes:
N/A

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☒ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility
Courts under construction ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☒ no
fishing piers, ect.) and equipment (i.e.
Benches, pools, shade shelters)
located adjacent to accessible paths?

If no please specify:
Some are, areas under construction.

Picnic Facilities

Total # # Accessible

Benches: _____ 3

Drinking Fountains: _____

Tables: _____ 0

5% of tables must be accessible

Grill: _____

Note the height of cooking surface

Picnic Shelters: _____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities: _____

CIRCULATION & CONNECTIVITY NOTES:

Paths vary in completion.

Corades exceed S/ in some areas.

PLANT MATERIAL NOTES:

Large, mature beautiful trees.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Panoramic view from Knoll-Clark University, neighborhood, and rare parts of the city.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Water fowl at pond.

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Winslow Park (Peace Park)

ADDRESS: Winslow Street and Pleasant Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☐ commercial
☐ industrial district: 4 acreage: 0.55

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly
☐ sports leagues
☐ other: _____

NEIGHBORHOOD CONTEXT

Commercial nearby, housing is residential.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	1

1 denotes lighting
1 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☒ concrete	<u>1 - Exposed aggregate</u>
☐ pavers	_____
☐ aggregate/ stonedust	<u>3</u>

☒ fencing material

	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	<u>3</u>
☒ ornamental	<u>2</u>
☐ wood guard rail	_____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☒ utilities

☐ gas ☐ water ☒ electric

☐ cameras for security _____

☒ lighting ☒ pedestrian

☐ sports ☐ other

manufacturer/ model: good condition

SITE INFRASTRUCTURE NOTES:

-Paths in good condition and look accessible.

-Community gardens—used but unsightly.

-Desire for swings.

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation

☐ bike route ☒ sidewalk

☒ parking ☐ trails

☐ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☒ benches

☒ interpretive signage ☐ trash

☒ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Parking on Winslow- very limited.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	<u>0</u>	<u> </u>
# Accessible parking spaces:	<u>0</u>	<u> </u>
Signage ☐	Aisle 5' ☐	Curbside ☐
	Aisle 8' ☐	Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☒ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, etc.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	<u> </u>	<u>All</u>
Drinking Fountains:	<u> </u>	<u> </u>
Tables:	<u>5</u>	<u>1</u>
5% of tables must be accessible	<u> </u>	<u> </u>
Grill:	<u> </u>	<u> </u>
Note the height of cooking surface	<u> </u>	<u> </u>
Picnic Shelters:	<u> </u>	<u> </u>

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

Nice trees and planting.

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Feedback from current park users: a small play structure—swings?



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L

This page left blank intentionally

District 5

Site Assessment Forms

Apricot Street Playground

Bailey-Prouty Playground

Beaver Brook Park

Bennett Field

Boynton Park

Cascades Park

Coes Knife Parks- Coes Knife

Coes Knife Parks- Coes Pond Beach

Coes Knife Parks- Columbus Park

Coes Knife Parks-Knight of Columbus

Farber Field

Hadwen Park

Logan Field

Rockwood Field

Ty Cobb Park

This page left blank intentionally



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Apricot Street Playground

ADDRESS: 11 Armandale Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 5 acreage: 2.32

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly
☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1 denotes lighting
1 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

condition rating
(1-2-3 = good-fair-poor)

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

PARK ACCESS

☒ public transportation

☐ bike route

☐ parking

☐ public lot

☐ street

☐ other:

☐ sidewalk

☐ trails

SITE FURNISHINGS

☒ picnic area

☐ shade shelter

☐ interpretive signage

☐ regulatory signage

☐ drinking fountain

☐ monuments

☐ benches

☐ trash

☒ bike rack

PARKING ACCESS NOTES:

19-23

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☒ belt
- ☐ standard

☒slides

☐2-5 age

☒5-12 age

Material: plastic

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
- ☒ wood fiber
- ☐ sand
- ☐ other:

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAY VALUE

motor skills

- ☐ rocking
- ☐ swinging
- ☐ spinning
- ☐ climbing
- ☐ sliding
- ☐ balancing

cognitive skills

- ☐ manipulative
- ☐ interactive
- ☐ exploratory
- ☐ engagement with peers
- ☐ problem solving
- ☐ other unstructured play:

PLAYGROUND NOTES:

2 belts

RECOMMENDED STRATEGIES AND ACTIONS:

Close off openings. Repair damaged components and invest on new playground?

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, yes, no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, yes, no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, yes, no. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Bailey-Prouty Playground

ADDRESS: Prouty Lane



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☒ low
☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial
☐ industrial district: 5 acreage: 3.74

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1 denotes lighting
1 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	1
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☐ vinyl coated c.l.	
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

2 benches at playground

SITE AMENITIES NOTES:

PARK ACCESS

☒ public transportation

☐ bike route ☐ sidewalk

☐ parking ☐ trails

☐ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☐ picnic area ☐ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☐ trash

☐ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

2 HC stalls with sign and 8' wide aisle.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure ☒ 5-12 age structure
☐ water elements ☒ seating for caregivers
☐ drinking fountain ☐ shade
☐ swings
☐ ADA ☒ infant
☒ belt ☐ standard
☒ slides
☒ 2-5 age
☒ 5-12 age

Material: metal

- ☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
☒ wood fiber
☐ sand
☐ other:

compliance

- ☒ meets requirements
- ☐ does NOT meet the requirements

PLAY VALUE

motor skills

- ☐ rocking
- ☐ swinging
- ☐ spinning
- ☐ climbing
- ☐ sliding
- ☐ balancing

cognitive skills

- ☐ manipulative
- ☐ interactive
- ☐ exploratory
- ☐ engagement with peers
- ☐ problem solving
- ☐ other unstructured play:

PLAYGROUND NOTES:

Bailey-Prouth Playground- "John W. Stillance Memorial Field"

2 infant swings with belts.

Has a curb cut.

manufacturer/condition of equipment:

NOTE: see ADA checklist for accessibility assessment

RECOMMENDED STRATEGIES AND ACTIONS:

[illegible]

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Little League

☒natural turf condition

☐synthetic turf condition

☒good

☐good

☐fair

☐fair

☐poor

☐poor

☐irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☒ sports netting	<u>1</u>

☐ seating

☒ team benches	☒ bleachers
☐ dugouts	☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

"Spillane Field"

Jesse Burkett is in new condition.

Scoreboard, ADA compliant building.

RECOMMENDED STRATEGIES & ACTIONS:

Buildings will have concrete apron.

COURTS

☐court surface condition

☐color surfacing/lines condition

☐good

☐good

☐fair

☐fair

☐poor

☐poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches	☐ bleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

ACCESSIBILITY FOR: _____

PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	<u>2</u>	_____
Signage ☒	Aisle 5' ☐	Curbcut ☒ Min. 3', 1:12 slopes textured or painted
	Aisle 8' ☒	Striping ☒

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☒ yes	☐ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface		
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

 This is a new field and playground.

 Construction is 98% complete so that building will be ADA accessible.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Bennett Field

ADDRESS: 1264 Main Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☒ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☐ commercial
☐ industrial district: 5 acreage: 5.17

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Residential at the back and community at the front.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	1
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1 denotes lighting
1 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

condition rating
(1-2-3 = good-fair-poor)

☐ fencing material

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

condition rating
(1-2-3 = good-fair-poor)

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route

☒ sidewalk

☒ parking

☐ trails

☒ public lot

☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☒ trash

☒ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

School parking lot. Pavement needs repair at entrance.

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

- | | |
|---|---|
| ☐ natural turf condition | ☐ synthetic turf condition |
| ☐ good | ☐ good |
| ☒ fair | ☐ fair |
| ☒ poor | ☐ poor |
| ☒ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
----------	--

☒ chain link	<u>2-3</u>
--	------------

☐ vinyl-coated c.l.	_____
--	-------

☐ sports netting	_____
---	-------

☒ seating

☒ team benches	☒ bleachers
--	---

☐ dugouts	☒ shade
----------------------------------	---

☐ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface condition | ☐ color surfacing/lines condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
----------	--

☐ chain link	_____
-------------------------------------	-------

☐ vinyl-coated c.l.	_____
--	-------

☐ sports	_____
---------------------------------	-------

☐ seating

☐ team benches	☐ bleachers
---------------------------------------	------------------------------------

☐ dugouts	☐ shade
----------------------------------	--------------------------------

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete	☐ good
-----------------------------------	-------------------------------

☐ surface mount	☐ fair
--	-------------------------------

☐ poor

ATHLETIC FIELD NOTES:

Irrigation is Toro 2001. Fence is broken and rusted.

Seating is in poor condition. There are 2 benches

and 1 bleacher. Lighting's security is in poor

condition. Needs fine grading from overuse? Good

access but not to bleachers.

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Repair and replace elements and field.

ACCESSIBILITY FOR:

PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	1
Signage ☒	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3'; 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☒

OR is there a drop off area? ☒ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☒ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☒ yes	☐ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

To field not bleachers ☒ yes ☒ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☒ no

If no please specify:

No benches of amenities.

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface		
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:


PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Implement master plan.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Beaver Brook Park

ADDRESS: Mayfield Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☐ mixed-use ☒ commercial

☐ industrial district: 5 acreage: 18.08

notes: _____

USER GROUPS

☐ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

Commerce bank field at Folem Stadium.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	2
Park Support Bldgs.	3
ACTIVE USE	
Football	1
Soccer	
Multipurpose Field	
Little League	2
Softball	1
Baseball	
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	1
Playground	2
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	1
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☒ denotes lighting
☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	1
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	

☒ fencing material

	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☐ vinyl coated c.l.	
☐ ornamental	
☒ wood guard rail	3

☐ grading / drainage

☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates

☐ utilities

☐ gas ☐ water ☐ electric
☐ cameras for security

☒ lighting ☒ pedestrian

☒ sports ☐ other

manufacturer/ model: Lumec (pedestrian)

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Needs more benches near shade trees and more trash receptacles.

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☒ public lot
☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☒ benches

☐ interpretive signage ☒ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Parking lot is bumpy. No accessible walk/clear
entrance from it (see desire lines).

No ADA assigner stalls or if they do (Near Hockey) it
has no sign.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard

☒ slides

☐ 2-5 age

☐ 5-12 age

Material: _____

☐ Individual elements: _____

SURFACING:

material

- ☐ PIP rubber
- ☒ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAYGROUND NOTES:

Surfacing is below roof level.

Some rusting of platforms and paint chipping.

*Who _____

RECOMMENDED STRATEGIES AND ACTIONS:

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure
- ☐ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☒ infant
- ☐ belt
- ☒ standard
- ☒ slides
- ☒ 2-5 age
- ☒ 5-12 age
- Material: plastic

☐ Individual elements:

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

SURFACING:

- material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other
- compliance

☒ meets requirements

☐ does NOT meet the requirements
- manufacturer/condition of equipment

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

Surfacing does not meet ADA requirements but meets ACC.

There are two infant swings and 4 broken swings.

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Ted William

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☒ fair

☐ fair

☐ poor

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>2</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports netting	<u></u>

☒ seating

☒ team benches

☒ bleachers

☒ dugouts

☐ shade

☒ field lighting

manufacturer/condition: Good. Musco.

(light structure 2)

ATHLETIC FIELD NOTES:

No path to seating. Seating has no ADA space.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Basket Ball

☒court surface

☒ color surfacing/lines

condition

☒ good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>1</u>
☐ vinyl-coated c.l.	<u></u>
☐ sports	<u></u>

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition:

☐ skate park condition

☐concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

No seating.

Poor location at parking lot,.

Had to be double fenced.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS 2 Little League

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports netting	_____

☒ seating

☒ team benches	☐ bleachers
☐ dugouts	☐ shade

☒ field lighting

manufacturer/condition: Good. Musco.

ATHLETIC FIELD NOTES:

No shade for seating.

Bleachers are with ADA

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐court surface

☐ color surfacing/lines

condition

☐ good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches	☐ bleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Softball

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☒ irrigation | |

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports netting | _____ |

☒ seating

- | | |
|--|---|
| ☒ team benches | ☒ bleachers |
| ☐ dugouts | ☐ shade |

☒ field lighting

manufacturer/condition: _____

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material condition rating
(1-2-3=good-fair-poor)

- | | |
|--|-------|
| ☐ chain link | _____ |
| ☐ vinyl-coated c.l. | _____ |
| ☐ sports | _____ |

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

ATHLETIC FIELD NOTES:

Bleachers are with ADA.
Has trash next to bleachers.
No shade for seating.

COURT NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

Fix backstop fabric.

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Football

☒natural turf condition

☐synthetic turf condition

☒good

☐good

☐fair

☐fair

☐poor

☐poor

☐irrigation

☒ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☐ sports netting	_____

☒ seating

☐ team benches	☒ bleachers
☐ dugouts	☐ shade

☒ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

Bleachers are new but there is no shade.

Field lighting has a Vikings scoreboard.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Roller Hockey

☒court surface condition

☒color surfacing/lines condition

☒good

☒good

☐fair

☐fair

☐poor

☐poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches	☒ bleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition: Museo. Good.

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

Fencing is board fencing in good condition.

Bleachers have HC space but no shade.

BUILDINGS AND FACILITIES

BUILDING TYPE Near Hockey Rink

- ☐ concessions
- ☒ community facility
- ☒ equipment storage
- ☐ filter building
- ☐ comfort station
- ☒ restrooms
- ☐ changing/locker rooms
- ☒ other: facilities

BUILDING/FACILITIES NOTES:

Good Shape

ROOF

- | material | condition I |
|---|-------------------------------|
| ☒ asphalt shingle | ☐ good |
| ☐ metal/standing seam | ☐ fair |
| ☐ concrete | ☐ poor |
| ☐ other: _____ | |

EXTERIOR WALLS

- | Material | condition rating
(1-2-3=good-fair-poor) |
|---|--|
| ☒ CMU block | _____ |
| ☐ concrete | _____ |
| ☐ wood/vinyl/siding | _____ |
| ☐ other: | _____ |

FILTER BUILDING/AREA

- | Material | condition rating
(1-2-3-=good-fair-poor) |
|--|---|
| ☐ fans | _____ |
| ☐ louvres | _____ |
| ☐ pipe conditions | _____ |
| ☐ filter system | _____ |
| ☐ other | _____ |

RECOMMENDED STRATEGIES & ACTIONS:

ADA compliant

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

No handicapped stalls on parking in front of stadium.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☒ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☒ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☒ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☒ yes	☐ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☒ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☒ no
Is the same experience provided to ALL?	☐ yes	☒ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

fields ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total # # Accessible

Benches:

Drinking Fountains:

Tables:

5% of tables must be accessible

Grill:

Note the height of cooking surface

Picnic Shelters:

Trail Amenities

☐ yes ☐ no

Is surface material accessible? ☐ yes ☐ no

Trail dimensions and slope gradients meet all ADA requirements? ☐ yes ☐ no

Is there a handrail? ☐ yes ☐ no

Is there signage for visually impaired? ☐ yes ☐ no

Boat Docks & Fishing Facilities ☐ yes ☐ no

Is there a handrail? ☐ yes ☐ no

Are there arm rests, bait shelves, and fish cleaning tables? ☐ yes ☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

Need access from parking lot at Chandler Street.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Trees in good condition and a lot of new planting except for weed whacking damage on the base of tree trunks.

There are ducks at Porook. No direct PLC access.

RECOMMENDED STRATEGIES & ACTIONS:

Accessibility to shade at players benches and bleacher areas.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H




Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K




Existing Conditions Photo L



NAME OF PARK: Boynton Park

ADDRESS: 2 Mower Street



Locus Map

USER GROUPS

☒ neighborhood ☐ city ☒ regional☐ kids/families ☐ teens ☐ adults/elderly

- sports leagues

☐ other: ?

NEIGHBORHOOD CONTEXT

Low density residential.

(list number of existing amenities)

	denotes lighting
	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	_____
☒ grading / drainage	
☒ low/wet areas	☒ blocked structures
☐ ADA compliant grates	
☐ utilities	
☐ gas	☐ water
☐ cameras for security	☐ electric
☐ lighting	☐ pedestrian
☐ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

There are 4 picnic areas and 2 bike racks.

Meadow Ridge Trail at Boynton Parkway/River Trail at Camp Street

Silver Spring Trails to Cascades Park

SITE AMENITIES NOTES:

Benches and picnic tables on/around field

Picnic area is in poor condition (broken tables and piles of stones).

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☒ parking	☒ trails
☐ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☒ picnic area	☐ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☒ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Parking is not painted.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☒ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard

- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements:

SURFACING:

material

- ☐ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAYGROUND NOTES:

Broken swing only.

RECOMMENDED STRATEGIES AND ACTIONS:

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

ATHLETIC FIELDS

ACCESSIBILITY FOR:

PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3'; 1:12 slopes textured or painted
		Striping ☐
Accessible parking closest to accessible entrance? ☐		
OR is there a drop off area? ☐ yes ☐ no		
Parking is by permit only? ☐ yes ☐ no		
Parking Notes:		

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no
If yes, specify facility and check for accessibility
_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no
fishing piers, ect.) and equipment (i.e.
Benches, pools, shade shelters)
located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Access from camp to Boynton Parkway needs improvements. (Road is unpaved at the beginning.)

Only for able bodies—woodland trails.

PLANT MATERIAL NOTES:

Trees need MGT: Some fallen/a lot of trees cleared (ALH beetle).

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Old stone wall.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Storm water management.

blocked drainage culverts creating undesired wetlands.

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B




CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Cascades Park

ADDRESS: Cataract Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☐ medium ☒ low
- ☐ other: _____

CONTEXT

- ☒ residential ☐ mixed-use ☐ commercial
- ☐ industrial district: 5 acreage: 69.07

notes: Just trails but not parking access close to trailhead.

USER GROUPS

- ☒ neighborhood ☐ city ☒ regional
- ☒ kids/families ☒ teens ☒ adults/elderly
- ☐ sports leagues
- ☐ other: _____

NEIGHBORHOOD CONTEXT

Low density residential.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

☐ denotes lighting

☐ denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	☐ low/wet areas ☐ blocked structures ☐ ADA compliant grates
☐ utilities	☐ gas ☐ water ☐ electric ☐ cameras for security _____
☐ lighting	☐ pedestrian ☐ sports ☐ other manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

No parking access for able bodies, only trails=dirt.

SITE AMENITIES NOTES:

PARK ACCESS

☒ public transportation	
☐ bike route	☐ sidewalk
☐ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☒ benches
☒ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

Public Transportation # 6 _____

ACCESSIBILITY FOR: PARKING

	Lot	On-Site	
Total # parking spaces:	_____	_____	
# Accessible parking spaces:	_____	_____	
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted	Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

Cascade trails for able bodies. Some trails have been closed because of erosion.

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Of cascades—wall.

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

*Vegetation management to avoid erosion.

Springs.

RECOMMENDED STRATEGIES & ACTIONS:

Stone wall may need repair.

Vegetation management to avoid erosion.



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



NAME OF PARK: Coes Knife Parks: Coes Knife

ADDRESS: _____ Coes Street and Mill Street



Locus Map

USER GROUPS

☒ neighborhood ☐ city ☐ regional☒ kids/families ☒ teens ☒ adults/elderly

- sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

Mill Street is busy. No parking road.

(list number of existing amenities)

	denotes lighting
	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material

condition rating
(1-2-3 = good-fair-poor)

☒ asphalt

1

☐ concrete

☐ pavers

☒ aggregate/ stonedust

1

☒ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☒ wood guard rail

1

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☒ public transportation

☒ bike route☐ sidewalk

☒ parking

☐ public lot☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area☐ monuments

☐ shade shelter☐ benches

☐ interpretive signage☐ trash

☐ regulatory signage☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Parking under construction.

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Coes Knife Parks: Coes Pond Beach

ADDRESS: 200 Mill Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☐ low

☐ other: _____

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 5 acreage: 1.67

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	☐ low/wet areas ☐ blocked structures ☐ ADA compliant grates
☐ utilities	☐ gas ☐ water ☐ electric ☐ cameras for security _____
☐ lighting	☐ pedestrian ☐ sports ☐ other manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation	
☐ bike route	☐ sidewalk
☐ parking	☐ trails
☐ public lot	
☐ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, yes, no. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, yes, no. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, yes, no. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Columbus Park

ADDRESS: Circuit Avenue North



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☐ medium ☐ low
- ☐ other: _____

CONTEXT

- ☐ residential ☐ mixed-use ☐ commercial
- ☐ industrial district: 5 acreage: 8.81

notes: _____

USER GROUPS

- ☐ neighborhood ☐ city ☐ regional
- ☐ kids/families ☐ teens ☐ adults/elderly
- ☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

condition rating
(1-2-3 = good-fair-poor)

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route☐ sidewalk

☐ parking

☐ public lot☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Elm Park

ADDRESS: Highland Street to Park Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☒ medium ☐ low
☐ other: _____

CONTEXT

☒ residential ☒ mixed-use ☒ commercial
☐ industrial district: 4-5 acreage: 58.38

notes: Low Density, School, Institution, Multi Family

USER GROUPS

☒ neighborhood ☒ city ☐ regional
☒ kids/families ☒ teens ☒ adults/elderly
☐ sports leagues
☐ other: _____

NEIGHBORHOOD CONTEXT

Greek Orthodox Community

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	2
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	1
Tennis	4
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	3
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	1
Monument/ Memorial	3
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	1
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	1
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting
 denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>Sidewalks-fair</u>
☐ concrete	_____
☐ pavers	_____
☒ aggregate/ stonedust	<u>Poor-fair</u>

☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage	☒ low/wet areas	☐ blocked structures
☐ utilities	☐ cameras for security	_____
☒ lighting	☒ water	☒ electric
	☒ pedestrian	
	☒ sports	☐ other
	manufacturer/ model: _____	

PARK ACCESS

☒ public transportation: Bus Stop Highland Ave.	
☒ bike route	☐ sidewalk
☒ parking	☐ trails
☐ public lot	
☒ street*	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☒ monuments
☐ shade shelter	☒ benches
☐ interpretive signage	☒ trash
☐ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

*Russel Street only

SITE INFRASTRUCTURE NOTES:

Period Pedestrian Lights need Repair. Wiring Exposed at Base

Paths are mostly accessible, Erosion and Settling Evident

SITE AMENITIES NOTES:

Pathways need definition and are not ADA compliant

Benches need replacement,

Trash in poor-fair condition

Some benches are not accessible

PLAYGROUND ASSESSMENT

COMPONENTS

- ☐ 2-5 age structure
- ☐ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☐ swings
- ☐ ADA
- ☐ infant
- ☐ belt
- ☐ standard

- ☐ slides
- ☐ 2-5 age
- ☐ 5-12 age

Material: _____

☐ Individual elements: _____

SURFACING:

material

- ☐ PIP rubber
- ☐ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☐ does NOT meet the requirements

PLAYGROUND NOTES:

UNDER CONSTRUCTION

RECOMMENDED STRATEGIES AND ACTIONS:

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play: _____

manufacturer/condition of equipment: _____

NOTE: see ADA checklist for accessibility assessment

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches

☐ dugouts

☐ bleachers

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS (4)Tennis Courts

☒ court surface condition

☐ color surfacing/lines condition

☐ good

☐ fair

☐ poor

☒ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☒ chain link	<u>Black painted 1-2</u>
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches

☐ dugouts

☐ bleachers

☐ shade

☒ court lighting

manufacturer/condition: 1-2

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

*Near bus stop

Net poles rusted

Surfacing needs sealant

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports netting

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Basketball

☐ court surface condition

☒ good

☒ fair

☐ poor

☐ color surfacing/lines condition

☐ good

☒ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☒ vinyl-coated c.l.

Needs Ties

☐ sports

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

Needs paint and Sealant

BUILDINGS AND FACILITIES

BUILDING TYPE

☐ concessions condition

☐ comfort station

☐ community facility

☐ restrooms

☐ equipment storage

☐ changing/locker rooms

☐ filter building

☐ other: _____

BUILDING/FACILITIES NOTES:

[Type a quote from the document or the summary of an interesting point. You can position the text box anywhere in the document. Use the Drawing Tools tab to change the formatting of the pull quote text box.]

ROOF

material	
☒ asphalt shingle	☒ good
☐ metal/standing seam	☐ fair
☐ concrete	☐ poor
☐ other: _____	

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	1 _____
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR:
PARKING

Lot On-Site
Total # parking spaces:
Accessible parking spaces:
Signage Aisle 5' Aisle 8' Curbcut Min. 3', 1:12 slopes textured or painted Striping
Accessible parking closest to accessible entrance?
OR is there a drop off area?
Parking is by permit only?
Parking Notes:

ACCESS & CIRCULATION

Table with 3 columns: Question, Yes, No. Rows include: Primary public entrances accessible to person with wheelchair independency?, Accessible path to travel from passenger disembarking area to accessible entrance?, Disembarking area at accessible entrance?, Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?, Any ponding of water?, Accessible route to all elements?, Accessible route to some elements?, Is there signage?, Is there signage for visually impaired?, Grates in the path of travel have openings of 1/2" maximum?

PLAY RECREATION FACILITIES

Table with 3 columns: Question, Yes, No. Rows include: Is there a swing set?, If yes, are there any swings accessible?, Is there a play structure?, If yes, is it accessible?, Meets standards?, Is the same experience provided to ALL?

Any other sports/recreation on site?
If yes, specify facility and check for accessibility

Are there berm cuts onto the courts?
Bleachers are ADA compliant?
Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths?
If no please specify:

Picnic Facilities
Benches:
Drinking Fountains:
Tables:
5% of tables must be accessible
Grill:
Note the height of cooking surface
Picnic Shelters:

Table with 3 columns: Trail Amenities, Yes, No. Rows include: Is surface material accessible?, Trail dimensions and slope gradients meet all ADA requirements?, Is there a handrail?, Is there signage for visually impaired?, Boat Docks & Fishing Facilities, Is there a handrail?, Are there arm rests, bait shelves, and fish cleaning tables?

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

Paths not ADA compliant and in need of refurbishment

PLANT MATERIAL NOTES:

Needs management. Tree roots exposed

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

Bridges inaccessible

State of long wear/decay across the park

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Pond Edges littered with Debris/Trash

Trees need to be pruned, vegetation managed

RECOMMENDED STRATEGIES & ACTIONS:

Take out old/broken benches

Repair Tennis and Basketball courts (high demand)

Prune trees and manage vegetation

Restore paths to ADA compliance



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Farber Field

ADDRESS: 30 Camelot Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high ☒ medium ☐ low
- ☐ other: _____

CONTEXT

- ☒ residential ☐ mixed-use ☐ commercial
- ☐ industrial district: 5 acreage: 3.15

notes: _____

USER GROUPS

- ☒ neighborhood ☐ city ☐ regional
- ☐ kids/families ☐ teens ☐ adults/elderly
- ☒ sports leagues

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material	condition rating (1-2-3 = good-fair-poor)
☐ asphalt	_____
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____

☒ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☒ wood guard rail	1-2 _____

☐ grading / drainage	☐ low/wet areas	☐ blocked structures
	☐ ADA compliant grates	
☒ utilities	☐ gas	☒ water
	☒ electric	
	☐ cameras for security	_____
☐ lighting	☐ pedestrian	
	☐ sports	☐ other
	manufacturer/ model:	_____

SITE INFRASTRUCTURE NOTES:

Parking lot was not open at the time.

SITE AMENITIES NOTES:

No sign, benches.

PARK ACCESS

☐ public transportation	
☐ bike route	☒ sidewalk
☒ parking	☐ trails
☒ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☐ regulatory signage	☐ bike rack
☒ drinking fountain	

PARKING ACCESS NOTES:

Parking open, Big leagues not painted

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports netting

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

Dedicated plaque

3 goals + 1 broken

1) 240 x144

2) Warm up

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐court surface

☐ color surfacing/lines

condition

☐ good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

BUILDINGS AND FACILITIES

BUILDING TYPE

- ☒ concessions
- ☐ comfort station
- ☐ community facility
- ☐ restrooms
- ☒ equipment storage
- ☐ changing/locker rooms
- ☐ filter building
- ☐ other: _____

BUILDING/FACILITIES NOTES:

ROOF

- | material | condition |
|--|-------------------------------|
| ☐ asphalt shingle | ☐ good |
| ☐ metal/standing seam | ☐ fair |
| ☐ concrete | ☐ poor |
| ☐ other: _____ | |

EXTERIOR WALLS

- | Material | condition rating
(1-2-3=good-fair-poor) |
|---|--|
| ☒ CMU block | <u>2</u> |
| ☐ concrete | _____ |
| ☐ wood/vinyl/siding | _____ |
| ☐ other: | _____ |

FILTER BUILDING/AREA

- | Material | condition rating
(1-2-3=good-fair-poor) |
|--|--|
| ☐ fans | _____ |
| ☐ louvres | _____ |
| ☐ pipe conditions | _____ |
| ☐ filter system | _____ |
| ☐ other | _____ |

RECOMMENDED STRATEGIES & ACTIONS:

Access to building.

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	?	_____
# Accessible parking spaces:	?	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

No ADA compliant accessibility.

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☒ yes ☐ no

If yes, specify facility and check for accessibility

Soccer ☐ yes ☒ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, ect.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



CITY OF WORCESTER, MASSACHUSETTS

Park Assessment Form

NAME OF PARK: Hadwen Park

ADDRESS: 1-49 Heard Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☐ mixed-use ☐ commercial

☐ industrial district: 5 acreage: 58.09

notes: _____

USER GROUPS

☒ neighborhood ☐ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	1
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	1
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	2
Ice Skating Area	
Sledding	1
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	1
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	
Picnicking	1
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	1-2
☐ concrete	
☐ pavers	
☐ aggregate/ stonedust	

☒ fencing material

	condition rating (1-2-3 = good-fair-poor)
☐ chain link	
☐ vinyl coated c.l.	
☐ ornamental	
☐ wood guard rail	

☐ grading / drainage

☐ low/wet areas ☐ blocked structures
☐ ADA compliant grates

☐ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security

☐ lighting ☐ pedestrian

☐ sports ☐ other

manufacturer/ model: _____

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

Need for more benches.

PARK ACCESS

☐ public transportation

☐ bike route ☐ sidewalk

☒ parking ☐ trails

☒ public lot

☐ street

☐ other: _____

SITE FURNISHINGS

☒ picnic area ☐ monuments

☐ shade shelter ☐ benches

☒ interpretive signage ☒ trash

☒ regulatory signage ☒ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

38 spaces

3 Handicapped stalls and accessible routes to most facilities.

PLAYGROUND ASSESSMENT

COMPONENTS

- ☒ 2-5 age structure
- ☐ 5-12 age structure
- ☐ water elements
- ☐ seating for caregivers
- ☐ drinking fountain
- ☐ shade
- ☒ swings
- ☐ ADA
- ☒ infant
- ☒ belt
- ☐ standard

☒ slides

☒ 2-5 age

☐ 5-12 age

Material: _____

☐ Individual elements: _____

SURFACING:

material

- ☐ PIP rubber
- ☒ wood fiber
- ☐ sand
- ☐ other: _____

compliance

- ☐ meets requirements
- ☒ does NOT meet the requirements

PLAY VALUE

- motor skills

☐ rocking

☐ swinging

☐ spinning

☐ climbing

☐ sliding

☐ balancing
- cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play:

PLAYGROUND NOTES:

2 infant swings with belts.

RECOMMENDED STRATEGIES AND ACTIONS:

Fix slide close opening.

PLAYGROUND ASSESSMENT

COMPONENTS

☐ 2-5 age structure

☒ 5-12 age structure

☐ water elements

☐ seating for caregivers

☐ drinking fountain

☐ shade

☒ swings

☐ ADA

☒ infant

☒ belt

☐ standard

☐ slides

☐ 2-5 age

☐ 5-12 age

Material: _____

☐ Individual elements: _____

PLAY VALUE

motor skills

☐ rocking

☒ swinging

☐ spinning

☒ climbing

☐ sliding

☐ balancing

cognitive skills

☐ manipulative

☐ interactive

☐ exploratory

☐ engagement with peers

☐ problem solving

☐ other unstructured play: _____

SURFACING:

material

☐ PIP rubber

☒ wood fiber

☐ sand

☐ other _____

compliance

☐ meets requirements

☒ does NOT meet the requirements

manufacturer/condition of equipment

NOTE: see ADA checklist for accessibility assessment

PLAYGROUND NOTES:

2 infant swings with belts.

Climbing structure has safety zone outside edens swing. S-hooks are non-compliant.

Edge is rubbed and in poor condition.

RECOMMENDED STRATEGIES AND ACTIONS:

ATHLETIC FIELDS Baseball

Near 2-5 playground.

Lights not working.

BUILDINGS AND FACILITIES

BUILDING TYPE

☒ concessions?	☐ comfort station
☐ community facility	☒ restrooms
☒ equipment storage?	☐ changing/locker rooms
☐ filter building	☐ other: _____

BUILDING/FACILITIES NOTES:

ROOF

material	condition
☐ asphalt shingle	☐ good
☐ metal/standing seam	☐ fair
☐ concrete	☐ poor
☐ other: _____	

EXTERIOR WALLS

Material	condition rating (1-2-3=good-fair-poor)
☒ CMU block	_____
☐ concrete	_____
☐ wood/vinyl/siding	_____
☐ other:	_____

FILTER BUILDING/AREA

Material	condition rating (1-2-3=good-fair-poor)
☐ fans	_____
☐ louvres	_____
☐ pipe conditions	_____
☐ filter system	_____
☐ other	_____

RECOMMENDED STRATEGIES & ACTIONS:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☒ Aisle 8' ☐	Curbside ☒ Min. 3', 1:12 slopes textured or painted Striping ☒

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

Beech trees

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

Erosion

Storm water

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G




Existing Conditions Photo H



Existing Conditions Photo I



Existing Conditions Photo J



Existing Conditions Photo K



Existing Conditions Photo L



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Coes Knife Parks: Knights of Columbus Conservation Restriction and Coes Reservation Park

ADDRESS: Englewood Avenue



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

- ☐ high
- ☐ medium
- ☐ low
- ☐ other: _____

CONTEXT

- ☐ residential
- ☐ mixed-use
- ☐ commercial
- ☐ industrial
- district: 5
- acreage: 7

notes: Under construction.

USER GROUPS

- ☐ neighborhood
- ☐ city
- ☐ regional
- ☐ kids/families
- ☐ teens
- ☐ adults/elderly
- ☐ sports leagues
- ☐ other: _____

NEIGHBORHOOD CONTEXT

?Master plan.

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	1
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	1
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	
Picnicking	1
Woodlands	1
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

denotes lighting

denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

condition rating
(1-2-3 = good-fair-poor)

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating
(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas

☐ water

☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian

☐ sports

☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route☐ sidewalk

☐ parking☐ trails

☐ public lot☐ street

☐ other:

SITE FURNISHINGS

☐ picnic area☐ monuments

☐ shade shelter☐ benches

☐ interpretive signage☐ trash

☐ regulatory signage☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports netting	_____

☐ seating

☐ team benches

☐ dugouts

☐ field lighting

☐ bleachers

☐ shade

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐ court surface condition

☐ good

☐ fair

☐ poor

☐ color surfacing/lines condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches

☐ dugouts

☐ court lighting

☐ bleachers

☐ shade

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

ACCESSIBILITY FOR:

PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbscut ☐ Min. 3'; 1:12 slopes textured or painted
		Striping ☐
Accessible parking closest to accessible entrance? ☐		
OR is there a drop off area? ☐ yes ☐ no		
Parking is by permit only? ☐ yes ☐ no		
Parking Notes:		

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no
If yes, specify facility and check for accessibility
_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no
fishing piers, ect.) and equipment (i.e.
Benches, pools, shade shelters)
located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Logan Field

ADDRESS: Between Chandler Street and Mill Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☒ medium ☐ low

☒ other: Seasonal

CONTEXT

☒ residential ☐ mixed-use ☐ commercial

☐ industrial district: 5 acreage: 11.32

notes: _____

USER GROUPS

☒ neighborhood ☒ city ☐ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☐ other:

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	1
Baseball	1
Basketball	1
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1	denotes lighting
1	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>1</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____

☒ fencing material

	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☒ vinyl coated c.l.	<u>1</u>
☐ ornamental	_____
☐ wood guard rail	_____

☐ grading / drainage

☐ low/wet areas ☐ blocked structures

☐ ADA compliant grates

☒ utilities

☐ gas ☒ water ☒ electric

☐ cameras for security _____

☒ lighting ☐ pedestrian

☐ sports ☒ other

manufacturer/ model: Street cobra lights
along Mill Street.

PARK ACCESS

☐ public transportation

☐ bike route ☒ sidewalk

☒ parking ☐ trails

☐ public lot

☒ street

☐ other: _____

SITE FURNISHINGS

☐ picnic area ☐ monuments

☐ shade shelter ☐ benches

☒ interpretive signage ☐ trash

☒ regulatory signage ☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

Sidewalks in repair

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Softball

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☐ fair

☐ poor

☒ irrigation

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☒ vinyl-coated c.l.

☐ sports netting

☒ seating

☐ team benches

☐ bleachers

☒ dugouts

☐ shade

☒ field lighting

manufacturer/condition New-Musco

ATHLETIC FIELD NOTES:

This field is under construction and almost done.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐court surface

☐ color surfacing/lines

condition

☐ good

☐ good

☐ fair

☐ poor

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐ poor

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Little League

☒natural turf

☐ synthetic turf

condition

☒good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☒ irrigation

☐ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1-2</u>
☒ sports netting	<u>1</u>

☒ seating

☒ team benches	☒ bleachers
☒ dugouts	☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

"Marshall Field"

1 portable bleacher, 2 fixed in fair condition

(3 bleachers)

RECOMMENDED STRATEGIES & ACTIONS:

COURTS Basketball

☒court surface

☒ color surfacing/lines

condition

☒ good

☐ good

☐ fair

☐ fair

☐ poor

☐ poor

☐ dimensions meet MIAA/NFHS standards

☒ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1-2</u>
☐ sports	_____

☐ seating

☐ team benches	☐ bleachers
☐ dugouts	☐ shade

☒ court lighting?

manufacturer/condition: 2

☐ skate park condition

☐ concrete	☐ good
☐ surface mount	☐ fair
	☐ poor

COURT NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbside ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of 1/2" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, fishing piers, ect.) and equipment (i.e. Benches, pools, shade shelters) located adjacent to accessible paths? ☐ yes ☐ no

If no please specify:

Picnic Facilities

	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible		
Grill:	_____	_____
Note the height of cooking surface	_____	
Picnic Shelters:	_____	_____

Trail Amenities

Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:

Meets all ADA requirements for accessibility?

☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no
☐ yes	☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B



Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



Existing Conditions Photo G



Existing Conditions Photo H



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: Rockwood Field

ADDRESS: 486 Chandler Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☒ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☒ mixed-use ☐ commercial

☐ industrial district: 5 acreage: 15.53

notes: Institutional (Worcester State University)

USER GROUPS

☐ neighborhood ☒ city ☒ regional

☒ kids/families ☒ teens ☒ adults/elderly

☒ sports leagues

☒ other: WSU + other universities

NEIGHBORHOOD CONTEXT

Next to campus

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	1
Multipurpose Field	
Little League	2
Softball	1
Baseball	1
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	1
Unprogrammed Open Lawns	1
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1	denotes lighting
1	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☒ pathways material	condition rating (1-2-3 = good-fair-poor)
☒ asphalt	<u>1</u>
☐ concrete	_____
☐ pavers	_____
☐ aggregate/ stonedust	_____
☐ fencing material	condition rating (1-2-3 = good-fair-poor)
☐ chain link	_____
☐ vinyl coated c.l.	_____
☐ ornamental	_____
☐ wood guard rail	_____
☐ grading / drainage	
☐ low/wet areas	☐ blocked structures
☐ ADA compliant grates	
☒ utilities	
☒ gas	☒ water
☒ electric	
☐ cameras for security	_____
☒ lighting	☐ pedestrian
☒ sports	☐ other
manufacturer/ model: _____	

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

PARK ACCESS

☐ public transportation	
☐ bike route	☒ sidewalk
☒ parking	☐ trails
☐ public lot	
☒ street	
☐ other:	_____

SITE FURNISHINGS

☐ picnic area	☐ monuments
☐ shade shelter	☐ benches
☐ interpretive signage	☐ trash
☒ regulatory signage	☐ bike rack
☐ drinking fountain	

PARKING ACCESS NOTES:

ATHLETIC FIELDS Little League 2/ Softball

Little League 2/ Softball

☒ irrigation☒ field fencing☒ seating

☐ shade

☐ field lighting

manufacturer/condition:

*only backstop

☐ court fencing

☐ sports☐ seating

☐ shade

☐ court lighting

manufacturer/condition:

☐ skate park condition

☐ poor

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Burkett Softball

- | | |
|--|---|
| ☒ natural turf | ☐ synthetic turf |
| condition | condition |
| ☒ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |
| ☒ irrigation | |

☒ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☒ sports netting	<u>1</u>

☒ seating

- | | |
|--|---|
| ☒ team benches | ☒ bleachers |
| ☒ dugouts | ☒ shade |

☒ field lighting

manufacturer/condition: Good-Musco

ATHLETIC FIELD NOTES:

*In great shape. Well maintained by college kids.

RECOMMENDED STRATEGIES & ACTIONS:

*Stone in fields-fields are eroding

COURTS

- | | |
|--|--|
| ☐ court surface | ☐ color surfacing/lines |
| condition | condition |
| ☐ good | ☐ good |
| ☐ fair | ☐ fair |
| ☐ poor | ☐ poor |

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

- | | |
|---------------------------------------|------------------------------------|
| ☐ team benches | ☐ bleachers |
| ☐ dugouts | ☐ shade |

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

- | | |
|--|-------------------------------|
| ☐ concrete | ☐ good |
| ☐ surface mount | ☐ fair |
| | ☐ poor |

COURT NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS Kevin Lyons Baseball Diamond

☒natural turf

☐ synthetic turf

condition

☒good

☐ fair

☐ poor

☒ irrigation

condition

☐ good

☐ fair

☐ poor

☒ dimensions meet MIAA/NFHS standards

☒ field fencing

Material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☒ vinyl-coated c.l.	<u>1</u>
☒ sports netting	<u>1</u>

☒ seating

☒ team benches	☒ bleachers
☒ dugouts	☒ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

Not lit but has LP bases, press box, bull pen and batting cage.

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐court surface

☐ color surfacing/lines

condition

☐ good

☐ fair

☐ poor

condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material	condition rating (1-2-3=good-fair-poor)
☐ chain link	_____
☐ vinyl-coated c.l.	_____
☐ sports	_____

☐ seating

☐ team benches	☐ bleachers
☐ dugouts	☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ surface mount

☐ good

☐ fair

☐ poor

COURT NOTES:

ACCESSIBILITY FOR: _____

PARKING

Lot

On-Site

Total # parking spaces: _____

Accessible parking spaces: _____

Signage ☒ Aisle 5' ☒ Curbcut ☒ Striping ☒

Aisle 8' ☐

Min. 3', 1:12 slopes
textured or painted

Accessible parking closest to accessible entrance? ☐OR is there a drop off area? ☐ yes ☐ noParking is by permit only? ☐ yes ☐ noParking Notes:
Striping needs paint

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☒ yes	☐ no
Disembarking area at accessible entrance?	☒ yes	☒ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☒ yes	☐ no
Any ponding of water?	☐ yes	☒ no
Accessible route to all elements?	☐ yes	☒ no
Accessible route to some elements?	☒ yes	☐ no
Is there signage?	☐ yes	☒ no
Is there signage for visually impaired?	☐ yes	☒ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☒ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☒ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no

If yes, specify facility and check for accessibility

☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no
fishing piers, ect.) and equipment (i.e.
Benches, pools, shade shelters)
located adjacent to accessible paths?

If no please specify:

Picnic Facilities

Total # # Accessible

Benches: _____

Drinking Fountains: _____

Tables: _____

5% of tables must be accessible

Grill: _____

Note the height of cooking surface

Picnic Shelters: _____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no

REFER TO PUNCH LIST

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:



Existing Conditions Photo A



Existing Conditions Photo B




Existing Conditions Photo C



Existing Conditions Photo D



Existing Conditions Photo E



Existing Conditions Photo F



CITY OF WORCESTER, MASSACHUSETTS


Park Assessment Form

NAME OF PARK: TY Cobb Park

ADDRESS: 43 South Ludlow Street



Aerial Oblique Photograph



Locus Map

INTENSITY OF USE

☐ high ☐ medium ☐ low

☐ other: _____

CONTEXT

☐ residential ☐ mixed-use ☐ commercial

☐ industrial district: 5 acreage: 12.20

notes: _____

USER GROUPS

☐ neighborhood ☐ city ☐ regional

☐ kids/families ☐ teens ☐ adults/elderly

☐ sports leagues

☐ other: _____

NEIGHBORHOOD CONTEXT

FACILITIES INVENTORY CHECKLIST:

(list number of existing amenities)

Parking Lot	
Park Support Bldgs.	
ACTIVE USE	
Football	
Soccer	
Multipurpose Field	
Little League	
Softball	
Baseball	
Basketball	
Tennis	
Handball	
Volleyball	
Roller Hockey	
Playground	
Ice Skating Area	
Sledding	
Spray Park	
Pool Complex	
PASSIVE USE	
Water Resources	
Bathing Beach	
Boating	
Fishing	
Historic Resources	
Monument/ Memorial	
Gazebo/Pavilion/Picnic Shelter	
Amphitheater	
Interpretive Signs & Kiosk	
Paths & Trails	
Unprogrammed Open Lawns	
Picnicking	
Woodlands	
Other: café seating area	
Other: community gardens	
Other: Zoo, golf	

1	denotes lighting
1	denotes overlay

SITE INFRASTRUCTURE/AMENITIES ASSESSMENT

SITE INFRASTRUCTURE

☐ pathways material

condition rating

(1-2-3 = good-fair-poor)

☐ asphalt

☐ concrete

☐ pavers

☐ aggregate/ stonedust

☐ fencing material

condition rating

(1-2-3 = good-fair-poor)

☐ chain link

☐ vinyl coated c.l.

☐ ornamental

☐ wood guard rail

☐ grading / drainage

☐ low/wet areas

☐ blocked structures

☐ ADA compliant grates

☐ utilities

☐ gas☐ water☐ electric

☐ cameras for security

☐ lighting

☐ pedestrian☐ sports☐ other

manufacturer/ model:

PARK ACCESS

☐ public transportation

☐ bike route☐ sidewalk

☐ parking☐ trails

☐ public lot☐ street☐ other:

SITE FURNISHINGS

☐ picnic area

☐ monuments

☐ shade shelter

☐ benches

☐ interpretive signage

☐ trash

☐ regulatory signage

☐ bike rack

☐ drinking fountain

PARKING ACCESS NOTES:

SITE INFRASTRUCTURE NOTES:

SITE AMENITIES NOTES:

ATHLETIC FIELDS AND COURTS ASSESSMENT

ATHLETIC FIELDS

☐ natural turf condition

☐ good

☐ fair

☐ poor

☐ irrigation

☐ synthetic turf condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ field fencing

Material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports netting

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ field lighting

manufacturer/condition: _____

ATHLETIC FIELD NOTES:

RECOMMENDED STRATEGIES & ACTIONS:

COURTS

☐ court surface condition

☐ good

☐ fair

☐ poor

☐ color surfacing/lines condition

☐ good

☐ fair

☐ poor

☐ dimensions meet MIAA/NFHS standards

☐ court fencing

material

condition rating
(1-2-3=good-fair-poor)

☐ chain link

☐ vinyl-coated c.l.

☐ sports

☐ seating

☐ team benches

☐ bleachers

☐ dugouts

☐ shade

☐ court lighting

manufacturer/condition: _____

☐ skate park condition

☐ concrete

☐ good

☐ surface mount

☐ fair

☐

☐ poor

COURT NOTES:

ACCESSIBILITY FOR: PARKING

	Lot	On-Site
Total # parking spaces:	_____	_____
# Accessible parking spaces:	_____	_____
Signage ☐	Aisle 5' ☐ Aisle 8' ☐	Curbcut ☐ Min. 3', 1:12 slopes textured or painted
		Striping ☐

Accessible parking closest to accessible entrance? ☐

OR is there a drop off area? ☐ yes ☐ no

Parking is by permit only? ☐ yes ☐ no

Parking Notes:

ACCESS & CIRCULATION

Primary public entrances accessible to person with wheelchair independency?	☐ yes	☐ no
Accessible path to travel from passenger disembarking area to accessible entrance?	☐ yes	☐ no
Disembarking area at accessible entrance?	☐ yes	☐ no
Surface firm, stable, evenly paved/hard-packed (no cracks, slip resistant)?	☐ yes	☐ no
Any ponding of water?	☐ yes	☐ no
Accessible route to all elements?	☐ yes	☐ no
Accessible route to some elements?	☐ yes	☐ no
Is there signage?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no

PLAY RECREATION FACILITIES

Is there a swing set?	☐ yes	☐ no
If yes, are there any swings accessible?	☐ yes	☐ no
Is there a play structure?	☐ yes	☐ no
If yes, is it accessible?	☐ yes	☐ no
Meets standards?	☐ yes	☐ no
Is the same experience provided to ALL?	☐ yes	☐ no

Any other sports/recreation on site? ☐ yes ☐ no
If yes, specify facility and check for accessibility
_____ ☐ yes ☐ no

☐ yes ☐ no

☐ yes ☐ no

Are there berm cuts onto the courts? ☐ yes ☐ no

Bleachers are ADA compliant? ☐ yes ☐ no

Note dimension and height of equipment at game areas

SITE AMENITIES

Are all activities (i.e. boat docks, ☐ yes ☐ no

fishing piers, etc.) and equipment (i.e.

Benches, pools, shade shelters)

located adjacent to accessible paths?

If no please specify:

Picnic Facilities	Total #	# Accessible
Benches:	_____	_____
Drinking Fountains:	_____	_____
Tables:	_____	_____
5% of tables must be accessible	_____	_____
Grill:	_____	_____
Note the height of cooking surface	_____	_____
Picnic Shelters:	_____	_____

Trail Amenities	☐ yes	☐ no
Is surface material accessible?	☐ yes	☐ no
Trail dimensions and slope gradients meet all ADA requirements?	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Is there signage for visually impaired?	☐ yes	☐ no
Boat Docks & Fishing Facilities	☐ yes	☐ no
Is there a handrail?	☐ yes	☐ no
Are there arm rests, bait shelves, and fish cleaning tables?	☐ yes	☐ no

List other amenities:

ACCESSIBILITY FOR: _____

SWIMMING FACILITIES

Beaches:	☐ yes	☐ no
Is there an accessible path of travel from parking lot to waterfront?	☐ yes	☐ no
Is shade provided?	☐ yes	☐ no
Are handrails provided where necessary?	☐ yes	☐ no
Pools:	☐ yes	☐ no
Is there an accessible path of travel from parking to pool?	☐ yes	☐ no
Safety features, i.e. warning sign for visually impaired?	☐ yes	☐ no
Grates in the path of travel have openings of ½" maximum?	☐ yes	☐ no
Ramp at least 34" wide into shallow end, with non-slip surface. Slope not exceeding 1:6 with handrails on both sides?	☐ yes	☐ no
Lifting device?	☐ yes	☐ no
Transfer area 18" above path or travel & min. of 18" wide?	☐ yes	☐ no
Unobstructed path of travel not less than 48" wide around pool?	☐ yes	☐ no
Shower Rooms:	☐ yes	☐ no
Shower rooms meet all ADA requirements for accessibility?	☐ yes	☐ no
REFER TO PUNCH LIST		

SUPPORT BUILDING FACILITIES

FOR ALL BUILDING ASPECTS:DOORS, FLOORS, SIGNS, SIGNALS AND SWITCHES, PLEASE REFER TO PUNCH LIST

Restrooms:	☐ yes	☐ no
5' turning space measured 12" from floor?	☐ yes	☐ no
At least one accessible sink*?	☐ yes	☐ no
At least one accessible stall*?	☐ yes	☐ no
Accessible dispensers & mirrors*?	☐ yes	☐ no

*Meeting all ADA requirements dor accessible restroom facilities..REFER TO PUNCH LIST

Total# #Accessible

Drinking Fountains: _____

LIST OTHER FACILITIES

Type of facility or equipment within the facility:	Meets all ADA requirements for accessibility?
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no
_____	☐ yes ☐ no

PHOTOS RELATED TO ADA REQUIREMENTS:

ADDITIONAL NOTES

CIRCULATION & CONNECTIVITY NOTES:

PLANT MATERIAL NOTES:

VIEWSHEDS & HISTORICAL RESOURCES NOTES:

ENVIROMENTAL RESOURCES & CONCERNS NOTES:

RECOMMENDED STRATEGIES & ACTIONS:
